

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0428/2022/JT
DATE : 26-May-22
WIP : 25540

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve,

6 days - ok - Jy - 26 Aug 22

OWNER'S NAME : MR TAY SOH ENG
ADDRESS : 145 SERANGOON AVE3
#05-01
SINGAPORE 556122
TELEPHONE : HP +65 97952092
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220007807
VEHICLE NO : **SND 7641 S**
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 24/01/2022
ENGINE NO : DEM 035355
CHASSIS NO : WAUZZZF46NN002872
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-May-22
PLACE OF ACCIDENT : CAPITOL PLAZZA

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 7641 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS , OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$	1,400.00		
4	TO CARRY OUT PRESSURISE, VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00		
5	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER.	S/N \$	800.00		
6	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR.	S/N \$	280.00		
SUB TOTAL LABOUR CHARGES		:	\$ 4,510.00	\$	730.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 7641 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
				\$	730.00
7	TO SETUP VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	c/f	\$ 2,400.00		
8	TO DISMANLE AND RENEW FRONT BUMPER, RKS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR BONNET. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED		\$ 6,500.00	\$	1,250.00
9	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER TOP SUPPORT, RHS FRONT FENDER AND RHS FRONT DOOR.	S/N	\$ 4,500.00	\$	1,925.00
10	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N	\$ 520.00		
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N	\$ 384.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 18,814.00	\$	4,097.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 7641 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	\$ 1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 393.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00	\$ 63.20
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 293.00	\$ 234.00
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 51.00	\$ 40.08
6	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	1	\$ 293.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	\$ 120.40
8	FRONT BUMPER TRIM - RH	1	\$ 54.00	\$ 42.64
9	RADIATOR GRILLE	1	\$ 1,754.00	
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 212.00	
12	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	\$ 32.24
13	FRONT BUMPER BRACKET - RH	1	\$ 254.00	
14	FRONT BUMPER TOP COVER	1	\$ 143.00	\$ 114.00
15	CAUTION STICKER	1	\$ 16.00	\$ 12.40
16	AIR COND STICKER	1	\$ 9.00	\$ 6.64
17	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	\$ 122.80
18	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
19	FRONT BUMPER POP RIVET	4	\$ 4.00	
20	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 530.00	
SUB TOTAL SPARE PARTS		:	\$ 7,771.00	\$ 2,690.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 7641 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	2,690.00
21	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00		
22	FRONT BUMPER WIRING SET	1	\$ 642.00		
23	HORN - RH	1	\$ 139.00		
24	HORN SUPPORT - RH	1	\$ 33.00		
25	FRONT FENDER - RH	1	\$ 1,227.00	\$	981.60
26	FRONT FENDER ATTACHMENT PARTS	1	\$ 211.00		
27	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 81.00	\$	64.24
28	FRONT FENDER BRACKET - RH	1	\$ 41.00	\$	32.72
29	FRONT FENDER BRACKET CENTER - RH	1	\$ 55.00	\$	44.00
30	FRONT FENDER POP RIVET	7	\$ 27.00	\$	21.28
31	FRONT FENDER BRACKET END - RH	1	\$ 36.00		
32	FRONT FENDER BRACE - RH	1	\$ 132.00	\$	105.20
33	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 37.00		
34	FRONT FENDER TOP CAP - RH	1	\$ 13.00		
35	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	\$	209.60
36	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 149.00		
37	FRONT WHEEL SPOILER - RH	1	\$ 82.00	\$	65.12
38	FRONT WHEEL SPOILER LOWER - RH	1	\$ 40.00		
39	FRONT FENDER LEDGE COVER LONG - RH	1	\$ 35.00	\$	27.52
40	HEADLAMPS COVER - RH	1	\$ 49.00	\$	38.64
SUB TOTAL SPARE PARTS		:	\$ 3,301.00	\$	4,279.92

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 7641 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	4,279.92
41	FRONT FENDER LEDGE COVER - RH INNER	1	\$ 68.00		
42	HEADLIGHT - RH	1	\$ 8,172.00	\$	6,537.60
43	HEADLIGHT HOSE	1	\$ 42.00		
44	SPACER	3	\$ 136.00	\$	107.84
45	CABLE TIES	1	\$ 2.00		
46	LIFT CYLINDER - RH	1	\$ 231.00	\$	184.40
47	LIFT CYLINDER BRACKET	1	\$ 7.00	\$	5.44
48	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00		
49	LIFT CYLINDER CORRUGATED PIPE - RH	1	\$ 53.00		
50	WASH WATER RESERVOIR	1	\$ 160.00		
51	LOCK CARRIER	1	\$ 1,127.00		
52	LOCK CARRIER SUPPORT - RH	1	\$ 43.00		
53	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00		
54	RADIATOR COOLANT	6	\$ 282.00		
55	RADIATOR AIR GUIDE - RH	1	\$ 51.00		
56	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 38.00		
57	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00		
58	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00		
59	FRONT FENDER CONNECTING PLATE - RH LOWER	1	\$ 279.00		
60	FRONT FENDER CONNECTING PLATE - RH UPPER	1	\$ 241.00		
SUB TOTAL SPARE PARTS		:	\$ 11,104.00	\$	11,115.20

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 7641 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 11,115.20
61	NOISE INSULATION	1	\$ 640.00	
62	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH	1	\$ 344.00	
63	FRONT ON PLATE	S/N	\$ 60.00	
64	RHS FRONT RIM	S/N	TBC	
65	ARYLIC SEALANT	S/N	\$ 180.00	
66	CAVITY WAX	S/N	\$ 140.00	
67	METAL FILLER POWDER	S/N	\$ 280.00	
68	STONE CHIP	S/N	\$ 180.00	
69	SUNDRIES		\$ 600.00	\$ 31.20
TOTAL SPARE PARTS			\$ 24,600.00	\$ 11,146.40
TOTAL LABOUR CHARGES			\$ 18,814.00	\$ 4,097.00
GRAND TOTAL			\$ 43,414.00	\$ 15,243.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-18/07/22

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT