

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0416/2022/JT
DATE : 24-May-22
WIP : 25276

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/5/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WONG KOK HONG
ADDRESS : BLK 601 JURONG WEST ST 62
#05-173
SINGAPORE 640601
TELEPHONE : HP +65 9797 1990
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700075221-04
VEHICLE NO : **SLT 7468 R**
MODEL CODE : Q2 1.0 TFSI S-TRONIC
MODEL YEAR : 9/11/2017
ENGINE NO : CHZ 570895
CHASSIS NO : WAUZZZGAXJA029062
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-May-22
PLACE OF ACCIDENT : TAMAN JURONG FOOD CENTRE
MULTI-STOREY CARPARK

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 7468 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	✓
2	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	✓
3	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, HINGES AND LHS REAR FENDER.	\$ 3,000.00	✓
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,792.00	

Wheel Alignment + change Rim \$280 (S/N) ✓ ✓

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 7468 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT DOOR - LH <i>Dented</i>	1	\$ 2,962.00	✓	2369.60
2	FRONT DOOR CATCH - LH <i>? nn</i>	1	\$ 134.00	? X	
3	FRONT DOOR COVER - LH <i>cut</i>	1	\$ 270.00	✓	216
4	FRONT DOOR GROMMET <i>xx ? nn</i>	5	\$ 15.00	? X	
5	REAR DOOR - LH <i>Distorted</i>	1	\$ 2,962.00	✓	2369.60
6	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 151.00	✓	120.40
7	BONDING AGENT <i>? nn</i>	1	\$ 51.00	? X	
8	CLEANING SOLUTION <i>? nn</i>	1	\$ 74.00	? X	
9	APPLICATOR <i>? nn</i>	1	\$ 8.00	? X	
10	REAR DOOR CATCH - LH <i>? damaged</i>	1	\$ 134.00	? 112	
11	REAR DOOR SEAL OUTER - LH <i>new</i>	1	\$ 66.00	✓	52.80
12	REAR DOOR SEAL INNER - LH <i>new</i>	1	\$ 313.00	X	
13	REAR DOOR COVER - LH <i>damaged</i>	1	\$ 238.00	✓	190.40
14	REAR DOOR HINGE HALF UPPER - LH LOWER <i>given</i>	1	\$ 53.00	X	
15	REAR DOOR HINGE HALF LOWER - LH	1	\$ 49.00	+	
16	REAR WHEEL ARCH COVER - LH <i>missing</i>	1	\$ 180.00	✓	143.60
17	REAR DOOR GROMMET <i>? nn</i>	3	\$ 9.00	? X	
18	REAR DOOR WINDOW REGULATOR - LH <i>? nn</i>	1	\$ 302.00	? X	
19	REAR DOOR WINDOW REGULATOR WITH MOTOR - LH <i>new</i>	1	\$ 308.00	+	
20	REAR WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 220.00	+	
SUB TOTAL SPARE PARTS			\$ 8,499.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 7468 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	ALUMINIUM RIM <i>cut</i>	1	\$ 1,002.00	<i>✓</i> 801.60
22	RUBBER VALVE plus nec	1	\$ 4.00	<i>✗</i> 2.96
23	SUNDRIES <i>?</i> nec		\$ 350.00	<i>?</i> 27.52
TOTAL SPARE PARTS		:	\$ 9,855.00	
TOTAL LABOUR CHARGES		:	\$ 6,792.00	
GRAND TOTAL		:	\$ 16,647.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adnan L
: 27/05/22
:
:
:
: Not Authorised, 05 Days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: