

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2205-282 TG

DATE : 28-May-2022

POLICY NO. : PHPV2019-00004946-01

VEHICLE REG. NO. : SKQ7988J

VEHICLE MAKE : HYUNDAI ELANTRA 1.6 AT ABS D/AB 2W

TO China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

P-3809
-20%
3047.20

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / <i>DD</i>	1	\$ 460.00	\$ 460.00
2	Rear Bumper Clips / <i>RLC</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Side Retainer (LH/RH) / <i>RR</i>	2	\$ 25.00	\$ 50.00
4	Rear Bumper Lower Garnish / <i>RR</i>	1	\$ 251.00	\$ 251.00
5	Rear Bumper Reinforcement / <i>RR</i>	1	\$ 325.00	\$ 325.00
6	Rear Bumper Reinforcement Bracket (LH) (866813X700) / <i>X nn</i>	1	\$ 10.00	\$ 10.00
7	Rear Bumper Reinforcement Bracket (RH) (866823X700) / <i>X nn</i>	1	\$ 10.00	\$ 10.00
8	Rear Bumper Antenna (954203K100) / <i>X nn</i>	1	\$ 65.00	\$ 65.00
9	Rear Boot / <i>DD</i>	1	\$ 1,840.00	\$ 1,840.00
10	Rear Boot Lock / <i>BT</i>	1	\$ 135.00	\$ 135.00
11	Rear Boot Hinge (LH/RH) / <i>BT</i>	2	\$ 68.00	\$ 136.00
12	Rear Boot Weatherstrip / <i>CR4</i>	1	\$ 80.00	\$ 80.00
13	Rear Boot Emblem / <i>RLC</i>	1	\$ 30.00	\$ 30.00
14	Rear Boot Lamp (LH/RH) / <i>X nn</i>	2	\$ 300.00	\$ 600.00
15	Rear Tail Lamp (LH/RH) / <i>X nn</i>	2	\$ 400.00	\$ 800.00
16	Rear End Panel / <i>DD</i>	1	\$ 455.00	\$ 455.00
17	Rear End Panel Top Garnish / <i>CR4</i>	1	\$ 75.00	\$ 75.00
Total Spare Parts				\$ 5,372.00
SPECIAL NETT				
18	Rear Reverse Sensor / <i>sh-hd</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 200.00
LABOUR				
19	Repair, Remove, Refit and Replace Affected Accident Parts	1	\$ 900.00	\$ 900.00
20	Spray Painting (Rear Bumper, Rear Boot, Rear End Panel, Rear Reinforcement)	1	\$ 900.00	\$ 900.00
21	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
22	Remove and Replace Reverse Sensor	1	\$ 80.00	\$ 80.00
23	Check and Rectify Electrical Wiring	1	\$ 50.00	\$ 50.00
Total Labour				\$ 2,030.00
Amount Before Excess				\$ 7,602.00
Add GST @ 7%				\$ 532.14
Total Amount Payable				\$ 8,134.14

LKK Auto Consultants hence notify

the Receiver of this Estimate prepared by: James Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1

L/S-3973.44
=3950

Supp-2960
=4966.80