



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Supplementary

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2205-282 TG
DATE : 1-Jun-2022
POLICY NO. : PNPV2019-00004946-01
VEHICLE REG. NO. : **SKQ7988J**
VEHICLE MAKE : HYUNDAI ELANTRA 1.6 AT ABS D/AB 2W

TO China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper Reflector (LH) ✓ BR	1	\$ 37.00	\$ 37.00
Parts Less 20%				\$ (7.40)
Total Spare Parts				\$ 29.60 ✓
Amount Before Excess				\$ 29.60
Add GST @ 7%				2.07
Total Amount Payable				\$ 31.67

Estimate prepared by: James Tan
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on