

ComfortDelGro Engineering Pte Ltd

59 Loyang Drive Singapore 508969

A	D - 6
(hir	ᅛᅀᅡ
Out	1701

305517628

Via Fax

emolic

Date

26.2. DC

Your Insured

are wase

Time of Fax

Date of Acc

71-0-22

Attn: Motor Claims Department

Lonpal

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

B62174

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

♦ Chiang Liat Choon

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

Lim Kwok Eng
 Jumani Bin Masudin
 Lim Tien Siong
 Tel: 6214 8355 or HP: 9824 0811
 Tel: 6214 8315 or HP: 9635 5305
 Tel: 6214 8398 or HP: 9635 8546

Tel: 6214 8314 or HP: 9296 6006

jumanibm@cdge.com.sg Fax no. 6546 8156

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Tax Accident Repair



ComfortDelGro Engineering Pte Ltd

205 Brindall Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

KMHC851CVLU186769

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 28.05.2022 08:46

Page: 1

eam:

ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305517628

TOMER

/IS

COMFORT TRANSPORTATION PTE LTD

7010045

TOMER NO. 383 SIN MING DRIVE RESS

Singapore SINGAPORE 575717

65508755 (R)

(O)

(P)

OUNT CARD NO.

REGN NO.: SHB6217Y	7	MILEAGE
MAKE: HYUNDAI		FUEL E1/2F
MODEL IONIQ(G3)	27	DATE/TIME IN 05.2022 16:45
YR OF MANU. 22.10.2019		TARGET DATE
CHASSIS CODE		COMPLETION DATE/TIME:


JOB DESCRIPTION

ccident Date: 27.05.2022 ATURE: 3P 27.05.2022 \

/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:		

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

SHB6217Y

JU LONPAC

Vehicle No.:

Exit Pass

SHB6217Y

Service Advisor

Signature/Date

Name of Service Advisor

Date

ırned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHB6217Y

MAKE HYUNDAI

MODEL IONIQ DOA: 27.05.22 LONPAC

28.05.22

DATE:

MVA JUMANI

	IONIQ	DOA:		
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
1	BOOTLID COVER			\$2,549.70
1	REAR BUMPER ASSY			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER BEAM			\$394.80
	REAR BUMPER CLIPS			\$22.00
	FOG LAMP			\$201.50
	ANTENNA ASSY – SMARTKEY			\$40.50
_	BOOTLID EMBLEM – IONIQ			\$31.30
	BOOTLID EMBLEM – HYBRID			\$24.30
	BOOTLID EMBLEM – H			\$28.00
	REAR WINDSCREEN GLASS (SMALL)			\$584.90
	SPOILER ASSY			\$665.40
	ISFOILER ASST			φοσ.40
	SUB TOTAL			\$5,453.05
	LESS 20%			\$1,090.61
	DISCOUNTED TOTAL			\$4,362.44
	REAR NUMBER PLATE			\$50.00
	REVERSE SENSOR			\$180.00
	REAR BOOTLID COMFORT LOGO			\$30.00
	REAR BOOTLID TEL.NOS LOGO			\$30.00
	REAR BOOTLID APPS LOGO			\$40.00
	WINDSCREEN SEALANT			\$46.00
				\$376.00
	Labour Charge			
	PANEL BEATING			\$800.00
	SPRAY PAINT			\$600.00
	REMOVE / REFIX REVERSE SENSOR			\$50.00
	CHECK WIRING			\$50.00
	REMOVE / REFIX REAR WINDSCREEN GLASS			\$120.00
	ADVERTISEMENT LOGO - BUMPER			\$50.00
	ADVERTISEMENT LOGO - BOMFER ADVERTISEMENT LOGO - BOOTLID			\$100.00
				\$200.00
	ADVERTISEMENT LOGO - FENDER			\$200.00
	TOTAL LABOUR			\$1,970.00
	ESTIMATE TOTAL			\$6,708.44