SK0L225Q000C / KAN FOOK SING MOTOR WORKSHOP [539147] ENTRY DATE & TIME: 26/05/2022 17:41 (SGT) SUBMITTED BY: DARRELL LEK VERSION: 1 (26/05/2022 17:41 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 26/05/2022 17:41 (SGT) Date of Accident 24/05/2022 07:45 (SGT) Exact Location of Accident Singapore Additional Location Information BLOCK 603, YISHUN STREET 61 CARPARK Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Toyota

Auto

1598

Vehicle Registration Number SI B9138A

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner TAY SEOW YONG NRIC No. Email Address Mobile Phone No (Phone) +65 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Model Corolla Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car

Transmission

INSURANCE COMPANY

Name of Insurance Company MSIG Insurance (Singapore) Pte. Ltd. Type of Coverage Comprehensive Fleet Policy Policy Number D 300430497 QMY Cover Note Number

DRIVER

CC

Name of Driver TEE HOCK LYE (TAY HOCK LYE) NRIC No.

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	Indoor Male (Phone) + - No Parent No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Side Swipe Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? PASSENGER 1	No 2 No - Yes 2 No
Name Gender	MRS. TAY Female
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Police Station Name Police Station Phone No Alt. Police Station Phone No Police Station Address Was notice of intended Prosecution given? If yes, against whom?	Yes Clementi Neighbourhood Police Centre (Phone) +65-18008729999 (Fax) +65-68728039 No. Singapore 129858 No
CIRCUMSTANCES OF ACCIDENT	
REFER TO POLICE REPORT ATTACHED	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes No No
DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Registration Number Vehicle Manufacturer	SCL8000Z

Vehicle Model	-
Vehicle Variant	_
Vehicle Colour	_
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	-

SKETCH PLAN IMPORTANT NOTICE 1. Please report correctly the details of the accident to speed up the claims process. 2. This Formmust be completed by the Policyholder and/or the Authorised Driver. 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy flability. 4. The issue and acceptance of this Formby insurance companies is not an admission of policy liability on the part of the insurance companies. 5. Any false reporting may be referred to the Police for investigation. 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurence Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties. 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid. 8, Consent under the Personal Data Protection Act (PDPA) Lunderstand, acknowledge, agree and consent that: (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of : (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims; (ii) investigating the accident and/or my claims; (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me; (iv) administering my claims (including the maling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes") (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and (c) my Parsonal information may/can be disclosed by any of the haurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes. Policyholder's Signature / Date & Witnessed by Reporting Centre (If driver is not the po icyholder) / Date Driver Personnel Sketch Plan

	refor to	Police	VGPOVT	attached
Declaration	s are true in every respect			


































Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999

Lof 3 Report No. T/20220524/2029

REPORT OF A TRAFFIC ACCIDENT

	ne Report I 022 10:20	Made:	Vide Report No.:	Station Diary No.: 36
Informa	nt's Partic	ulars		
Name of TEE HO	f Informant: CK LYE		Address:	
ID Type NRIC NO	/ ID No.:		Contact No.: Home/Office:	Mobile:
National SINGAP	ity: ORE CITIZ	EN	Email:	
Sex: Male	Age:	Date of Birth:	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupati Drink Sta	ion: all Operator		Driving Licence Information: Class: 3	Date of Expiry:

General Infor	mation of the Accide	ent		
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 24/05/2022 07:4	Type of Location: Car Park
Location: YISHUN STR Weather: Clear	EET 61	Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collis Between Mov		wipe - Opposite Directi	on	Anyone conveyed by ambulance:

Details of V	ehicle Invo	lved		August 1		
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SCL8000Z	Car	TOYOTA		Blue	No Damage	0
SLB9138A	Car	TOYOTA	ALTIS	Blue	Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Police Station Of Origin: Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

CONTINUATION OF REPORT

Report No. T/20220524/2029

Driver		Mary Park		aluch - I	-	District Commence of the Comme
Name	Justin Chan Hong	Chiat		ID No),	
Related Vehicle	SCL8000Z (Car)			Conta	act No.	
Hospital/Clinic	NIL			Class Drivin Licen Expin	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc		NIL	
The state of the s	ted Medical Leave	NIL	Degree o		NIL	
Driver		No. of the last		STATE OF	Vellay!	NEW STATE OF THE PARTY OF THE P
Name	TEE HOCK LYE			ID No		
Related Vehicle	SLB9138A (Car)			Conta	ct No.	
Hospital/Clinic	NIL			Class Driving Licend Expiry	g se &	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Disc		NIL	
No. of Days grant	ted Medical Leave	NIL	Degree of		NIL	

Brief Details.

On 24/5/2022 at about 7.45am I was at the carpark of Blk 603 Yishun St 61. I was reverse parking my car SLB9138A, I was almost inside my parking lot when along came another car SCL8000Z. The other driver did not wait for me to enter completely into my parking lot and started to reverse his car into the opposite parking lot.

As such the front left tyre of the other car hit onto the front left portion of my car, causing the bumper of my car to be dented and dislodged.

Nobody was injured. We exchange particulars. I could see that there was no damage on his car and asked me to claim from insurance. Later he also message that there was no damage to his car. I do not have any in-car camera install inside my car.





Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999 CONTINUATION OF REPORT

Report No. T/20220524/2029

3 of 3

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: D /	Signature Of Informant:
SI SUHAIMI BIN NGAPI	神仙
Signature Of Interpreter: Not applicable	Date/Time: 24/05/2022 10:20
Officer In Charge Of Case: TP / GIA / SI TAN JEOK LENG Contact No.: 65476151	Classification Of Case:
NP168	

Reg no. 201924041Z

JP/92/22/2856/AR

Receipt

To: Tay Seow Yong

Invoice No:

2022/INV/ 0080

Your Reference:

Our Reference:

2022/05046

Date:

6/6/2022

Kaki Bukit AutoHub 2 Kaki Bukit Ave 2 #02-24 S417921

CC: Ace Chrome & Restorations Pte Ltd

Description	Amount S\$
<u>Particulars</u>	
Vehicle No: SLB9138A	
Accident Date : 24/5/2022	_
Date of Inspection: 31/5/2022	
Service:	
Assessment with report (inclusive of photographs and transport charges etc)	\$630
Total	Amount: \$630

Payment Details:

1) Cheque: Kindly make all cheques crossed and payable to PRECISE APPRAISER PTE LTD

2) Online Banking: Maybank 041-9107653-9

Precise Appraiser Pte Ltd

Address: 53 Hume Avenue, #05-08, Singapore 598751, Email: Preciseappraiser@gmail.com, Mobile: +65 9103 5000

Reg no. 201924041Z

JP /22/22/2856 /AR

Invoice

To: Tay Seow Yong

Invoice No:

2022/INV/ 0080

Your Reference:

Our Reference:

2022/05046

Date:

6/6/2022

CC: Ace Chrome & Restorations Pte Ltd Kaki Bukit AutoHub 2 Kaki Bukit Ave 2 #02-24 S417921

Description	Amount S\$
<u>Particulars</u>	
Vehicle No: SLB9138A	
Accident Date : 24/5/2022	
Date of Inspection: 31/5/2022	
Service:	
Assessment with report (inclusive of photographs and transport charges etc)	\$630
Total Amoun	t: \$630

Payment Details:

1) Cheque: Kindly make all cheques crossed and payable to PRECISE APPRAISER PTE LTD

2) Online Banking: Maybank 041-9107653-9

Precise Appraiser Pte Ltd

Address: 53 Hume Avenue, #05-08, Singapore 598751, Email: Preciseappraiser@gmail.com, Mobile: +65 9103 5000

VEHICLE DAMAGE ASSESSMENT REPORT

Reg no. 201924041Z

To: Tay Seow Yong

CC: Ace Chrome & Restorations Pte Ltd Kaki Bukit AutoHub 2 Kaki Bukit Ave 2 #02-24 S417921

JP/52/22/2856/AR

6/6/2022

31/5/2022

24/5/2022

31/5/2022

REFERENCES

Ref No : 2022/05046 Date of Report
Claim Type : Third Party Date of Request
Third party vehicle : SLB9138A Date of Accident
Insured Vehicle : Date of Inspection

Your Reference No :

DAMAGED VEHICAL PARTICULARS

Registration Plate No SLB9138A Engine Modification NIL Model / Make : Toyota Altis Pre-accident damage NIL Colour Grey **General Condition** Good 2019 Manufacturing Year General Paint Work Good **Engine No** : 1ZRY293183 Serviceable Steering **Engine Capacity** 1600 cc Handbrake Serviceable **Chassis No** : MR053REH104551178 Footbrake Serviceable

Odometer No : 68810
Transmission : Auto

TYRES CONDITION

 Front Right
 Rear Left
 x2

 Make
 : Michelin
 Make
 : Michelin

 Size
 : 205/55 r16
 4
 Size
 : 205/55 r16
 4

 Front Left
 Rear Right
 x2
 x2
 x2
 x2
 x3
 x4
 x4

 Make
 : Michelin
 Make
 : Michelin

 Size
 : 205/55 r16
 4
 Size
 : 205/55 r16

The above millimetres represent the remaining life of tyre treads

VEHICAL REPAIR COST

 Descriptions
 Repairer (\$\$)
 Difference (\$\$)
 Adjuster (\$\$\$)

 Parts
 4,609.98
 2,668.85

 Labour
 2,650.00
 1,930.00

 Calculated Cost (\$\$):
 7,259.98
 2,661.13
 4,598.85

Recommended Lump Sum Repair Cost (S\$)

Estimate Repair Duration : 5
Survery Inspection At : Ace Chrome & Restorations Pte Ltd
Survery Inspection Address : Kakl Bukit AutoHub

2 Kaki Bukit Ave 2 #02-24 S417921

3.700.00

Reg no. 201924041Z

DESCRIPTION OF DAMAGE


At the time of inspection, this vehicle sustained damages to the Front Lh Portion.

Front bumper, front lh fender dented, lh headlamp grazed, support panel push in etc.

Please see attached scheduled details.







SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated 5 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inpection Report and photographs.



Anthony Automotive Appraiser MSAAA

Disclaimer:

This survey was conducted by Precise Appraiser Pte Ltd without prejudice basis and we do not authorized repair. Report by Precise Appraiser Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle. All findings and recommendations are listed accordingly and final decision of settlement to your good selves parts thereof accordingly and final. No liability shall be attached to Precise Appraiser Pte Ltd therefore.

Our Reference : 2022/05046

Your Reference:

Vehicle Number: SLB9138A

	Qty	Description	Condition	Repairer	Our
				Estimate (S\$)	Assessment (S\$)
		Parts			
	1pcs	Front bumper	Dented	531.10	531.10
	1pcs	Front bumper center grille	Torn	170.10	170.10
	1pcs	Front bumper fog lamp	Serviceable	246.90	250
	1pcs	Front bumper fog lamp cover	Grazed	65.90	65.90
	1pcs	Front bumper side retainer	Torn	85.50	85.50
	1pcs	Front bumper sponge	Crack	90.10	90.10
	1pcs	Front bumper re enforcement	Dented	399.50	399.50
	1pcs	Front grille	Crack	643.00	643.00
	1pcs	Front grille logo	Necessary	47.90	47.90
	1pcs	Lh headlamp	Base Crack	927.60	927.60
	1pcs	Front Ih fender	Repair	789,40	20
12	1pcs	Front Ih fender inner shield	Torn	75.90	75.90
13	1pcs	Front Ih fender emblem "VVTI"	Necessary	75.00	75.00
	1pcs	Support panel	Repair	1,136.30	(77)
15	1pcs	Brace panel	Repair	149.40	157
16	1pcs	Air filter resonator	Holder Torn	237.50	237.50
17	1pcs	Air filter air duct	Deformed	142.20	142.70
			1		
			Total	5,813.30	3,491.80
			Less 25%	1,453.33	872.95
			Parts Sub Total	4,359.98	2,618.85
		Special Nett			
18	1sets	Front bumper clips	Necessary	80.00	50.00
- 1	1sets 1sets	Front bumper clips Front lh fender inner shield clips	Necessary Necessary	80.00 80.00	
19			'		50.00
19 20	1sets	Front Ih fender inner shield clips	Necessary	80.00	50.00 30.00
19 20	1sets 1sets	Front Ih fender inner shield clips Front grille clips	Necessary Necessary Dented	80.00 40.00 50.00	50.00 50.00 30.00 50.00
19 20	1sets 1sets	Front Ih fender inner shield clips Front grille clips	Necessary Necessary	80.00 40.00	50.00 30.00
19 20	1sets 1sets	Front Ih fender inner shield clips Front grille clips	Necessary Necessary Dented	80.00 40.00 50.00	50.00 30.00 50.00
19 20	1sets 1sets	Front Ih fender inner shield clips Front grille clips Front number plate	Necessary Necessary Dented	80.00 40.00 50.00	50.00 30.00 50.00
19 20 21	1sets 1sets 1pcs	Front Ih fender inner shield clips Front grille clips Front number plate Labour Check wiring	Necessary Necessary Dented Total	80.00 40.00 50.00 250.00	50.00 30.00 50.00 50.00
19 20 21	1sets 1sets 1pcs	Front Ih fender inner shield clips Front grille clips Front number plate Labour	Necessary Necessary Dented Total	80.00 40.00 50.00 250.00	50.00 30.00 50.00 50.00
19 20 21 1	1sets 1sets 1pcs	Front Ih fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works	Necessary Necessary Dented Total	80.00 40.00 50.00 250.00 50.00	50.00 30.00 50.00 50.00 450.00
19 20 21	1sets 1sets 1pcs	Front Ih fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea	Necessary Necessary Dented Total	80.00 40.00 50.00 250.00	50.00 30.00 50.00 50.00 450.00
19 20 21 1	1sets 1sets 1pcs	Front Ih fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea on front both wheel housing. To regreat front bumper	Necessary Necessary Dented Total	80.00 40.00 50.00 250.00 50.00	50.00 30.00 50.00 50.00 450.00
19 20 21 1	1sets 1sets 1pcs	Front Ih fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea	Necessary Necessary Dented Total	80.00 40.00 50.00 250.00 50.00	50.00 30.00 50.00 50.00 450.00
19 20 21 1 2	1sets 1sets 1pcs	Front Ih fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea on front both wheel housing. To r&r front bumpe headlamp and others attachments.	Necessary Necessary Dented Total it and straighten er, front lh fender,	80.00 40.00 50.00 250.00 50.00 500.00	50.00 30.00 50.00 50.00 450.00 600.00
19 20 21 1	1sets 1sets 1pcs	Front lh fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea on front both wheel housing. To r&r front bumpe headlamp and others attachments. To respray on front bumper, front lh fender, front	Necessary Necessary Dented Total it and straighten er, front lh fender,	80.00 40.00 50.00 250.00 50.00	50.00 30.00 50.00 50.00
19 20 21 1 2	1sets 1sets 1pcs	Front Ih fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea on front both wheel housing. To r&r front bumpe headlamp and others attachments.	Necessary Necessary Dented Total it and straighten er, front lh fender,	80.00 40.00 50.00 250.00 50.00 500.00	50.00 30.00 50.00 50.00 450.00 600.00
19 20 21 1 2 3	1sets 1sets 1pcs	Front lh fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea on front both wheel housing. To r&r front bumpe headlamp and others attachments. To respray on front bumper, front lh fender, from support panel and accident affected areas.	Necessary Necessary Dented Total it and straighten er, front lh fender,	80.00 40.00 50.00 250.00 500.00 1,000.00	50.00 30.00 50.00 50.00 450.00 600.00
19 20 21 1 2	1sets 1sets 1pcs	Front lh fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea on front both wheel housing. To r&r front bumpe headlamp and others attachments. To respray on front bumper, front lh fender, front	Necessary Necessary Dented Total it and straighten er, front lh fender,	80.00 40.00 50.00 250.00 50.00 500.00	50.00 30.00 50.00 50.00 450.00 600.00
19 20 21 1 2 3	1sets 1sets 1pcs	Front lh fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea on front both wheel housing. To r&r front bumpe headlamp and others attachments. To respray on front bumper, front lh fender, from support panel and accident affected areas.	Necessary Necessary Dented Total at and straighten er, front lh fender, at lh wheeel housing.	80.00 40.00 50.00 250.00 500.00 1,000.00 1,000.00	50.00 30.00 50.00 50.00 450.00 600.00 50.00
19 20 21 1 2 3	1sets 1sets 1pcs	Front lh fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea on front both wheel housing. To r&r front bumpe headlamp and others attachments. To respray on front bumper, front lh fender, from support panel and accident affected areas.	Necessary Necessary Dented Total it and straighten er, front lh fender,	80.00 40.00 50.00 250.00 50.00 1,000.00 1,000.00	50.00 30.00 50.00 50.00 450.00 600.00 50.00
19 20 21 1 2 3	1sets 1sets 1pcs	Front lh fender inner shield clips Front grille clips Front number plate Labour Check wiring To reprogramme after the accident repair works To cut and weild on support panel. To panel bea on front both wheel housing. To r&r front bumpe headlamp and others attachments. To respray on front bumper, front lh fender, front support panel and accident affected areas. Rust Proofing	Necessary Necessary Dented Total at and straighten er, front lh fender, at lh wheeel housing.	80.00 40.00 50.00 250.00 50.00 500.00 1,000.00 1,000.00 2,650.00	50.00 30.00 50.00 50.00 450.00 600.00

Address: 53 Hume Avenue, #05-08, Singapore 598751, Email: Preciseappraiser@gmail.com, Mobile: +65 9103 5000

Precise Appraiser Pte Ltd Reg no: 201924041Z

Adjustment / Recommendations

Note: For Lump Sum Repair

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).

The final adjusted Lump Sum contract amount is \$\$3,700.

Under normal circumstances, the repair period would be about 5 working days.

JP/52/22/2856 [AR

Precise Appraiser Pte Ltd Reg no. 201924041Z

INSPECTION PHOTOS



Our Ref: 2022/05046 Vehicle No.: SLB9138A

Page 1 of 18

Our Ref: 2022/05046 Vehicle No.: SLB9138A



Our Ref: 2022/05046 Vehicle No.: SLB9138A

INSPECTION PHOTOS








Our Ref: 2022/05046 Vehicle No.: SLB9138A




Our Ref: 2022/05046 Vehicle No.: SLB9138A



Our Ref: 2022/05046 Vehicle No.: SLB9138A

INSPECTION PHOTOS












Our Ref: 2022/05046 Vehicle No.: SLB9138A





Our Ref: 2022/05046 Vehicle No.: SLB9138A




Our Ref: 2022/05046 Vehicle No.: SLB9138A


INSPECTION PHOTOS




Our Ref: 2022/05046 Vehicle No.: SLB9138A




Our Ref: 2022/05046 Vehicle No.: SLB9138A



Our Ref: 2022/05046 Vehicle No.: SLB9138A



Our Ref: 2022/05046 Vehicle No.: SLB9138A







Our Ref: 2022/05046 Vehicle No.: SLB9138A









Our Ref: 2022/05046 Vehicle No.: SLB9138A

INSPECTION PHOTOS









Your Ref : $SCL \ 8000Z$ Fax : $6538 \ 3708$ Our Ref : $JP/SL/22/SLB \ 9138A/AR$ Tel : $3152 \ 0985$

Date : 27 May 2022 Email : jiapei@kscgp.com

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

BY EMAIL ONLY

DATE OF ACCIDENT: 24 MAY 2022 NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of SLB 9138A to notify you of a road traffic accident on 24 May 2022 at about 7.45 a.m at Blk 603, Yishun Street 61 carpark, involving our client's vehicle registration number SLB 9138A and vehicle registration number SCL 8000Z which was insured by you at the material time. A copy of the Singapore accident statement is enclosed herein.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

f sl

Enc.

Your Ref : SNM22D203695 Fax : **6538 3708**

Our Ref : JP/SL/22/SLB 9138A/AR Tel : 3152 0985

Date : 27 May 2022 Email : jiapei@kscgp.com

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD BY EMAIL ONLY

DATE OF ACCIDENT: 24 MAY 2022 NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Name of Surveyor	Company Name
1.	Anthony Lim	Precise Appraisers Pte Ltd
2.	Nicky Seah	Absolute Appraisal Services Pte Ltd
3.	Andrew How	Prominent Appraiser Services Pte Ltd

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Ace Chrome Restorations & Automotive

2 Kaki Bukit Avenue 2 #02-24 Kaki Bukit Autohub

Singapore 417921

. Ah Tiong / HP: 9646 0253

Contact Person/Tel

Yours faithfully,

SL

Your Ref : SNM22D203695

Our Ref : JP/SL/22/SLB 9138A/AR

Date : 23 May 2022

Acknowledgement

Thi		[Full Name of Surveyor] of Surveyor's Company] have completed as follows:-			
(a)	Pre- Repair Survey/Inspection on		•		
	Name and signature of Appointed Surveyor Company Stamp	Witnessed by: Date:			
(b)	Pre- Repair Survey/Inspection (during disman	tling) on	[Date] at[Time].		
	Name and signature of Appointed Surveyor Company Stamp	Witnessed by: Date:			
(c)	Re-inspection of new replacement part (part by part) on [Date] at[Time].				
	Name and signature of Appointed Surveyor Company Stamp	Witnessed by: Date:			
(d)	Post – Repair Survey/Inspection on	[Date] at	[Time].		
	Name and signature of Appointed Surveyor Company Stamp	Witnessed by: Date:			

Your Ref
Our Ref
Date

Acknowledgement

Thi	1 1 6	[Full Name of Surveyor] of Surveyor's Company] have completed as follows:-
(a)	Pre- Repair Survey/Inspection on 31/5/	[Date] at 163 (Time].
	Thuan 22 LAM	
	Name and signature of Appointed Surveyor Company Stamp	Witnessed by: Date:
(b)	Pre- Repair Survey/Inspection (during disma	ntling) on $1/6/77$ [Date] at 170 [Time].
	Theran M	
	Name and signature of Appointed Surveyor Company Stamp	Witnessed by: Date:
(c)	Re-inspection of new replacement part (part	by part) on [Date] at[Time].
	Name and signature of Appointed Surveyor	Witnessed by:
	Company Stamp	Date:
(d)	Post – Repair Survey/Inspection on 4/6	[Date] at [Time].
	Thwan Lth A	
	Name and signature of Appointed Surveyor Company Stamp	Witnessed by: Date:



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Date of Request: 10/06/2022 Your Ref No: JP/SL/22/2856/AR

Dear Sir/Madam,

Date of Accident: 24/05/2022 00:00 (SGT)

Vehicle No: SLB9138A Place of Accident: Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)	
SCL8000Z	Singapore	(31.00)	1	(28.97)	
GST Amount					
Total Amount Due (GS	(31.00)				

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.

SC1G2261000B / CHENG HOE MOTOR PTE LTD[768761] ENTRY DATE & TIME: 01/06/2022 16:37 (SGT) SUBMITTED BY: CHIONG BENG CHOON VERSION: 1 (01/06/2022 16:37 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 01/06/2022 16:37 (SGT) Date of Accident 24/05/2022 07:33 (SGT) Exact Location of Accident Singapore Additional Location Information HDB CARPARK Y33 (YISHUN ST 61) Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCL8000Z

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner JUSTIN CHAN HONG CHIAT (JUSTIN ZENG HONGJIE)

VEHICLE PARTICULARS

Manufacturer Toyota

Model C-HR HYBRID 1.8G CVT

Variant

Vehicle Category Private car Transmission Auto 1797

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.

Type of Coverage Comprehensive

Fleet Policy

Policy Number DMPCSNA00010512201 Cover Note Number 13/01/22 - 12/01/23

DRIVER

Name of Driver JUSTIN CHAN HONG CHIAT (JUSTIN ZENG HONGJIE)

NRIC No S7913107E

Address BLK 422 HOUGANG AVE 6 #03-118

Address complement

530422 Does Driver Own Other Vehicles? No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Major/Minor Rd
Weather Conditions Clear

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Was anybody injured in the Accident? No
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1

REFER ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No
Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration NumberSLB9138BVehicle Manufacturer-Vehicle Model-Vehicle Variant-Vehicle Colour-Vehicle CategoryPrivate carName of Driver-Insurance Company Name-

SKETCH PLAN

1. VEHICLE NO .: SCL 8000Z

2. INSURER CO: China Taiping

3.ACCIDENT DATE & TIME:

24 5 22 7.33am

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

s Signature / Date & Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre

Personnel

Sketch Plan


PLEASE
TURN
OVER

Sketch Plan
HDB
Corporle 133
112 pm 24 61
2002
SCI 80002
 Interview of a property of the property of the contract.
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
On 24 May 2022, at around 933 hr. The Vehicle SCL 8000Z, driver
by me, Justin Chan, had an accident with vehicle number 52891384
driven by a Mr. Tee Hock Lye (50192321H). The accident hoppined
inside HDB corporat 433 along Young Street 61.
The Cr 5LB 9 138 B Was in front of me, and offer it
reversed into Lot 16 (apposite Blk 603), moved my or forward
and extempted + reverse into lot 45 opposite lot 15 in corport 433.
However, my car knocked into the vehicle SLB 9138 A as 1
WE reversige, cousing domine + its first bumper. There was no
buping it my revene servor & no dimoge to my ar. Mr Tec
claimed that his relicle has yet to be fully reversely into Lot 16,
but my view was that he had moved his car out (adjusting)
when I was revising.
the state of the s
16
Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim
under your own comprehensive policy. Please check with your policy for more information.
DECLARATION
I/We declare the foregoing particulars are true in every respect.
1: 2
Policyholder's Signature Driver's Signature Reporting Centre Personnel's Signature
Date & Time: (If driver is not the policyholder) Name: Date & Time: NRIC/FIN No.:
() Claim Own Policy () Claim Third Party (Reporting Only
() Claim OD/TP at other workshop ()













INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SCL8000Z

Date of Accident

24/05/2022

Reset

% RESULT & RECEIPT

TP Insurer Enquiry Insurance China Taiping Insurance (Sing... Period of Insurance 13/01/2022 - 12/01/2023 Requested By KSCGP02 (KSCGP JURIS LLP) Requested Date 27/05/2022 08:41

Payment details

Request Amount: **\$\$1.87** GST Amount: **\$\$0.13**

Total Amount Due (GST Inclusive): **\$\$2**

General Insurance Association

Records Management Centre GST Registration No: **M400017735**



Enquire Vehicle's Insurance Particulars (As At 24 May 2022 / 07:45:00)

Vehicle No.: Make Description/Model:

SCL8000Z TOYOTA / C-HR HYBRID 1.8G CVT

Insurance Company Name:

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Business Transaction Reference No.:

20220616112638647867

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).