

The Motor Claims Department
M/s Lonpac Insurance Bhd
300 Beach Road, #17-04/07
The Concourse
Singapore 199555

File No : SH/2021
Date : 28-May-2022

Estimated cost of repair for vehicle no : SJV4344Y Toyota Vios
Policy no: Z22VP05030556 Accident Date: 25.05.2022

Description	Quantity		Cost Price
Bonnet	1	\$	190.00
RH Bonnet hinge	1	\$	28.00
LH Bonnet hinge	1	\$	28.00
Bonnet lock	1	\$	38.00
Front grille	1	\$	90.00
Front grille clips (1 set)	1	\$	18.00
Front grille chrome moulding	1	\$	38.00
RH head lamp	1	\$	160.00
LH head lamp	1	\$	160.00
RH front fender	1	\$	150.00
LH front fender	1	\$	150.00
RH front fender wheel cowling	1	\$	65.00
LH front fender wheel cowling	1	\$	65.00
Front fender wheel cowling clips (1 set)	2	\$	48.00
Front bumper	1	\$	180.00
Front bumper clips (1 set)	1	\$	28.00
Front bumper centre grille	1	\$	38.00
Front bumper tow cover	1	\$	20.00
Front bumper reinforcement	1	\$	150.00
RH Front bumper fog lamp cover	1	\$	36.00
LH Front bumper fog lamp cover	1	\$	36.00
RH Front bumper retainer	1	\$	35.00
LH Front bumper retainer	1	\$	35.00
Front bumper under dust cover	1	\$	50.00
Front bumper centre top bracket	1	\$	120.00
Front support panel	1	\$	250.00
Front support panel top garnish	1	\$	50.00
Front support panel top garnish clips (1 set)	1	\$	18.00
Air con condensor	1	\$	180.00
Air con condensor pipe inlet	1	\$	170.00
Air con condensor pipe outlet	1	\$	140.00
RH Air con condensor air guide	1	\$	30.00
LH Air con condensor air guide	1	\$	30.00
Radiator	1	\$	170.00
Radiator top hose	1	\$	25.00
Radiator lower hose	1	\$	25.00
Radiator auto fan cowling	1	\$	110.00

Radiator auto fan blade	1		\$	65.00
Radiator auto fan motor	1		\$	150.00
Engine air cleaner	1		\$	290.00
Engine air cleaner air duct	1		\$	45.00
Steering wheel air bag	1		\$	850.00
Steering wheel clock spring	1		\$	180.00
Air bag ECU	1		\$	450.00
Air bag sensors	2		\$	320.00
RH front seat belt	1		\$	320.00
			\$	5,824.00
		Add 15%	\$	873.60
			\$	6,697.60
Front number plate	1	S. nett	\$	45.00
Engine coolant	1	S. nett	\$	30.00
To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality			\$	120.00
To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member, to replace damaged parts and adjust body panel alignment			\$	650.00
To remove and install dashboard and centre console, including instrument panel, centre info screen, radio, climate control module. To remove & install RH air bags, clockspring, and air bag ECU. To remove RH front seats to remove and install RH front seat belt			\$	350.00
To reprogram air bag ECU and clear fault codes.			\$	380.00
To spray paint affected front and inner damaged portion inclusive of preparatory works and material			\$	1,300.00
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp			\$	50.00
			\$	9,622.60