



The Motor Claims Department
M/s Lonpac Insurance Bhd
300 Beach Road, #17-04/07
The Concourse
Singapore 199555

File No : SH/2022/118/05/004/OD
Date : 01-June-2022

Supplementary estimated cost of repair for vehicle no: SJV4344Y Toyota Vios
Policy No: Z22VP05030556 **Accident Date:** 25.05.2022

Description	Quantity	Cost Price
RH front bumper reinforcement bracket	1	\$ <i>R</i> 65.00 ✓
LH front bumper reinforcement bracket	1	\$ <i>R</i> 65.00 ✓
Front windscreen	1	\$ <i>RM</i> 260.00 ✓
Front windscreen moulding	1	\$ <i>RM</i> 40.00 ✓
RH AC condensor frame	1	\$ <i>CM</i> 25.00 ✓
LH front bumper under dust cover	1	\$ <i>CM</i> 50.00 ✓
		\$ 505.00
	Add 15%	\$ 75.75
		\$ 580.75
Front windscreen sealant	1	s. nett \$ <i>RM</i> 60.00 <i>gata</i>
Front windscreen inner rubber seal	1	s. nett \$ <i>RM</i> 28.00 ✓
To remove and reinstall front windscreen and conduct water leak test		\$ 120.00 ✓
		<u>\$ 788.75</u>