

# REPAIR DETAILS

Att: MR. Kenneth

SJR 8028E

71/CH/MA

## Reference

**Part Source:** (Last Synchronised: 30 May 2022)  
**Parts:** N/A MAZDA 5 2.0 SP.6EAT SUNROOF (A) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SJR8028E)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	*430.00 F ✓
2	1		*1 PC RERA BUMPER REINFORCEMENT	0.00	0.00	*95.00 F X 7f
3	1		*6 PCS REAR BUMPER CLIP @2/PCE	0.00	0.00	*12.00 F ✓
4	1		*1 PC TAILGATE	0.00	0.00	*650.00 F ✓
5	1		*1 PC TAILGATE LOGO	0.00	0.00	*35.00 F ✓
6	1		*1 PC TAILGATE EMBLEM - MAZDA 5	0.00	0.00	*30.00 F ✓
7	1		*1 PC TAILGATE EMBLEM - ACTIV	0.00	0.00	*33.00 F ✓
8	1		*1 PC TAILGATE INNER LOCK	0.00	0.00	*140.00 F ✓
9	1		*1 PC TAILGATE INNER RUBBER	0.00	0.00	*85.00 F X 2
10	1		*2 PCS REVERSE SENSOR @85/PCE	0.00	0.00	*170.00 F 7
11	1		*1 PC REAR END PANEL	0.00	0.00	*230.00 F X 7
12	1		*1 PC REAR END PANEL INNER TOP GARNIHS	0.00	0.00	*48.00 F X 7
13	1		*1 PC REAR WINDSCREEN MOULDING	0.00	0.00	*70.00 F ✓
Total Parts (\$\$)						2,028.00

F=Franchise part.

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 PC REAR WINDSCREEN GUM	40.00 ✓
Sub Total (\$\$)			40.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
1	1) TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00 ✓
2	2) TO REMOVE AND REFIX TAILGATE, TOP SPOILER, REAR WIPER ASSY, LOCK ASSY; CTU, WELD AND RENEW RR END PANEL AND RE-ALIGN TO SAME	New	550 800.00 7
3	3) TO PUTTY AND RESPRAY ON REAR PANEL, TAILGATE, TAILGATE LOWER GARNISH, REAR BUMPER, REINFORCEMENT	New	750 900.00
4	4) TO REMOVE AND REFIX REVERSE CAMERA, SENSOR, SMART KEY SENSOR AND RESET SYSTEM	New	50.00 ✓
5	5) TO RUSTPROOFING	New	30 60.00 7
Gross Labour Cost (\$\$)			1,910.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Supp 1

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 30 Jun 2022)

**Parts:** N/A MAZDA 5 2.0 SP.6EAT SUNROOF (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** Cheng Hoe Motor Pte Ltd/SJR8028E/30/06/2022 13:38

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC TAILGATE LOWER OUTER PROTECTOR	0.00	0.00	*220.00 F
2	1		*1 PC REAR BUMPER INNER SQUARE CLIP	0.00	0.00	*6.00 F

F=Franchise part.

Total Parts (S\$) **226.00**

Cheng Hoe Motor Pte Ltd/SJR8028E/30/06/2022 13:38. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

### Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/SJR8028E/30/06/2022 13:38. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >