

ASS. REC. BY: TG Lim

REF:

CC6/AIG22005060/Bea3Asher

ASSIGNMENT

From: _____ Date: 30/5/2022

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKU 7991Cat Workshop m/s Dean Autoproof 100 Sin Ming Dr # 01-14

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 62,000/-

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKU 7991C Yr Regn: 2/12/2009Type: M / Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Wish C.C. 1987Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 231075 T/Radio: Insured / Std / NI / NAEng/No: 38RA416333C/No: JTDGJ20W505001479Gen. Cond: Good / Fair / Poor / BurntSteering: In / order / Jammed / Leaked / Burnt orBrake: In / order / Jammed / Leaked / Burnt orModi: Nil / 8 / Rim / STD A/Rim orTyre Size: F: 195/65/15R: 195/65/15BS / DUN / EXNOVA / GY / FS / LIZA / W / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 29/5/2022 D.O.I. 30/5/2022Survey held at Dean AutoproDes. of Damages: Frt / Rear / Q / S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range : <u>5,000/- - 6,000/-</u>
	Recommended CR: <u>██████████</u> L/S \$5,800
	MV <u>62,000/-</u> PV <u>24,492/-</u> NV <u>37,508/-</u>
	<u>TG Lim</u> <u>1/6/2022</u>
	<u>TG Lim</u> <u>30/5/2022</u>

Date/Time, File Pass to? ☐ : Preli. Report1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B. / C) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SKU 7991 C**

Model : Toyota Wish

Year : _____

Chassis No : JTDGW20W505001479

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front fender RH	1	\$ 987.00	\$ 987.00
2	Front fender inner cowling RH	1	\$ 180.30	\$ 180.30
3	Front door RH	1	\$ 1,526.50	\$ <u>1295.00</u> 1,526.50
4	Front door black tape RH	1	\$ 92.60	\$ <u>25.00</u> 92.60
5	Front door weatherstrip RH	1	\$ 272.00	\$ <u>154.90</u> 272.00
6	Front door inner lock RH	1	\$ 358.30	\$ 358.30
7	Front door inner lock striker RH	1	\$ 68.00	\$ 68.00
8	Front door frame rubber RH	1	\$ 106.90	\$ 106.90
9	Front door trimboard RH	1	\$ 397.90	\$ 397.90
10	Front door regulator RH	1	\$ 332.00	\$ <u>158.00</u> 332.00
11	Front door regulator motor RH	1	\$ 421.00	\$ <u>421.00</u> 421.00
12	Front door glass channel RH	1	\$ 177.30	\$ <u>154.30</u> 177.30
13	Front door outer handle RH	1	\$ 210.00	\$ 210.00
14	Front door outer moulding RH	1	\$ 104.00	\$ 104.00
15	Front door hinge RH	2	\$ 85.00	\$ 170.00
16	Front door checker RH	1	\$ 131.90	\$ 131.90
17	Side mirror assy RH	1	\$ 685.00	\$ 685.00
18	Door centre pillar RH	1	\$ 827.50	\$ <u>465.00</u> 827.50
19	Rear door RH	1	\$ 1,467.50	\$ <u>1087.90</u> 1,467.50
20	Rear door black tape RH	1	\$ 92.60	\$ <u>25.00</u> 92.60
21	Rear door weatherstrip RH	1	\$ 272.00	\$ <u>154.00</u> 272.00
22	Rear door inner lock RH	1	\$ 328.90	\$ 328.90
23	Rear door inner lock striker RH	1	\$ 86.50	\$ 86.50
24	Rear door trimboard RH	1	\$ 397.90	\$ 397.90
25	Rear door frame rubber RH	1	\$ 106.90	\$ 106.90
26	Rear door regulator RH	1	\$ 332.00	\$ <u>158.00</u> 332.00
27	Rear door regulator motor RH	1	\$ 421.00	\$ 421.00
28	Rear door glass channel RH	1	\$ 177.30	\$ 177.30
29	Rear door outer handle RH	1	\$ 210.00	\$ 210.00
30	Rear door outer moulding RH	1	\$ 104.00	\$ 104.00
31	Rear door hinge RH	2	\$ <u>63.00</u> 85.00	\$ <u>126.00</u> 170.00
32	Rear door checker RH	1	\$ 102.80	\$ 102.80
33	Side skirt RH	1	\$ 785.30	\$ <u>650.00</u> 785.30
34	Rocker panel RH	1	\$ 615.00	\$ 615.00
35	Rear fender RH	1	\$ 1,137.50	\$ 1,137.50
36	Rear fender inner trim board RH	1	\$ 918.00	\$ 918.00
37	Rear fender inner cowling RH	1	\$ 185.90	\$ 185.90
38	Rear fender side glass moulding RH	1	\$ 227.60	\$ 227.60

2009
 NDX
 NDX
 DDV
 NECV
 TNV
 JMV
 NDX
 NDX
 BRV
 BTV
 JMV
 NECV
 NDX
 } NDX
 NDX
 NDX
 DDV
 DDV
 NECV
 TNV
 } NDX
 } NDX
 BTV
 NDX
 } NDX
 BTV
 NDX
 BRV
 DDV
 } NDX

39	Front knuckle arm RH	1	\$	398.00	\$	398.00
40	Front knuckle arm bearing RH	1	\$	245.50	\$	245.50
41	Front shock absorber RH	1	\$	364.00	\$	364.00
42	Front lower arm RH	1	\$	535.25	\$	535.25
43	Steering rack	1	\$	1,108.00	\$	1,108.00
44	Rear shock absorber RH	1	\$	412.50	\$	412.50
45	Rear axle	1	\$	1,688.00	\$	1,688.00
46	Rear wheel hub with bearing RH	1	\$	369.80	\$	369.80

Parts Sub Total : \$ 6245.30 20,307.95

Discount 25% : \$ 1561.33 5,076.99

PARTS TOTAL : \$ 4683.98 15,230.96

Nos.	SPECIAL NETT ITEMS	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$	80.00
2	Front fender sealant	1	\$	100.00
3	Front fender inner cowling clips	1	\$	50.00
4	Front door sealant	1	\$	100.00 \$ 30.00
5	Front door speaker	1	\$	210.00
6	Front door trimboard clips	1	\$	50.00 \$ 30.00
7	Side mirror seal	1	\$	60.00
8	Door centre pillar sealant	1	\$	100.00 \$ 30.00
9	Rear door sealant	1	\$	100.00 \$ 30.00
10	Rear door speaker	1	\$	210.00
11	Rear door trimboard clips	1	\$	50.00
12	Side skirt clips	1	\$	50.00 \$ 30.00
13	Rocker panel sealant	1	\$	100.00 \$ 20.00
15	Rear fender sealant	1	\$	100.00
16	Rear fender inner trim board clips	1	\$	50.00
17	Rear fender inner cowling clips	1	\$	50.00
18	Rear fender side glass sealant	1	\$	100.00
19	Rear fender side glass inner seal	1	\$	60.00
20	Rear fender side glass primer & cleaner	1	\$	80.00
21	Front & rear alloy rim RH	2	\$	1,960.00
22	Front & rear tyre RH	2	\$	960.00

SPECIAL NETT TOTAL : \$ 170.00 4,620.00

Nos.	LABOUR	S\$	
1	R&R front door component	\$ 80.00	150.00
2	R&R Door centre pillar inner garnish	\$ 30.00	100.00
3	R&R rear door component	\$ 80.00	150.00
4	R&R rear fender side glass	\$	250.00
5	R&R fuel tank pipe	\$	150.00
6	R&R rear bumper reverse sensor	\$	100.00
7	R&R front & rear under carriage	\$	600.00
8	R&R front & rear tyre and balancing	\$	200.00
9	R&R steering rack	\$	150.00
10	Wheel alignment	\$	180.00
11	Check wiring	\$ 50.00	100.00
12	Upholstery	\$	300.00
13	Diagnostic reset fault code	\$	300.00
14	Panel beat	\$ 1200.00	1800.00
15	Rust proofing	\$	200.00
16	Spray paint	\$ 1000.00	1800.00
LABOUR TOTAL :		\$	6,530.00

NNX

NNX

NNX

2440.00

PARTS TOTAL :	\$	15,230.96
SPECIAL NETT TOTAL :	\$	4,620.00
LABOUR TOTAL :	\$	6,530.00
GRAND TOTAL :	\$	26,380.96

PARTS 4683.98
 SN 170.00
 LABOUR 2440.00
 7293.98
 @20% 1458.80
 5835.18

TGlim Min
 1/6/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: