

## Vehicle Damage Assessment Report for [SND3111G]

Estimate Created: 16/06/2022 08:56 by LKK\_admin-a  
(LKK\_Auto\_Consultants\_Pte\_Ltd)

Owned: 14/12/2022 04:57 by LKK\_cs-a (LKK\_Auto\_Consultants\_Pte\_Ltd)

### General Information

---

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

### Vehicle Information

---

Brand	Opel	Model	Crossland
Engine Type			
License Plate Number	SND3111G	VIN (or Chassis #)	

### Vehicle Condition

---

Damaged Diagram	Odometer	4,304.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

### Comments

---

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COR AT \$ 4,043.40 WITH 3 DAYS

Insurlogic 5 (14/12/2022 04:56)

**Parts**

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
RR TAILGATE OPEL LOGO		1	92.00	-10.00 %	82.80
RR TAILGATE CROSSLAND X EMBLEM		1	85.00	-10.00 %	76.50
RR TAILGATE WEATHERSTRIP		1	414.00	-10.00 %	372.60
RR BUMPER CENTRE		1	1120.00	-10.00 %	1,008.00
RR BUMPER REFLECTOR RH		1	124.00	-10.00 %	111.60
RR BUMPER TOW COVER		1	112.00	-10.00 %	100.80
RR BUMPER SIDE RETAINER RH (INNER)		1	161.00	-10.00 %	144.90
RR BUMPER CENTER RETAINER		1	164.00	-10.00 %	147.60
RR BUMPER LOW BRACKET CENTRE RH		1	95.00	-10.00 %	85.50
RR BUMPER REINFORCEMENT		1	703.00	-10.00 %	632.70
RR BUMPER REVERSE SENSOR INNER		1	207.00	-10.00 %	186.30
RR BUMPER REVERSE SENSOR RUBBER SEAL		1	72.00	-10.00 %	64.80
RR END PANEL AIR DUCT		1	126.00	-10.00 %	113.40
RR BUMPER LOWER GARNISH		1	451.00	-10.00 %	405.90

Parts Subtotal 3,533.40

**Materials**

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
RR BUMPER CLIP		1.0	30.00	0.00 %	30.00

Materials Subtotal 30.00

**Labor**

## Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPAIR/REPLACE DAMAGED PARTS	RnR	200.00	0.00 %	200.00
WIRING CHARGE	RnR	30.00	0.00 %	30.00
REMOVE/REFIT REVERSE SENSOR	RnR	50.00	0.00 %	50.00

**Repair**

Description	Severity	Cost	Markup/Disc %	Price
RR END PANEL	Medium	0.00	0.00 %	0.00
RR TAILGATE	Medium	0.00	0.00 %	0.00

**Paint**

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING	Full spray	200.00	0.00 %	200.00

Labor Rate            S\$ 50 / Hour

General Labor Subtotal    280.00

Paint Labor Subtotal      200.00

---

Labor Subtotal            480.00

**Summary**

Repair Cost	4,043.40
Discount(0 %)	(0.00)
	4,043.40
Excess	(0.00)
GST(0.00 %)	0.00
<hr/> Grand Subtotal	4,043.40