



**Auto Insure Pte. Ltd.**  
6 Marsiling Lane  
Singapore (739145)  
E: claims01@autoinsure.com.sg  
W: www.autoinsure.com.sg  
T: 3157 2626 F: 6368 0081  
**GST No.: 201437380M**

**Page No.1**

**AUTOMOBILE ASSESSMENT REPORT**

Our Ref: **GBL2394M (MARVYN)**

Date: **25-May-22**

BY EMAIL ONLY  
(claims01@autoinsure.com.sg)

**ATTENTION: MOTOR CLAIMS DEPT**

**Allianz Insurance Singapore Pte. Ltd**

79 Robinson Road  
#09-01,  
Singapore 068897

**Assessed Vehicle No** : **GBL2394M**  
**Car Make and Model** : **TOYOTA HIACE DX 2.8 AUTO**  
**Date of Accident** : **15-May-22**  
**Date of Assessment** : **25-May-22**

We have carried out a physical assessment of GBL2394M at our workshop Auto Insure Pte Ltd sustained damages to the FRONT portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the FRONT portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **P/P**  
Adjusted Amount : **\$ 22,309.50**  
Est. Repair Days : **18**



Pursuant to your instruction, we have **AUTHORIZED to** repair.  
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

**AUTO INSURE PTE. LTD.** For any reliance on this report by any third party.

Our Ref: **GBL2394M**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
		<b><u>PARTS REPLACEMENT - LIST ITEMS</u></b>		
1	1	FRONT WINDSCREEN		\$ 720.00
2	1	FRONT WINDSCREEN MOULDING		\$ 55.00
3	1	FRONT WINDSCREEN WIPER ARM RH		\$ 60.00
4	1	FRONT WINDSCREEN WIPER ARM LH		\$ 60.00
5	1	FRONT WINDSCREEN WIPER MOTOR		\$ 420.00
6	1	FRONT WINDSCREEN WIPER LINKAGE		\$ 160.00
7	1	FRONT WIPER COVER		\$ 20.00
8	1	FRONT WIPER TANK		\$ 100.00
9	1	FRONT COWL PANEL		CHECK
10	1	BONNET		\$ 265.00
11	1	BONNET HINGE RH		\$ 45.00
12	1	BONNET HINGE LH		\$ 45.00
13	1	BONNET SUPPORT		\$ 220.00
14	1	FRONT FENDER RH		\$ 100.00
15	1	FRONT FENDER BRACKET RH		CHECK
16	1	FRONT FENDER LH		\$ 100.00
17	1	FRONT FENDER BRACKET LH		CHECK
18	1	FRONT FENDER SIDE MIRROR ASSEMBLY LH		\$ 145.00
19	1	FRONT UPPER GRILLE		\$ 160.00
20	1	FRONT LOWER GRILLE		\$ 280.00
21	1	FRONT GRILLE BASE		\$ 265.00
22	1	FRONT BUMPER		\$ 205.00
23	1	FRONT BUMPER LOWER GRILLE		\$ 85.00
24	1	FRONT BUMPER LOWER COVER RH		\$ 45.00
25	1	FRONT BUMPER LOWER COVER LH		\$ 45.00
26	1	FRONT BUMPER REINFORCEMENT		\$ 135.00
27	1	FRONT PANEL CROSSMEMBER		CHECK
28	1	FRONT LOCK CARRIER PANEL		CHECK
29	1	FRONT SUPPORT PANEL		\$ 220.00
30	1	FRONT LOWER CROSSMEMBER		CHECK
31	1	FRONT SUPPORT PANEL STRUT		CHECK
32	1	FRONT ENGINE FIREWALL		CHECK
33	1	FRONT ENGINE FIREWALL INSULATION		CHECK
34	1	FRONT FUSE BOX TOP COVER		CHECK
35	1	FRONT FUSE BOX BOTTEM COVER		CHECK
36	1	FRONT FUSE BOX RELAY BLOCK		CHECK
37	1	FRONT AIR INTAKE MANIFOLD		CHECK
38	1	FRONT INTAKE CHANNEL		CHECK
39	1	FRONT FILTER INTAKE HOSE		CHECK
40	1	FRONT AIR FILTER ASSEMBLY		\$ 340.00
41	1	FRONT BRAKE BOOSTER		\$ 660.00
42	1	FRONT BRAKE MASTER CYLINDER		\$ 420.00
43	1	FRONT BRAKE FLUID TANK		W/CYLINDER
44	1	FRONT A PILLAR LH		\$ 230.00
45	1	FRONT A PILLAR INNER LH		\$ 265.00
46	1	FRONT A PILLAR TRIM LH		\$ 120.00

47	1	FRONT A PILLAR LOWER FRAME REINFORCEMENT LH	CHECK	
48	1	FRONT A PILLAR SIDE PANEL LH	\$	160.00
49	1	FRONT A PILLAR LOWER REINFORCEMENT LH	CHECK	
50	1	SIDE MEMBER LH	REPAIR	
51	1	SIDE MEMBER RH	REPAIR	
52	1	FRONT DOOR LH	\$	600.00
53	1	FRONT DOOR UPPER HINGE LH	\$	45.00
54	1	FRONT DOOR LOWER HINGE LH	\$	45.00
55	1	FRONT DOOR INNER TRIM LH	\$	360.00
56	1	FRONT DOOR LOCK LH	\$	230.00
57	1	FRONT DOOR STRIKER LH	\$	75.00
58	1	FRONT DOOR GLASS LH	\$	195.00
59	1	FRONT DOOR SIDE MIRROR LH	\$	420.00
60	1	FRONT STEP PANEL LH	\$	60.00
61	1	FRONT STEP PANEL INNER LH	\$	110.00
62	1	FRONT STEP PANEL TRIM LH	CHECK	
63	1	FRONT WHEEL RIM LH	\$	255.00
64	1	FRONT SHOCKABSORBER LH	CHECK	
65	1	FRONT KNUCKLE ARM LH	\$	255.00
66	1	FRONT TIE ROD LH	\$	90.00
67	1	FRONT TIE ROD END LH	\$	70.00
68	1	FRONT WHEEL HUB LH	\$	180.00
69	1	FRONT WHEEL HUB BEARING LH	\$	120.00
70	1	FRONT DASHBOARD	\$	580.00
71	1	FRONT DASHBOARD CENTER COVER	CHECK	
72	1	FRONT DASHBOARD GLOVEBOX	\$	160.00
73	1	FRONT DASHBOARD UPPER TRIM	CHECK	
74	1	FRONT DASHBOARD UPPER COVER	CHECK	
75	1	FRONT DASHBOARD LOWER TRIM	CHECK	
76	1	FRONT DASHBOARD LOWER SHIFT COVER	CHECK	
77	1	FRONT DASHBOARD STEERING GEAR COVER	CHECK	
78	1	FRONT DASHBOARD LOWER PANEL COVER	CHECK	
79	1	FRONT DASHBOARD SUPPORT	\$	460.00
80	1	FRONT AIRCON FAN HOUSING ASSEMBLY	CHECK	
81	1	FRONT AIRCON COOLING COIL ASSEMBLY	\$	2,520.00
82	1	DRIVER AIRBAG	\$	1,020.00
83	1	AIRBAG CLOCK SPRING	CHECK	
84	1	FRONT AIRBAG SENSOR	CHECK	
85	1	FRONT AIRBAG CONTROL MODULE	CHECK	
			SUB TOTAL	\$ 14,000.00
			MARGIN 10%	\$ 1,400.00
			TOTAL AMOUNT	\$ 15,400.00

Our Ref: **GBL2394M**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT BUMPER CLIPS		\$ 50.00
2	1	FRONT BRAKE FLUID		\$ 30.00

3	1	FRONT AIRCON GAS		\$	60.00
4	1	FRONT RADIATOR COOLANT		\$	30.00
5	1	FRONT WHEEL TYRE		\$	350.00
			SUB TOTAL	\$	520.00
			TOTAL PARTS COST	\$	15,920.00

Our Ref: **GBL2394M**

S/NO	DESCRIPTION	EST. BY WORKSHOP
	<b><u>LABOUR &amp; PAINTWORK</u></b>	
1	REMOVE, REFIT AND REPAIR AFFECTED DAMAGED PARTS	\$ 2,800.00
2	TO REMOVE & REFIT AIR CON CONDENSER, PIPES & VACUUM, INCLUDING	\$ 150.00
3	RECHARGING GAS	\$ 20.00
4	SIMPLE WIRING	\$ 300.00
5	TO REPAIR & WELD FRONT CHASSIS RH & LH	\$ 20.00
6	SIMPLE WIRING	\$ 20.00
7	ANTI RUST COATING	\$ 1,600.00
8	PAINT MATERIALS PER PANEL	\$ 20.00
	SUNDRIES	
	TOTAL BEFORE GST	\$ 20,850.00
	LESS EXCESS	\$ -
	TOTAL BEFORE GST	\$ 20,850.00
	7% GST	\$ 1,459.50
	TOTAL REPAIR COST	<b>\$ 22,309.50</b>

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

**\*\*This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.**

**\*\*\*On a separate note, please let us have your authorize repair confirmation and/or approval for the above OD case in your next reply.**

Yours Faithfully,

Jason Heng  
Claims Director