

(08/11/13)

Wef

ASS. REC. BY:

REF:

C8/AB 2200 5063/Rty3

2856

ASSIGNMENT

From:

Date:

Estimated Cost:

OB / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GDL 2394M

at Workshop m/s

Auto INSURE

of

6, MARSLING LN

Insured:

AIS

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

88K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GDL 2394M

Yr Regn:

2021 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HILUX DX 2.8A

c.c

2754

Colour

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GDL 2011056420

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/80R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/05/22

D.O.I.

30/05/22

Survey held at

Autoinsure

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 48K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) : S + RS : SI

☐

: Interview (\$

) : Photos

☐

: Tech. Invs (\$

) : Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **GBL2394M (MARVYN)**

Date: **25-May-22**

BY EMAIL ONLY
(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Allianz Insurance Singapore Pte. Ltd

79 Robinson Road
#09-01,
Singapore 068897

Assessed Vehicle No : GBL2394M
Car Make and Model : TOYOTA HIACE DX 2.8 AUTO
Date of Accident : 15-May-22
Date of Assessment : 25-May-22

We have carried out a physical assessment of GBL2394M at our workshop Auto Insure Pte Ltd sustained damages to the FRONT portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P
Adjusted Amount : \$ 22,309.50
Est. Repair Days : 18



Pursuant to your instruction, we have **AUTHORIZED** to repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: GBL2394M

| S/NO | QTY | DESCRIPTIONS | ASSESSED CONDITION | EST. BY WORKSHOP |
|---------------------------------------|-----|--|-----------------------|------------------|
| PARTS REPLACEMENT - LIST ITEMS | | | | |
| 1 | 1 | FRONT WINDSCREEN <i>bn</i> | | \$ 720.00 |
| 2 | 1 | FRONT WINDSCREEN MOULDING <i>an</i> | | \$ 55.00 |
| 3 | 1 | FRONT WINDSCREEN WIPER ARM RH <i>bt</i> | | \$ 60.00 |
| 4 | 1 | FRONT WINDSCREEN WIPER ARM LH <i>bt</i> | | \$ 60.00 |
| 5 | 1 | FRONT WINDSCREEN WIPER MOTOR | | \$ 420.00 |
| 6 | 1 | FRONT WINDSCREEN WIPER LINKAGE | | \$ 160.00 |
| 7 | 1 | FRONT WIPER COVER <i>bn</i> | | \$ 20.00 |
| 8 | 1 | FRONT WIPER TANK <i>de</i> | | \$ 100.00 |
| 9 | 1 | FRONT COWL PANEL | | CHECK |
| 10 | 1 | BONNET <i>bt</i> | | \$ 265.00 |
| 11 | 1 | BONNET HINGE RH <i>X</i> | | \$ 45.00 |
| 12 | 1 | BONNET HINGE LH <i>bt</i> | | \$ 45.00 |
| 13 | 1 | BONNET SUPPORT <i>X</i> | | \$ 220.00 |
| 14 | 1 | FRONT FENDER RH <i>X</i> | | \$ 100.00 |
| 15 | 1 | FRONT FENDER BRACKET RH <i>T</i> | | CHECK |
| 16 | 1 | FRONT FENDER LH <i>bn</i> | | \$ 100.00 |
| 17 | 1 | FRONT FENDER BRACKET LH <i>?</i> | | CHECK |
| 18 | 1 | FRONT FENDER SIDE MIRROR ASSEMBLY LH <i>bn</i> | | \$ 145.00 |
| 19 | 1 | FRONT UPPER GRILLE <i>bn</i> | | \$ 160.00 |
| 20 | 1 | FRONT LOWER GRILLE <i>bn</i> | | \$ 280.00 |
| 21 | 1 | FRONT GRILLE BASE <i>bn</i> | | \$ 265.00 |
| 22 | 1 | FRONT BUMPER <i>de</i> | | \$ 205.00 |
| 23 | 1 | FRONT BUMPER LOWER GRILLE <i>de</i> | | \$ 85.00 |
| 24 | 1 | FRONT BUMPER LOWER COVER RH <i>X</i> | | \$ 45.00 |
| 25 | 1 | FRONT BUMPER LOWER COVER LH <i>X</i> | | \$ 45.00 |
| 26 | 1 | FRONT BUMPER REINFORCEMENT <i>X</i> | | \$ 135.00 |
| 27 | 1 | FRONT PANEL CROSSMEMBER <i>?</i> | | CHECK |
| 28 | 1 | FRONT LOCK CARRIER PANEL <i>?</i> | | CHECK |
| 29 | 1 | FRONT SUPPORT PANEL <i>bt</i> | | \$ 220.00 |
| 30 | 1 | FRONT LOWER CROSSMEMBER <i>?</i> | | CHECK |
| 31 | 1 | FRONT SUPPORT PANEL STRUT <i>?</i> | | CHECK |
| 32 | 1 | FRONT ENGINE FIREWALL <i>?</i> | | CHECK |
| 33 | 1 | FRONT ENGINE FIREWALL INSULATION <i>?</i> | | CHECK |
| 34 | 1 | FRONT FUSE BOX TOP COVER <i>?</i> | | CHECK |
| 35 | 1 | FRONT FUSE BOX BOTTEM COVER <i>?</i> | | CHECK |
| 36 | 1 | FRONT FUSE BOX RELAY BLOCK <i>?</i> | | CHECK |
| 37 | 1 | FRONT AIR INTAKE MANIFOLD <i>?</i> | | CHECK |
| 38 | 1 | FRONT INTAKE CHANNEL <i>?</i> | | CHECK |
| 39 | 1 | FRONT FILTER INTAKE HOSE <i>?</i> | | CHECK |
| 40 | 1 | FRONT AIR FILTER ASSEMBLY <i>?</i> | | \$ 340.00 |
| 41 | 1 | FRONT BRAKE BOOSTER <i>X</i> | | \$ 660.00 |
| 42 | 1 | FRONT BRAKE MASTER CYLINDER <i>X</i> | | \$ 420.00 |
| 43 | 1 | FRONT BRAKE FLUID TANK <i>X</i> | | W/CYLINDER |
| 44 | 1 | FRONT A PILLAR LH <i>bt</i> | | \$ 230.00 |
| 45 | 1 | FRONT A PILLAR INNER LH <i>bt</i> | | \$ 265.00 |
| 46 | 1 | FRONT A PILLAR TRIM LH <i>?</i> | | \$ 120.00 |

| | | | | |
|----|---|--|--------------|--------------|
| 47 | 1 | FRONT A PILLAR LOWER FRAME ? | | |
| 48 | 1 | REINFORCEMENT LH ? | | CHECK |
| 49 | 1 | FRONT A PILLAR SIDE PANEL LH ? | \$ | 160.00 |
| 50 | 1 | FRONT A PILLAR LOWER REINFORCEMENT LH ? | | CHECK |
| 51 | 1 | SIDE MEMBER LH <i>repair</i> | | REPAIR |
| 52 | 1 | SIDE MEMBER RH <i>X</i> | | REPAIR |
| 53 | 1 | FRONT DOOR LH <i>br</i> | \$ | 600.00 |
| 54 | 1 | FRONT DOOR UPPER HINGE LH <i>bt</i> | \$ | 45.00 |
| 55 | 1 | FRONT DOOR LOWER HINGE LH <i>bt</i> | \$ | 45.00 |
| 56 | 1 | FRONT DOOR INNER TRIM LH <i>ch</i> | \$ | 360.00 |
| 57 | 1 | FRONT DOOR LOCK LH <i>at</i> | \$ | 230.00 |
| 58 | 1 | FRONT DOOR STRIKER LH <i>X</i> | \$ | 75.00 |
| 59 | 1 | FRONT DOOR GLASS LH <i>br</i> | \$ | 195.00 |
| 60 | 1 | FRONT DOOR SIDE MIRROR LH <i>sur</i> | \$ | 420.00 |
| 61 | 1 | FRONT STEP PANEL LH <i>at</i> | \$ | 60.00 |
| 62 | 1 | FRONT STEP PANEL INNER LH ? | \$ | 110.00 |
| 63 | 1 | FRONT STEP PANEL TRIM LH ? | | CHECK |
| 64 | 1 | FRONT WHEEL RIM LH <i>X</i> | \$ | 255.00 |
| 65 | 1 | FRONT SHOCKABSORBER LH ? | | CHECK |
| 66 | 1 | FRONT KNUCKLE ARM LH ? | \$ | 255.00 |
| 67 | 1 | FRONT TIE ROD LH ? | \$ | 90.00 |
| 68 | 1 | FRONT TIE ROD END LH ? | \$ | 70.00 |
| 69 | 1 | FRONT WHEEL HUB LH ? | \$ | 180.00 |
| 70 | 1 | FRONT WHEEL HUB BEARING LH ? | \$ | 120.00 |
| 71 | 1 | FRONT DASHBOARD <i>de</i> | \$ | 580.00 |
| 72 | 1 | FRONT DASHBOARD CENTER COVER ? | | CHECK |
| 73 | 1 | FRONT DASHBOARD GLOVEBOX <i>ma X</i> | \$ | 160.00 |
| 74 | 1 | FRONT DASHBOARD UPPER TRIM ? | | CHECK |
| 75 | 1 | FRONT DASHBOARD UPPER COVER ? | | CHECK |
| 76 | 1 | FRONT DASHBOARD LOWER TRIM ? | | CHECK |
| 77 | 1 | FRONT DASHBOARD LOWER SHIFT COVER ? | | CHECK |
| 78 | 1 | FRONT DASHBOARD STEERING GEAR COVER ? | | CHECK |
| 79 | 1 | FRONT DASHBOARD LOWER PANEL COVER ? | | CHECK |
| 80 | 1 | FRONT DASHBOARD SUPPORT ? | \$ | 460.00 |
| 81 | 1 | FRONT AIRCON FAN HOUSING ASSEMBLY ? | | CHECK |
| 82 | 1 | FRONT AIRCON COOLING COIL ASSEMBLY <i>co</i> | \$ | 2,520.00 |
| 83 | 1 | DRIVER AIRBAG <i>dr</i> | \$ | 1,020.00 |
| 84 | 1 | AIRBAG CLOCK SPRING ? | | CHECK |
| 85 | 1 | FRONT AIRBAG SENSOR ? | | CHECK |
| | | FRONT AIRBAG CONTROL MODULE ? | | CHECK |
| | | | SUB TOTAL | \$ 14,000.00 |
| | | | MARGIN 10% | \$ 1,400.00 |
| | | | TOTAL AMOUNT | \$ 15,400.00 |

Our Ref: **GBL2394M**

| S/NO | QTY | SPECIAL NETT ITEMS | ASSESSED CONDITION | EST. BY WORKSHOP |
|------|-----|----------------------------|--------------------|--------------------|
| 1 | 1 | FRONT BUMPER CLIPS | | \$ 50.00 <i>30</i> |
| 2 | 1 | FRONT BRAKE FLUID <i>X</i> | | \$ 30.00 <i>X</i> |

Our Ref: GBL2394M

| S/NO | DESCRIPTION | EST. BY WORKSHOP |
|-------------------------------|--|-----------------------------|
| LABOUR & PAINTWORK | | |
| 1 | REMOVE, REFIT AND REPAIR AFFECTED DAMAGED PARTS | \$ 1200 2,800.00 |
| 2 | TO REMOVE & REFIT AIR CON CONDENSER, PIPES & VACUUM, INCLUDING | \$ 120 150.00 |
| 3 | RECHARGING GAS | \$ 20.00 |
| 4 | SIMPLE WIRING | \$ 200 300.00 |
| 5 | TO REPAIR & WELD FRONT CHASSIS RH & LH | \$ 20.00 |
| 6 | SIMPLE WIRING | \$ 20.00 |
| 7 | ANTI RUST COATING | \$ 20.00 |
| 8 | PAINT MATERIALS PER PANEL | \$ 800 1,600.00 |
| | SUNDRIES | \$ 20.00 |
| TOTAL BEFORE GST | | \$ 20,850.00 |
| LESS EXCESS | | \$ - |
| TOTAL BEFORE GST | | \$ 20,850.00 |
| 7% GST | | \$ 1,459.50 |
| TOTAL REPAIR COST | | \$ 22,309.50 |

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

**This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

***On a separate note, please let us have your authorize repair confirmation and/or approval for the above OD case in your next reply.

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rene
Hp 90010068

12 days

P/P

30/05/22 @1410

EXCESS: TBA

Rene

Resay before print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|--------------------------------|
| Date of Submission | 17/05/2022 18:10 (SGT) |
| Date of Accident | 14/05/2022 22:45 (SGT) |
| Exact Location of Accident | Jurong Town Hall Rd, Singapore |
| Additional Location Information | TRAFFIC JUNCTION |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------|
| Vehicle Registration Number | GBL2394M |
|-----------------------------|----------|

INSURED/POLICYHOLDER

| | |
|--------------------------|-------------------------------|
| Is company? | Yes |
| Name Of Registered Owner | SKYLINK VEHLCE RENTAL PTE LTD |
| Company Reg No | 2XXXXX755G |
| Email Address | YVETTE@SKYLINK.COM.SG |
| Mobile Phone No | (Phone) +65-62665858 |
| Alternative Phone No | (Office) +65-62665858 |

VEHICLE PARTICULARS

| | |
|--|-------------------|
| Manufacturer | Toyota |
| Model | Hiace |
| Variant | HIACE DX 2.8 AUTO |
| Exact purpose for which vehicle was being used at time of accident | Employment |
| Are you claiming under your own insurance policy for repair to your vehicle? | Yes |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 2754 |

INSURANCE COMPANY

| | |
|---------------------------|---------------------------------------|
| Name of Insurance Company | Allianz Insurance Singapore Pte. Ltd. |
| Type of Coverage | Comprehensive |
| Fleet Policy | No |
| Policy Number | SPMF1000000537 |
| Cover Note Number | - |

DRIVER

| | |
|----------------|-------------------|
| Name of Driver | PAVADAI SIVAKUMAR |
| Work Permit No | GXXXX546M |

Date Of Birth 19/06/1972
 Occupation Outdoor
 Date Of Driving Pass 03/02/2009
 Driving experience 13 YEARS AND 3 MONTHS
 Gender Male
 Mobile Number (Phone) +65-84172029
 Alt. Phone Number -
 Email Address YVETTE@SKYLINK.COM.SG
 Address 749 JURONG WEST ST 73 #02-147
 Address complement -
 Postcode 640749
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Hirer
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 3
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name PASSENGER
 Gender Male

PASSENGER 2

Name PASSENGER
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN
 Vehicle Manufacturer -

Allianz Insurance Singapore Pte. Ltd.

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION) (REPUBLIC OF SINGAPORE)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 (REPUBLIC OF SINGAPORE)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1988
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Certificate Number : SPMF1000000537
 Date of Issue : 26 April 2022
 Coverage : COMPREHENSIVE - AUTHORISED WORKSHOP
 Policyholder : SKYLINK VEHICLE RENTAL PTE. LTD.
 Finance Company : -
 Period of Insurance : 23 April 2022 To 22 April 2023 (both dates inclusive)
 Registration Number : GBL2394M
 Chassis Number of Vehicle : GDH2011056420

Persons or Classes of Persons Entitled to Drive*:

- (a) The Policyholder.
- (b) Any other person who is driving on the Policyholder's order or with his/her permission or to whom the vehicle is hired.
- * Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulations in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act (Cap 276) (Republic of Singapore) and such registration has not been cancelled at the time of accident loss or damage.

Limitation as to Use*:


- (a) Use for carriage of passengers or goods in connection with the Policyholder's business.
- (b) Use for social, domestic and pleasure purposes and business purposes of any person to whom the vehicle is hired.
- * Limitation rendered inoperative by Section 8 of Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Policy does not cover:

- (a) Use for racing, pace-making, reliability trials or speed-testing.
- (b) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.
- (c) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

26 April 2022
 Issue Date


 Nicholas Raisul
 Chief Executive Officer
 Allianz Insurance Singapore Pte. Ltd.

Intermediary Code : 0000161 AON SINGAPORE PTE LTD

Allianz Insurance Singapore Pte. Ltd. | UEN 201903913C
 79 Robinson Road #09-01 | Singapore 068897 | Tel: +65 6714 3369 | Website: www.allianz.sg

SKETCH PLAN



A = GBL 2394m

B = unknown

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/5/22 at 2245 hrs, I was travelling along Juyong Town Hall Rd. Near the traffic junction vehicle B jam brake. I couldn't brake in time and collided onto vehicle B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Police Officer's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

755G

Vehicle Details

Vehicle No.:

GBL2394M

Vehicle to be Exported:

No

Intended Deregistration Date:

25 May 2022

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE DX 2.8 AUTO

Primary Colour:

Silver

Manufacturing Year:

2021

Engine No.:

1GD8693378

Chassis No.:

GDH2011056420

Maximum Power Output:

-

Open Market Value:

\$33,153.00

Original Registration Date:

31 Mar 2021

First Registration Date:

31 Mar 2021

Transfer Count:

1

Actual ARF Paid:

\$1,658.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

30 Mar 2031

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$45,001.00

COE Rebate Amount:

\$39,811.00

Total Rebate Amount:

\$39,811.00

The information contained herein is correct as at 25 May 2022

OK

Toyota Hiace 2.8A DX

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price **\$88,800** Lifespan 02-Mar-2041

Depreciation  \$10,140 /yr
[View models with similar depre](#) Reg Date 03-Mar-2021
(8yrs 9mths COE left)

Mileage 25,000 km (20.1k /yr) Manufactured  2020

Road Tax  N.A. Transmission Auto

Dereg Value  \$30,842 as of today ([change](#)) Fuel Type Diesel

COE  \$35,201 OMV  \$34,656

Engine Cap 2,754 cc ARF  \$1,733

Curb Weight 1,800 kg No. of Owners 2

Type of Vehicle [Van](#)