



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

7669

Affiliated to Federation Internationale Des Experts En Automobile

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 SINGAPORE 068897

Ref: CS/AIS22005063/Rty3

Date: 30/05/2022

Code: AIS

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBL 2394M
Policy No.		Coverage (\$)	0.00
Claim No.	SVRAISCL2022-00010FR	Excess (\$)	0.00
Assign From	GERMAINE LEONG	Assign Date	30/05/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	14/05/2022	Inspection Date	30/05/2022
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

(08/11/13) wef
ASS. REC. BY: How

REF:

C8/AB22005063/Rty3

78556

ASSIGNMENT

From:

Date:

Estimated Cost:

OP/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: GBL 2394M

at Workshop m/s AUTO INSURE

of 6 MARSILING LN

Insured: AB

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

88K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBL 2394M

Yr Regn: 2021 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HILUX DX 2.8A

c.c 2754

Colour

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

404 2011056420

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

195/80R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/05/22

D.O.I.

30/05/22

Survey held at

AUTOINSURE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 48K

MV \$ 88K

Date/Time, File Pass to?

☐

: Prell. Report

1) Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **GBL2394M (MARVYN)**

Date: **25-May-22**

BY EMAIL ONLY
(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Allianz Insurance Singapore Pte. Ltd

79 Robinson Road
#09-01,
Singapore 068897

Assessed Vehicle No : **GBL2394M**
Car Make and Model : **TOYOTA HIACE DX 2.8 AUTO**
Date of Accident : **15-May-22**
Date of Assessment : **25-May-22**

We have carried out a physical assessment of GBL2394M at our workshop Auto Insure Pte Ltd sustained damages to the FRONT portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **P/P**
Adjusted Amount : **\$ 22,309.50**
Est. Repair Days : **18**



Pursuant to your instruction, we have **AUTHORIZED** to repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by
AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: GBL2394M

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	FRONT WINDSCREEN <i>bn</i>	\$	✓ 720.00
2	1	FRONT WINDSCREEN MOULDING <i>ae</i>	\$	✓ 55.00
3	1	FRONT WINDSCREEN WIPER ARM RH <i>bt</i>	\$	✓ 60.00
4	1	FRONT WINDSCREEN WIPER ARM LH <i>bt</i>	\$	✓ 60.00
5	1	FRONT WINDSCREEN WIPER MOTOR	\$	420.00
6	1	FRONT WINDSCREEN WIPER LINKAGE	\$	160.00
7	1	FRONT WIPER COVER <i>de</i>	\$	20.00
8	1	FRONT WIPER TANK <i>de</i>	\$	✓ 100.00
9	1	FRONT COWL PANEL		CHECK
10	1	BONNET <i>bt</i>	\$	✓ 265.00
11	1	BONNET HINGE RH <i>X</i>	\$	45.00
12	1	BONNET HINGE LH <i>bt</i>	\$	✓ 45.00
13	1	BONNET SUPPORT <i>X</i>	\$	220.00
14	1	FRONT FENDER RH <i>X</i>	\$	100.00
15	1	FRONT FENDER BRACKET RH <i>T</i>		CHECK
16	1	FRONT FENDER LH <i>huc</i>	\$	✓ 100.00
17	1	FRONT FENDER BRACKET LH <i>?</i>		CHECK
18	1	FRONT FENDER SIDE MIRROR ASSEMBLY LH <i>hru</i>	\$	✓ 145.00
19	1	FRONT UPPER GRILLE <i>con</i>	\$	✓ 160.00
20	1	FRONT LOWER GRILLE <i>con</i>	\$	✓ 280.00
21	1	FRONT GRILLE BASE <i>con</i>	\$	✓ 265.00
22	1	FRONT BUMPER <i>de</i>	\$	✓ 205.00
23	1	FRONT BUMPER LOWER GRILLE <i>de</i>	\$	✓ 85.00
24	1	FRONT BUMPER LOWER COVER RH <i>X</i>	\$	45.00
25	1	FRONT BUMPER LOWER COVER LH <i>X</i>	\$	45.00
26	1	FRONT BUMPER REINFORCEMENT <i>X</i>	\$	135.00
27	1	FRONT PANEL CROSSMEMBER <i>?</i>		CHECK
28	1	FRONT LOCK CARRIER PANEL <i>?</i>		CHECK
29	1	FRONT SUPPORT PANEL <i>bt</i>	\$	✓ 220.00
30	1	FRONT LOWER CROSSMEMBER <i>?</i>		CHECK
31	1	FRONT SUPPORT PANEL STRUT <i>?</i>		CHECK
32	1	FRONT ENGINE FIREWALL <i>?</i>		CHECK
33	1	FRONT ENGINE FIREWALL INSULATION <i>?</i>		CHECK
34	1	FRONT FUSE BOX TOP COVER <i>?</i>		CHECK
35	1	FRONT FUSE BOX BOTTEM COVER <i>?</i>		CHECK
36	1	FRONT FUSE BOX RELAY BLOCK <i>?</i>		CHECK
37	1	FRONT AIR INTAKE MANIFOLD <i>?</i>		CHECK
38	1	FRONT INTAKE CHANNEL <i>?</i>		CHECK
39	1	FRONT FILTER INTAKE HOSE <i>?</i>		CHECK
40	1	FRONT AIR FILTER ASSEMBLY <i>?</i>	\$	340.00
41	1	FRONT BRAKE BOOSTER <i>X</i>	\$	660.00
42	1	FRONT BRAKE MASTER CYLINDER <i>X</i>	\$	420.00
43	1	FRONT BRAKE FLUID TANK <i>X</i>		W/CYLINDER
44	1	FRONT A PILLAR LH <i>bt</i>	\$	✓ 230.00
45	1	FRONT A PILLAR INNER LH <i>bt</i>	\$	✓ 265.00
46	1	FRONT A PILLAR TRIM LH <i>?</i>	\$	120.00

47	1	FRONT A PILLAR LOWER FRAME ?			
48	1	REINFORCEMENT LH ?			
49	1	FRONT A PILLAR SIDE PANEL LH ?			
50	1	FRONT A PILLAR LOWER REINFORCEMENT LH ?			
51	1	SIDE MEMBER LH <i>repair</i>			
52	1	SIDE MEMBER RH <i>X</i>			
53	1	FRONT DOOR LH <i>bur</i>			
54	1	FRONT DOOR UPPER HINGE LH <i>bt</i>			
55	1	FRONT DOOR LOWER HINGE LH <i>bt</i>			
56	1	FRONT DOOR INNER TRIM LH <i>ch</i>			
57	1	FRONT DOOR LOCK LH <i>at</i>			
58	1	FRONT DOOR STRIKER LH <i>X</i>			
59	1	FRONT DOOR GLASS LH <i>br</i>			
60	1	FRONT DOOR SIDE MIRROR LH <i>sur</i>			
61	1	FRONT STEP PANEL LH <i>at</i>			
62	1	FRONT STEP PANEL INNER LH ?			
63	1	FRONT STEP PANEL TRIM LH ?			
64	1	FRONT WHEEL RIM LH <i>X</i>			
65	1	FRONT SHOCKABSORBER LH ?			
66	1	FRONT KNUCKLE ARM LH ?			
67	1	FRONT TIE ROD LH ?			
68	1	FRONT TIE ROD END LH ?			
69	1	FRONT WHEEL HUB LH ?			
70	1	FRONT WHEEL HUB BEARING LH ?			
71	1	FRONT DASHBOARD <i>de</i>			
72	1	FRONT DASHBOARD CENTER COVER ? <i>X</i>			
73	1	FRONT DASHBOARD GLOVEBOX <i>not</i>			
74	1	FRONT DASHBOARD UPPER TRIM ?			
75	1	FRONT DASHBOARD UPPER COVER ?			
76	1	FRONT DASHBOARD LOWER TRIM ?			
77	1	FRONT DASHBOARD LOWER SHIFT COVER ?			
78	1	FRONT DASHBOARD STEERING GEAR COVER ?			
79	1	FRONT DASHBOARD LOWER PANEL COVER ?			
80	1	FRONT DASHBOARD SUPPORT ?			
81	1	FRONT AIRCON FAN HOUSING ASSEMBLY ?			
82	1	FRONT AIRCON COOLING COIL ASSEMBLY <i>col</i>			
83	1	DRIVER AIRBAG <i>qrs</i>			
84	1	AIRBAG CLOCK SPRING ?			
85	1	FRONT AIRBAG SENSOR ?			
	1	FRONT AIRBAG CONTROL MODULE ?			
			SUB TOTAL	\$	14,000.00
			MARGIN 10%	\$	1,400.00
			TOTAL AMOUNT	\$	15,400.00

Our Ref: GBL2394M

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP	
1	1	FRONT BUMPER CLIPS		\$	50.00 <i>30</i>
2	1	FRONT BRAKE FLUID <i>X</i>		\$	30.00 <i>X</i>

3	1	FRONT AIRCON GAS nec		\$	60.00
4	1	FRONT RADIATOR COOLANT nec		\$	30.00
5	1	FRONT WHEEL TYRE 70%		\$	? 350.00
			SUB TOTAL	\$	520.00
			TOTAL PARTS COST	\$	15,920.00

Our Ref: GBL2394M

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	REMOVE, REFIT AND REPAIR AFFECTED DAMAGED PARTS	\$ 1200 2,800.00
2	TO REMOVE & REFIT AIR CON CONDENSER, PIPES & VACUUM, INCLUDING	\$ 120 150.00
3	RECHARGING GAS	\$ 20.00
4	SIMPLE WIRING	\$ 200 300.00
5	TO REPAIR & WELD FRONT CHASSIS RH & LH	\$ 20.00
6	SIMPLE WIRING	\$ 20.00
7	ANTI RUST COATING	\$ 1000 1,600.00
8	PAINT MATERIALS PER PANEL	\$ 20.00
	SUNDRIES	\$ 20.00
TOTAL BEFORE GST		\$ 20,850.00
LESS EXCESS		\$ -
TOTAL BEFORE GST		\$ 20,850.00
7% GST		\$ 1,459.50
TOTAL REPAIR COST		\$ 22,309.50

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

****This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.**

*****On a separate note, please let us have your authorize repair confirmation and/or approval for the above OD case in your next reply.**

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rene
Hp 90010068
12 days
P/P
30/05/22 @1410
EXCESS: TBA
Rene
Resy before
paint