

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0435/2022/JT  
DATE : 27-May-22  
WIP : 25721

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/5/2022.

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR HO WEI RUI, GILBERT  
ADDRESS : 501 DUNMAN ROAD  
#11-03  
SINGAPORE 439193  
TELEPHONE : HP +65 9669 8629  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1900244032-01  
VEHICLE NO : SKH 6911 J  
MODEL CODE : AUDI A3 SB 1.0 TFSI  
MODEL YEAR : 15/11/2019  
ENGINE NO : CHZ C33218  
CHASSIS NO : WAUZZZ8VXKA121470  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 26-May-22  
PLACE OF ACCIDENT : STADIUM WALK



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6911 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.	S/N \$	360.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	<i>2 x 250</i> <i>g 500</i>
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$	1,400.00 /	
4	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N \$	800.00	? (ph)
5	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY FOR BOTH FRONT DOOR.	S/N \$	560.00	<i>RH</i> <i>280</i>
6	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES.	S/N \$	2,800.00	? (ph)
<b>SUB-TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 6,620.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6911 J**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$	2,400.00	? (phn)
8	TO SETUP VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	? (phn)
9	TO REMOVE AND RENEW THROTTLE BODY AND OTHER ENGINE COMPONENTS.	S/N \$	980.00	? X
10	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00	✓
11	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	400.00	X
12	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$	200.00	150
<b>SUB-TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 6,860.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6911 ]**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORT AND LHS FRONT CHASSIS FRAME WITH COVER PLATE. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S 14,000.00 <i>6.5 x 500</i>	<i>3250</i>
14	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT FENDER TOP SUPPORTS, LHS FRONT CHASSIS FRAME WITH COVER PLATE, BOTH FRONT DOORS AND BOTH UP A-PILLARS.	S 8,500.00 <i>550 x 6</i>	<i>3300</i>
15	TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N S 480.00	<i>?</i>
16	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N S 280.00	<i>X</i>
17	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N S 384.00	<i>✓</i>
<b>TOTAL LABOUR CHARGES</b>		<b>S 37,124.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / BR	1	\$	2,146.00	
2	FRONT BUMPER FIXING PARTS - MC	1	\$	195.00	
3	FRONT BUMPER GUIDE SECTION- LH / RH / BT	2	\$	86.00	
4	FRONT BUMPER GRILLE - CENTER - BR	1	\$	179.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER - BR	1	\$	332.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH - BR	2	\$	636.00	
7	RADIATOR GRILLE - BR	1	\$	1,578.00	
8	RADIATOR GRILLE CLOSING ELEMENT - BR	1	\$	210.00	
9	AIR COND STICKER - MC	1	\$	9.00	
10	CAUTION STICKER - MC	1	\$	16.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH - BR	2	\$	420.00	
12	FRONT BUMPER FOAM FILLER PIECE - BR	1	\$	211.00	
13	FRONT BUMPER REINFORCEMENT BEAM COVER - BR	1	\$	136.00	
14	FRONT BUMPER REINFORCEMENT BEAM - OK	1	\$	847.00	
15	HORN - LH / RH - BR	2	\$	426.00	
16	FRONT FENDER - LH / RH - BT	2	\$	1,908.00	
17	FRONT FENDER ATTACHMENT PARTS X	1	\$	75.00	
18	FRONT FENDER BRACKET - LH / RH - BT	2	\$	112.00	
19	FRONT FENDER POP RIVET - MC	16	\$	61.00	
20	FRONT FENDER CLOSING ELEMENT - LH / RH - MC	2	\$	136.00	
<b>SUB TOTAL SPARE PARTS</b>			:	<b>\$ 9,719.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT FENDER BRACE - LH / RH ?	2	\$ 214.00	
22	FRONT FENDER BRACKET END - LH / RH - nec	(2)	\$ 62.00	
23	FRONT FENDER INSULATION - LH / RH ?	2	\$ 96.00	
24	FRONT FENDER CLOSING ELEMENT END - LH / RH ?	2	\$ 74.00	
25	FRONT WHEEL HOUSING LINER - LH / RH - CR4	(2)	\$ 366.00	
26	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - m	1	\$ 60.00	
27	BONNET - 00	1	\$ 3,370.00	
28	BONNET ATTACHMENT PARTS ?	1	\$ 172.00	
29	BONNET HINGE - LH / RH - BT	2	\$ 136.00	
30	BONNET SIDE COVER - LH / RH - CR4	21	\$ 92.00	
31	BONNET ABSOBER X	1	\$ 110.00	
32	BONNET EDGE PROTECTION - m	1	\$ 31.00	
33	BONNET CATCH HOOK - UPPER - BT	1	\$ 100.00	
34	BONNET STRIKER - LH / RH - BT	2	\$ 246.00	
35	BONNET CATCH HOOK - LOWER - BT	1	\$ 71.00	
36	BONNET LOCK MICRO-SWITCH - BT	2	\$ 455.00	
37	BONNET LOCK COVER m ?	2	\$ 8.00	
38	BONNET BOWDEN CABLE - CENTER ?	1	\$ 64.00	
39	BONNET RELEASE CABLE COVER ?	1	\$ 11.00	
40	BONNET LOCK CABLE ?	1	\$ 82.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 5,820.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	BONNET SOUND ABSORBER X	1	\$ 244.00	
42	BONNET PLENUM CHAMBER - CVT	1	\$ 199.00	
43	HEADLIGHT - LH / RH - BR	(2)	\$ 11,758.00	
44	HEADLIGHT POWER MODULE - LH / RH ?	2	\$ 1,700.00	
45	HEADLIGHT CONTROL UNIT ?	2	\$ 1,249.00	
46	LED HEAT SINK - LH / RH ?	2	\$ 1,636.00	
47	HEADLIGHT HOSE - LH / RH ?	2	\$ 92.00	
48	LIFT CYLINDER (LH) / RH - MR	2/1	\$ 312.00	
49	LIFT CYLINDER HOSE - TH	1	\$ 78.00	
50	LIFT CYLINDER PUMP - BR	1	\$ 171.00	
51	WINDSCREEN WASHER SYSTEM PUMP X	1	\$ 137.00	
52	WASH WATER RESERVOIR - CR4	1	\$ 225.00	
53	WINDSCREEN STRAINER X	1	\$ 24.00	
54	WINDSCREEN STRAINER END CAP X	1	\$ 24.00	
55	WINDSCREEN SPRAY NOZZLE HEATED - LH / RH ?	2	\$ 234.00	
56	LOCK CARRIER - BR	1	\$ 806.00	
57	A/C CONDENSER - BR	1	\$ 569.00	
58	REFRIGERANT LINE ?	1	\$ 621.00	
59	REFRIGERANT LINE ?	1	\$ 499.00	
60	REFRIGERANT LINE ?	1	\$ 569.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 21,147.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	REFRIGERANT LINE BRACKET ?	1	\$ 29.00	
62	OUTSIDE TEMPERATURE SENSOR BRACKET - nec	1	\$ 21.00	
63	EXTERNAL TEMPERATURE SENSOR ?	1	\$ 64.00	
64	ADDITIONAL RADIATOR - DD (photo)	1	\$ 959.00	
65	RADIATOR BRACKET - UPPER - BR	2	\$ 90.00	
66	RADIATOR BUSH - LOWER - nec	2	\$ 22.00	
67	RADIATOR - DD (photo)	1	\$ 1,061.00	
68	RADIATOR FAN RING - BR (photo)	1	\$ 1,488.00	
69	RADIATOR AIR GUIDE - LH / RH ?	2	\$ 56.00	
70	RADIATOR SEAL - RH OUTER X	1	\$ 9.00	
71	RADIATOR AIR GUIDE - UPPER CENTER ?	1	\$ 14.00	
72	RADIATOR COOLANT - nec	6	\$ 282.00	
73	QUICK RELEASE COUPLING COOLANT HOSE - FRONT ?	1	\$ 251.00	
74	QUICK RELEASE COUPLING COOLANT HOSE - UPPER ?	1	\$ 125.00	
75	COOLANT PIPE - UPPER ?	1	\$ 65.00	
76	COOLANT PIPE - LOWER ?	1	\$ 34.00	
77	QUICK RELEASE COUPLING COOLANT HOSE - LOWER ?	1	\$ 60.00	
78	QUICK RELEASE COOLANT HOSE ?	1	\$ 159.00	
79	INTAKE AIR DUCT COVER ?	1	\$ 30.00	
80	INTAKE AIR GUIDE - LOWER ? - BR	1	\$ 59.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 4,878.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
81	INTAKE AIR GUIDE - UPPER ?	1	\$	21.00	
82	WATER DRAINAGE HOSE ?	1	\$	37.00	
83	INTAKE AIR GUIDE - LOWER ?	1	\$	69.00	
84	AIR FILTER BOX ?	1	\$	310.00	
85	INTAKE MANIFOLD - UPPER ?	1	\$	156.00	
86	INTAKE MANIFOLD - LOWER ?	1	\$	786.00	
87	THROTTLE BODY ?	1	\$	796.00	
88	CHARGE AIR COOLER ?	1	\$	864.00	
89	TOOTHED BELT GUARD - UPPER / LOWER ?	2	\$	160.00	
90	TOOTHED BELT GUARD ?	1	\$	202.00	
91	POLY V-BELT ?	1	\$	52.00	
92	BATTERY CONSOLE ?	1	\$	203.00	
93	BATTERY HEAT INSULATION ?	1	\$	96.00	
94	BATTERY FILLED CHARGED ?	1	\$	584.00	
95	BATTERY PROTECTION COVER ?	1	\$	145.00	
96	BATTERY MONITORING CONTROL UNIT ?	1	\$	568.00	
97	FRONT FENDER TOP SUPPORT - LH / RH ?	2	\$	164.00	
98	FRONT CHASSIS FRAME COVER PLATE - LH ?	1	\$	107.00	
99	SIDE MEMBER - LH ?	1	\$	742.00	
100	GEARBOX MOUNTING BRACKET - LH ?	1	\$	123.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 6,185.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
101	NOISE INSULATION ?	1	\$ 376.00	
102	BASE ENGINE ?	1	\$ 18,936.00	
103	SUSPENSION SUBFRAME ASSEMBLY CARRIER ?	1	\$ 1,105.00	
104	BONDED RUBBER BUSHES ?	1	\$ 116.00	
105	GEARBOX MOUNTING - LH ?	1	\$ 286.00	
106	ENGINE MOUNTING - RH ?	1	\$ 277.00	
107	ENGINE MOUNTING CONSOLE - LH ?	1	\$ 209.00	
108	ENGINE SUPPORT ?	1	\$ 243.00	
109	ENGINE SUPPORT - LH / RH OUTER ?	2	\$ 50.00	
110	PENDULUM SUPPORT ?	1	\$ 100.00	
111	FRONT WINDSCREEN COLOUR STRIP - BR	1	\$ 1,206.00	
112	RAIN SENSOR GEL FOIL - ne	1	\$ 130.00	
113	SPRING CLIP x	1	\$ 23.00	
114	PRIMER - ne	1	\$ 22.00	
115	WINDSCREEN WATER DEFLECTOR STRIP (LH) RH - (M) x 1	2	\$ 150.00	
116	AERO WIPER ARM - LH / RH x	2	\$ 230.00	
117	AERODYNAMIC WIPER BLADE x	1	\$ 101.00	
118	AERODYNAMIC WIPER BLADE CAP x	2	\$ 20.00	
119	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH x	2	\$ 604.00	
120	ROOF CHROME MOLDING - LH / RH x	2	\$ 1,330.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 25,514.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
121	GEARBOX ?	1	\$	18,564.00
122	TRANSMISSION FLUID ?	5	\$	353.00
123	ELECTRIC SYSTEM HOUSING ?	1	\$	93.00
124	FUSE BOX COVER ?	1	\$	54.00
125	ENGINE COMPARTMENT ?	1	\$	27.00
126	E BOX ?	1	\$	394.00
127	FRONT NO PLATE / MIS	S/N	\$	60.00
128	FRONT WINDSCREEN SEALANT / nc	S/N	\$	200.00
129	ARYLIC SEALANT ?	S/N	\$	180.00
130	CAVITY WAX ?	S/N	\$	140.00
131	METAL PILLER POWDER ?	S/N	\$	280.00
132	STONE CHIP ?	S/N	\$	180.00
133	SUNDRIES ?		\$	800.00
<b>TOTAL SPARE PARTS</b>		:	\$	<b>94,588.00</b>
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>37,124.00</b>
<b>GRAND TOTAL</b>		:	\$	<b>131,712.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Steve (LKK)  
30/5/22, 3.00pm

00- M L  
Exm- ?  
PIP  
M BL y  
12 LJS

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT