



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0435/2022/JT
DATE : 27-May-22
WIP : 25721

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/5/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve
24 days - Johnny Boo
14-Nov-22

OWNER'S NAME : MR HO WEI RUI, GILBERT
ADDRESS : 501 DUNMAN ROAD
#11-03
SINGAPORE 439193
TELEPHONE : HP +65 9669 8629
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900244032-01
VEHICLE NO : **SKH 6911 J**
MODEL CODE : AUDI A3 SB 1.0 TFSI
MODEL YEAR : 15/11/2019
ENGINE NO : CHZ C33218
CHASSIS NO : WAUZZZ8VXKA121470
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-May-22
PLACE OF ACCIDENT : STADIUM WALK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6911 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.	S/N \$	360.00 \$	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00 \$	500.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$	1,400.00 \$	1,400.00
4	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N \$	800.00 \$	800.00
5	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY FOR BOTH FRONT DOOR.	S/N \$	560.00 \$	280.00
6	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES.	S/N \$	2,800.00 \$	2,800.00
SUB-TOTAL LABOUR CHARGES			\$ 6,620.00	\$ 6,140.00



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6911 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
				\$ 6,140.00
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBRFRAME TO FACILITATE CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	S/N \$	2,400.00	\$ 2,400.00
8	TO SETUP VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	\$ 2,400.00
9	TO REMOVE AND RENEW THROTTLE BODY AND OTHER ENGINE COMPONENTS.	S/N \$	980.00	\$ 980.00
10	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00	\$ 480.00
11	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	400.00	
12	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$	200.00	\$ 150.00
SUB-TOTAL LABOUR CHARGES		:	\$ 6,860.00	\$ 12,550.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 6911 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
			\$ 12,550.00
13	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORT AND LHS FRONT CHASSIS FRAME WITH COVER PLATE. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 14,000.00	\$ 5,250.00
14	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT FENDER TOP SUPPORTS, LHS FRONT CHASSIS FRAME WITH COVER PLATE, BOTH FRONT DOORS AND BOTH UPP A-PILLARS.	\$ 8,500.00	\$ 3,575.00
15	TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 480.00	\$ 480.00
16	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	
17	Added labour - see attached	\$ 980.00	\$ 980.00
17a	Added labour - see attached	\$ 1,800.00	\$ 1,800.00
18	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		: \$ 39,904.00	\$ 25,019.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,146.00	\$	1,716.80
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	\$	156.00
3	FRONT BUMPER GUIDE SECTION- LH / RH	2	\$ 86.00	\$	68.48
4	FRONT BUMPER GRILLE - CENTER	1	\$ 179.00	\$	143.20
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 332.00	\$	265.20
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 636.00	\$	508.80
7	RADIATOR GRILLE	1	\$ 1,578.00	\$	1,262.40
8	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 210.00	\$	168.00
9	AIR COND STICKER	1	\$ 9.00	\$	6.64
10	CAUTION STICKER	1	\$ 16.00	\$	10.85
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 420.00	\$	336.00
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 211.00	\$	168.80
13	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 136.00	\$	108.80
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00	\$	677.20
15	HORN - LH / RH	2	\$ 426.00	\$	340.00
16	FRONT FENDER - LH / RH	2	\$ 1,908.00	\$	1,526.40
17	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00		
18	FRONT FENDER BRACKET - LH / RH	2	\$ 112.00	\$	88.80
19	FRONT FENDER POP RIVET	16	\$ 61.00	\$	48.64
20	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 136.00	\$	108.48
SUB TOTAL SPARE PARTS			\$ 9,719.00	\$	7,709.49

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
		<i>c/f</i>		\$	7,709.49
21	FRONT FENDER BRACE - LH / RH	2	\$	214.00	\$ 171.20
22	FRONT FENDER BRACKET END - LH / RH	2	\$	62.00	\$ 48.48
23	FRONT FENDER INSULATION - LH / RH	2	\$	96.00	
24	FRONT FENDER CLOSING ELEMENT END - LH / RH	2	\$	74.00	
25	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	366.00	\$ 292.80
26	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	60.00	
27	BONNET	1	\$	3,370.00	\$ 2,696.00
28	BONNET ATTACHMENT PARTS	1	\$	172.00	
29	BONNET HINGE - LH / RH	2	\$	136.00	\$ 108.48
30	BONNET SIDE COVER - LH / RH	2	\$	92.00	\$ 36.24
31	BONNET ABSORBER	1	\$	110.00	
32	BONNET EDGE PROTECTION	1	\$	31.00	\$ 24.72
33	BONNET CATCH HOOK - UPPER	1	\$	100.00	\$ 79.44
34	BONNET STRIKER - LH / RH	2	\$	246.00	\$ 196.00
35	BONNET CATCH HOOK - LOWER	1	\$	71.00	\$ 56.32
36	BONNET LOCK MICRO-SWITCH	2	\$	455.00	\$ 364.00
37	BONNET LOCK COVER	2	\$	8.00	\$ 6.40
38	BONNET BOWDEN CABLE - CENTER	1	\$	64.00	\$ 50.56
39	BONNET RELEASE CABLE COVER	1	\$	11.00	\$ 8.56
40	BONNET LOCK CABLE	1	\$	82.00	
SUB TOTAL SPARE PARTS		:	\$	5,820.00	\$ 11,848.69

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 11,848.69
41	BONNET SOUND ABSORBER	1	\$ 244.00	
42	BONNET PLENUM CHAMBER	1	\$ 199.00	\$ 159.20
43	HEADLIGHT - LH / RH	2	\$ 11,758.00	\$ 9,406.40
44	HEADLIGHT POWER MODULE - LH / RH	2	\$ 1,700.00	
45	HEADLIGHT CONTROL UNIT	2	\$ 1,249.00	
46	LED HEAT SINK - LH / RH	2	\$ 1,636.00	
47	HEADLIGHT HOSE - LH / RH	2	\$ 92.00	\$ 73.60
48	LIFT CYLINDER - LH / RH	2	\$ 312.00	\$ 124.40
49	LIFT CYLINDER HOSE	1	\$ 78.00	\$ 62.24
50	LIFT CYLINDER PUMP	1	\$ 171.00	\$ 136.80
51	WINDSCREEN WASHER SYSTEM PUMP	1	\$ 137.00	
52	WASH WATER RESERVOIR	1	\$ 225.00	\$ 180.00
53	WINDSCREEN STRAINER	1	\$ 24.00	
54	WINDSCREEN STRINER END CAP	1	\$ 24.00	\$ 18.96
55	WINDSCREEN SPRAY NOZZLE HEATED - LH / RH	2	\$ 234.00	
56	LOCK CARRIER	1	\$ 806.00	\$ 644.80
57	A/C CONDENSER	1	\$ 569.00	\$ 454.80
58	REFRIGERANT LINE	1	\$ 621.00	\$ 496.80
59	REFRIGERANT LINE	1	\$ 499.00	\$ 399.20
60	REFRIGERANT LINE	1	\$ 569.00	\$ 455.20
SUB TOTAL SPARE PARTS		:	\$ 21,147.00	\$ 24,461.09

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 24,461.09
61	REFRIGERANT LINE BRACKET	1	\$ 29.00	
62	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	\$ 16.32
63	EXTERNAL TEMPERATURE SENSOR	1	\$ 64.00	
64	ADDITIONAL RADIATOR	1	\$ 959.00	\$ 766.80
65	RADIATOR BRACKET - UPPER	2	\$ 90.00	\$ 71.68
66	RADIATOR BUSH - LOWER	2	\$ 22.00	\$ 16.96
67	RADIATOR	1	\$ 1,061.00	\$ 848.80
68	RADIATOR FAN RING	1	\$ 1,488.00	\$ 1,190.40
69	RADIATOR AIR GUIDE - LH / RH	2	\$ 56.00	\$ 44.32
70	RADIATOR SEAL - RH OUTER	1	\$ 9.00	\$ 7.12
71	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 14.00	\$ 10.88
72	RADIATOR COOLANT	6	\$ 282.00	\$ 225.60
73	QUICK RELEASE COUPLING COOLANT HOSE - FRONT	1	\$ 251.00	\$ 200.80
74	QUICK RELEASE COUPLING COOLANT HOSE - UPPER	1	\$ 125.00	
75	COOLANT PIPE - UPPER	1	\$ 65.00	
76	COOLANT PIPE - LOWER	1	\$ 34.00	\$ 26.80
77	QUICK RELEASE COUPLING COOLANT HOSE - LOWER	1	\$ 60.00	
78	QUICK RELEASE COOLANT HOSE	1	\$ 159.00	
79	INTAKE AIR DUCT COVER	1	\$ 30.00	\$ 23.76
80	INTAKE AIR GUIDE - LOWER	1	\$ 59.00	\$ 46.48
SUB TOTAL SPARE PARTS		:	\$ 4,878.00	\$ 27,957.81

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 27,957.81
81	INTAKE AIR GUIDE - UPPER	1	\$ 21.00	\$ 16.16
82	WATER DRAINAGE HOSE	1	\$ 37.00	
83	INTAKE AIR GUIDE - LOWER	1	\$ 69.00	\$ 54.64
84	AIR FILTER BOX	1	\$ 310.00	
85	INTAKE MANIFOLD - UPPER	1	\$ 156.00	
86	INTAKE MANIFOLD - LOWER	1	\$ 786.00	\$ 628.80
87	THROTTLE BODY	1	\$ 796.00	
88	CHARGE AIR COOLER	1	\$ 864.00	\$ 691.20
89	TOOTHED BELT GUARD - UPPER / LOWER	2	\$ 160.00	
90	TOOTHED BELT GUARD	1	\$ 202.00	
91	POLY V-BELT	1	\$ 52.00	
92	BATTERY CONSOLE	1	\$ 203.00	\$ 162.00
93	BATTERY HEAT INSULATION	1	\$ 96.00	
94	BATTERY FILLED CHARGED	1	\$ 584.00	
95	BATTERY PROTECTION COVER	1	\$ 145.00	
96	BATTERY MONITORING CONTROL UNIT	1	\$ 568.00	
97	FRONT FENDER TOP SUPPORT - LH / RH	2	\$ 164.00	
98	FRONT CHASSIS FRAME COVER PLATE - LH	1	\$ 107.00	\$ 85.20
99	SIDE MEMBER - LH	1	\$ 742.00	
100	GEARBOX MOUNTING BRACKET - LH	1	\$ 123.00	
SUB TOTAL SPARE PARTS			\$ 6,185.00	\$ 29,595.81

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>c/f</i>		\$	29,595.81
101	NOISE INSULATION	1	\$	376.00	\$ 300.80
102	BASE ENGINE	1	\$	18,936.00	
103	SUSPENSION SUBFRAME ASSEMBLY CARRIER	1	\$	1,105.00	
104	BONDED RUBBER BUSHES	1	\$	116.00	
105	GEARBOX MOUNTING - LH	1	\$	286.00	\$ 228.40
106	ENGINE MOUNTING - RH	1	\$	277.00	\$ 196.80
107	ENGINE MOUNTING CONSOLE - LH	1	\$	209.00	
108	ENGINE SUPPORT	1	\$	243.00	
109	ENGINE SUPPORT - LH / RH OUTER	2	\$	50.00	
110	PENDULUM SUPPORT	1	\$	100.00	
111	FRONT WINDSCREEN COLOUR STRIP	1	\$	1,206.00	\$ 964.80
112	RAIN SENSOR GEL FOIL	1	\$	130.00	\$ 104.00
113	SPRING CLIP	1	\$	23.00	
114	PRIMER	1	\$	22.00	\$ 17.36
115	WINDSCREEN WATER DEFLECTOR STRIP - LH / RH	2	\$	150.00	\$ 60.00
116	AERO WIPER ARM - LH / RH	2	\$	230.00	
117	AERODYNAMIC WIPER BLADE	1	\$	101.00	
118	AERODYNAMIC WIPER BLADE CAP	2	\$	20.00	
119	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH	2	\$	604.00	
120	ROOF CHROME MOLDING - LH / RH	2	\$	1,330.00	
SUB TOTAL SPARE PARTS		:	\$	25,514.00	\$ 31,467.97

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 6911 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 31,467.97
121	GEARBOX	1	\$ 18,564.00	
122	TRANSMISSION FLUID	5	\$ 353.00	\$ 112.96
123	ELECTRIC SYSTEM HOUSING	1	\$ 93.00	
124	FUSE BOX COVER	1	\$ 54.00	
125	ENGINE COMPARTMENT	1	\$ 27.00	
126	E BOX	1	\$ 394.00	
127	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
128	FRONT WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
129	ARYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
130	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
131	METAL PILLER POWDER	S/N	\$ 280.00	\$ 280.00
132	STONE CHIP	S/N	\$ 180.00	
133	ADDED PARTS - SEE ATTACHED		\$ 8,824.00	\$ 5,191.36
134	ADDED PARTS - SEE ATTACHED		\$ 5,664.10	\$ 4,770.48
135	SUNDRIES		\$ 800.00	\$ 260.88
TOTAL SPARE PARTS		:	\$ 109,076.10	\$ 42,663.65
TOTAL LABOUR CHARGES		:	\$ 39,904.00	\$ 25,019.00
GRAND TOTAL		:	\$ 148,980.10	\$ 67,682.65

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0435/2022/JT 8-Jun-22 CHANG 1 of 1 SKH 6911 J AUDI A3 SB 1.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	COVER PLATE FOR SLIDE MEMBER - LH	1 \$ 860.00	\$ 689.20
2	VACUUM HOSE WITH NON-RETURN VALVE	1 \$ 378.00	\$ 302.80
3	OIL FILTER	1 \$ 28.00	\$ 22.32
4	MECHATRONIC WITH SOFTWARE	1 \$ 4,426.00	\$ 3,540.80
5	SOCKET HEAD BOLT	4 \$ 49.00	\$ 38.72
6	FLAT CONNECTOR HOUSING	1 \$ 23.00	\$ 18.32
7	1 SET SINGLE WIRE	2 \$ 79.00	\$ 62.88
8	COOLANT HOSE	1 \$ 139.00	\$ 111.20
9	COOLANT PUMP	1 \$ 373.00	\$ 298.00
10	OIL SEPARATOR COVER	1 \$ 16.00	\$ 12.72
11	OIL SEPARATOR	1 \$ 118.00	\$ 94.40
12	A/C COMPRESSOR	1 \$ 2,335.00	
GRAND TOTAL		\$ 8,824.00	\$ 5,191.36

For Premium Automobiles Pte Ltd

 Authorised Signature



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0435/2022/JT 5-Jul-22 GLORY 1 of 1 SKH 6911 J AUDI A3 SB 1.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO RENEW GEARBOX MECHATRONICS AND CARRY OUT ADAPTATION.	S/N \$ 980.00	\$ 980.00
GRAND TOTAL		\$ 980.00	\$ 980.00

For Premium Automobiles Pte Ltd

 Authorised Signature



Supplementary Estimate-3

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0435/2022/JT 23-Jul-22 CHANG 1 of 1 SKH 6911 J AUDI A3 SB 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	OIL FILTER	1	\$ 27.90
2	BRAKE FLUID	2	\$ 69.20
3	SEATBELT ADJUSTER	2	\$ 430.00
4	SEAT BELT - LH	1	\$ 1,227.00
5	SEAT VELT - RH	1	\$ 1,227.00
6	AIRBAG CONTROL UNIT	1	\$ 1,982.00
7	FUSE	1	\$ 48.10
8	OIL SEPERATOR	1	\$ 290.50
9	ENGINE COVER SEALANT	1	\$ 63.40
10	ENGINE OIL	2	\$ 598.00
		\$ 5,963.10	\$ 4,770.48
<u>Labour</u>			
1	To remove and renew both front seat belts, airbag control unit (Include remove and reinstall console)	S/N	\$ 1,800.00
GRAND TOTAL		\$ 7,763.10	\$ 6,570.48

For Premium Automobiles Pte Ltd

 Authorised Signature