

ASS. REC. BY:

REF:

Smo / 22005071/K+

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SHC 4853T

Yr Regn:

11 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1788

Colour

M-Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN364505766623

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pailun

Front

Rear

R/Bal.

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

5

mm

D.O.A.

27/5/22

D.O.I.

30/5/2022

Survey held at

Des. of Damages: Rear / O/S / N/S / UIC / Rooftop or

M O/S

The UIC / Chassis frame / Body Structure affected due to collision.

LUMP SUM \$3250

red: 11,983.01;78%

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



## Case Details

Case Reference Number : TAX/05/22/2075  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHC4853T

Company Type : Strides Taxi Pte Ltd  
 Estimation ID : EST-18394-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : Sompo Insurance Singapore Pte. Ltd  
 Accident Date and Time : 27/05/2022 07:36 AM  
 Vehicle Age(In Months) : 78

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	✓ Buz
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	10	33.75	Replace	✓ m
Standard	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check	✓ Su X
Standard	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	✓
Standard	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check	✓ CPA
Standard	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check	✓ Bz
Standard	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	✓
Standard	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check	✓ Su X
Standard	Main			DEFLECTOR, RADIATOR RH	1	83.50	83.50	25.00	62.63	Replace	0	0	Not Give	✓
Standard	Main			DEFLECTOR, RADIATOR LH	1	77.00	77.00	25.00	57.75	Replace	0	0	Not Give	✓
Standard	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	1	82.80	Replace	✓ Di X
Standard	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	✓ Ad
Standard	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	✓ dented
Standard	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Give	✓
Total Spare Part Cost									13,925.19	Surveyor Total 2,073.24				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									11,109.01	Final Sur Total 1,658.59				



SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Give	
Standard	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace	CM
Standard	Main			WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	10.00	217.80	Replace	0	0	Not Give	
Standard	Main			THERMISTOR ASSY	1	107.00	107.00	10.00	96.30	Replace	0	0	Not Give	
Standard	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Check	my m
Standard	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Not Give	
Standard	Main			BRACKET, FR TURN CENTER RH	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Give	
Standard	Main			BRACKET, FR TURN UPPER RH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give	
Standard	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give	
Standard	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	
Standard	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	
Standard	Main			EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	1	64.88	Replace	m
Standard	Main			HOOD END PANEL SEAL	1	35.50	35.50	25.00	26.63	Replace	0	0	Not Give	
Standard	Main			COVER, RADIATOR	1	122.80	122.80	25.00	92.10	Replace	0	0	Not Give	
Standard	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Check	pu x
Standard	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Not Give	
Standard	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	CM
Standard	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	CM
Standard	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0	Not Give	
Standard	Main			UNDER COVER SIDE/LH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	
Standard	Main			UNDER COVER SIDE/RH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	
Standard	Main			HOOD PANEL	1	748.10	748.10	25.00	561.08	Replace	1	561.08	Replace	B1
Standard	Main			HOOD PANEL INSULATOR	1	390.50	390.50	25.00	292.88	Replace	0	0	Not Give	
Total Spare Part Cost									13,925.19	Surveyor Total 2,073.24				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									11,109.01	Final Sur Total 1,658.59				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			HOOD HINRE LH	1	55.90	55.90	25.00	41.93	Replace	1	0	Repair	
Standard	Main			HOOD HINGE RH	1	55.90	55.90	25.00	41.93	Replace	1	0	Repair	
Standard	Main			HOOD LOCK	1	128.90	128.90	25.00	96.68	Replace	1	0	Repair	
Standard	Main			CABLE ASSY,HOOD	1	52.20	52.20	25.00	39.15	Replace	0	0	Not Give	
Standard	Main			HOOD AUXILIARY CATCH	1	8.60	8.60	25.00	6.45	Replace	0	0	Not Give	
Standard	Main			CLAMP, HOOD LOCK	1	5.90	5.90	25.00	4.43	Replace	0	0	Not Give	
Standard	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Not Give	
Standard	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give	
Standard	Main			HEAD LAMP RH	1	945.20	945.20	25.00	708.90	Replace	1	708.90	Replace	CRM
Standard	Main			WIPER WASHER INLET	1	36.90	36.90	25.00	27.67	Replace	0	0	Not Give	
Standard	Main			WIPER WASHER JAR	1	180.10	180.10	25.00	135.08	Replace	0	0	Not Give	
Standard	Main			MOTOR NO:1, WIPER WASHER JAR	1	239.00	239.00	10.00	215.10	Replace	0	0	Not Give	
Standard	Main			MOTOR NO:2, WIPER WASHER JAR	1	240.00	240.00	10.00	216.00	Replace	0	0	Not Give	
Standard	Main			SUPPORT RADIATOR, LH	1	17.70	17.70	25.00	13.27	Replace	0	0	Not Give	
Standard	Main			SUPPORT RADIATOR, RH	1	54.50	54.50	25.00	40.88	Replace	0	0	Not Give	
Standard	Main			SUPPORT, RADIATOR	2	18.50	37.00	25.00	27.75	Replace	0	0	Not Give	
Standard	Main			RADIATOR LOWER SUPPORT	1	876.30	876.30	25.00	657.22	Replace	0	0	Not Give	
Standard	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	0	Old Dam	
Standard	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.93	Replace	0	0	Not Give	
Standard	Main			FENDER PROTECTOR FRT/RH SIDE	1	113.90	113.90	25.00	85.43	Replace	0	0	Not Give	
Standard	Main			FENDER SEAL TO COWL SIDE RH	1	15.20	15.20	25.00	11.40	Replace	0	0	Not Give	
Standard	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	
Standard	Main			FENDER LINER PAD, FR WHEEL RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	
Total Spare Part Cost									13,925.19	Surveyor Total		2,073.24		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									11,109.01	Final Sur Total		1,658.59		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			FENDER APRON SUB FRT/RH	1	637.80	637.80	25.00	478.35	Replace	0	0	Not Give	▼
Standard	Main		6505658	WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give	▼
Standard	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	▼
Standard	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	0	0	Not Give	▼
Standard	Main			STICKER STRIDES TAXI ( DOOR )	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	▼
Standard	Main			HINGE LOWER RHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Give	▼
Standard	Main			HINGE UPPER RHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Not Give	▼
Standard	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	▼
Standard	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give	▼
Standard	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.93	Replace	0	0	Not Give	▼
Total Spare Part Cost									13,925.19	Surveyor Total		2,073.24		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									11,109.01	Final Sur Total		1,658.59		

**Labour's Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,014.00	400	
Total:			1,014.00	400.00	

**Spray Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT HOOD	378.00	200	
4	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
5	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
Total:			2,610.00	400.00	

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**



S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO RESPRAY APRON PANEL RH	180.00	0	
7	Main	TO RESPRAY RIM	180.00	0	
8	Main	TO RESPRAY FRONT FENDER LH	378.00	0	
9	Main	TO RESPRAY FRONT DOOR RH	378.00	0	
<b>Total:</b>			<b>2,610.00</b>	<b>400.00</b>	

18018.44

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
<b>Total:</b>			<b>500.00</b>	<b>50.00</b>	

**Summary**

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	11,109.01	1,658.59
Total Labour Cost	1,014.00	400.00
Total Spray Painting	2,610.00	400.00
Other	500.00	50.00
Overall Total	15,233.01	2,508.59
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	15,250.00	2,500.00
Surveyor Approved Amount		2,500.00
No of Repair Days*	6	14
Remarks	-	REQUEST NBV / LUMP SUM REPAIR / AFTER PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 /

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

Signature

Kenneth Kong (LKK)



Save

Clear

Survey Date

30/05/2022

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 369K

### Vehicle Details

Vehicle No.: SHC4853T  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 30 May 2022  
Vehicle Make: TOYOTA  
Vehicle Model: PRIUS TAXI (SMRT)  
Primary Colour: Maroon  
Manufacturing Year: 2015  
Engine No.: 2ZR6549201  
Chassis No.: JTDKN36U505766623  
Maximum Power Output: 100.0 kW (134 bhp)  
Open Market Value: \$29,508.00  
Original Registration Date: 06 Nov 2015  
First Registration Date: 06 Nov 2015  
Transfer Count: 0  
Actual ARF Paid: \$5,000.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 05 Nov 2023  
PARF Rebate Amount: \$3,250.00

### Intended COE Rebate Details

COE Expiry Date: 05 Nov 2023  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 8  
PQP Paid: \$45,267.00  
COE Rebate Amount: \$8,109.00

**Total Rebate Amount: \$11,359.00**

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 May 2022

OK

$$96 - 78 = \$18 \text{ month}$$

$$pc \text{ Val} \div 96 = \$ \underline{\hspace{2cm}}$$

$$\swarrow \quad \times 18 \text{ month}$$

$$= \$$$



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	28/05/2022 08:18 (SGT)
Date of Accident	27/05/2022 15:36 (SGT)
Exact Location of Accident	Near 804B Keat Hong Cl, Singapore
Additional Location Information	JUNCTION OF BRICKLAND ROAD AND CHOA CHU KANG AVE 6
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4853T
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	STRIDES TAXI PTE LTD
Company Reg No	1XXXXX369K
Email Address	Auto-Svcs-TARC@smrt.com.sg
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

#### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-22099115MFSH
Cover Note Number	-

#### DRIVER

Name of Driver	SALINI BIN ROHMAT
----------------	-------------------

NRIC No	SXXXX530J
Date Of Birth	08/05/1972
Occupation	Outdoor
Date Of Driving Pass	03/07/2003
Driving experience	18 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	Auto-Svcs-TARC@smrt.com.sg
Address	1
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	UNKNOWN
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING STRAIGHT ALONG BRICKLAND ROAD AT THE RIGHT MOST LANE WITH A PASSENGER ON BOARD. WHEN REACHING THE TRAFFIC JUNCTION, TRAFFIC LIGHT WAS GREEN IN MY FAVOUR AND THUS I CONTINUE PROCEED STRAIGHT. SUDDENLY THE VEHICLE SKG5681J FROM THE OPPOSITE DIRECTION MAKE A RIGHT TURN AND RESULTED THE LEFT FRONT SIDE OF THE VEHICLE HIT ONTO THE FRONT PORTION OF MY TAXI.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKG5681J
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	YAP SEK BENG
NRIC No	SXXXX115G
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



We declare the foregoing particulars are true in every respect.



27.05.2022

Witnessed by Reporting Centre  
Personnel