



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22005081/Eny3m4 Date: 22/11/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 4179L	Veh. Inspected	SMF 5564X	
Policy No.		Coverage (\$)	0.00	
Claim No.	AISCL2022-00001SL	Excess (\$)	0.00	
Assign From	SHANTI	Assign Date	30/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JF1SJ5KC5JG112508	Colour	GREY	
Odometer	106334 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	BRIDGESTONE	5 mm	
L/H Front Tyre	225/60 R17	BRIDGESTONE	5 mm	
R/H Rear Tyre	225/60 R17	BRIDGESTONE	5 mm	
L/H Rear Tyre	225/60 R17	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/05/2022	Inspection Date	31/05/2022	
Survey held at	25 LENG KEE ROAD, SINGAPORE 159097			
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	