



25 LENG KEE ROAD
S(159097)



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SMF5564X	MODEL : FORESTER 2.0I-L AWD CVT
REF NO:	YEAR: 16 - NOV - 2018
ENGINE NO: FB20YE49879	CHASSIS NO: JF1SJ5KC5JG112508
DOA: 23/05/2021	TOA: 1740 hrs
TYPE OF CLAIM: 3rd Party	INS COMPANY:

S/N	NATURE OF JOB	AMOUNT
1.	TO REPLACE REAR BUMPER,BUMPER BEAM,TAILGATE	\$1740.00
2.	TO RESPRAY REAR BUMPER,BUMPER BEAM,TAILGATE	\$1470.00
3.	TRANSFER TAILGATE INNER TRIMS & MECHANISM	\$150.00
4.	REMOVE & REPLACE REAR WINDSCREEN	\$300.00
5.	TO INSTALL REAR WINDSCREEN SOLAR FILM	\$145.00
6.	TO INSTALL REVERSE SENSOR 2-EYES	\$300.00
7.	FAULT DIAGNOSTIC (RESET)	\$280.00
8.	TO CONDUCT REAR LIGHTING TEST	\$150.00
9.	REMOVE & REFIX EXHAUST	\$150.00
10.	REMOVE & REFIX CARPET,SEAT TO FACILITATE REPAIRS	\$400.00
11.	DISMENTLE & REFIX REAR UNDERCARRIAGE TO FACILITATE REPAIRS	\$300.00
12.	REMOVE & REFIX FUEL TANK	\$300.00
13.	4 WHEEL ALIGNMENT	\$200.00
14.	REPLACE & REPAIR REAR END PANEL,REAR LHS FENDER,REAR RHS FENDER,REAR FLOOR PAN	\$2000.00
15.	RESPRAY REAR END PANEL,REAR LHS FENDER,REAR RHS FENDER,REAR FLOOR PAN	\$1960.00
16.	TO CONDUCT REAR PROTECTANT COATING	\$500.00
17.	TO CONDUCT REAR ANTI RUST COATING	\$580.00
	Total Labour	\$10925.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	
HP / EMAIL:	/
BEFORE PAINT:	
DAYS GIVEN:	

Part Number	Qty	Description	Dealer	Suggested
57711SG0219P	1	BACK BEAM COMPLETE-REAR		296.00
57707SG090	1	BRACKET-REAR BUMPER SIDE,LEFT		14.80
57707SG080	1	BRACKET-REAR BUMPER SIDE,RIGHT		14.80
57704SG012	1	BUMPER-FACE,REAR		555.00
57731SG010EN	1	COVER-REAR BUMPER		13.00
909140062	2	CLIP-2PIECE D7		6.00
909140007	9	CLIP-BUMPER		21.60
60809SG0109P	1	PANEL-REAR GATE		1,102.60
63232SG000	2	DAM RUBBER-REAR GATE GLASS		7.40
63232SG010	1	RUBBER-REAR GATE		13.00
93079SG000	1	LETTER MARK-REAR		40.70
93079SG030	1	LETTER MARK-REAR		66.60
52401SG0109P	1	SKIRT COMPLETE-REAR		296.00
63019SG000	1	GLASS-REAR GATE		821.40
Total:	24			3,268.90