

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF5564X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	CONDUCT 3RD PARTY CLAIM AIS DATE:23/05/2022 TIME:1740 LOCATION:UPP SERANGGOON RD 18 WOODSVILLE		
2	ZZ/002	REPAIR/REPLACE REAR BUMPER,END PANEL & TAILGATE	1680.00	1120.00
3	ZZ/003	RESPRAY REAR BUMPER,END PANEL & TAILGATE	1260.00	840.00
4	ZZ/004	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	150.00	150.00
5	ZZ/005	REMOVE/REPLACE REAR WINDSCREEN	300.00	300.00
6	ZZ/006	SUPPLY/INSTALL REAR WINSCREEN TINTED FILM	145.00	145.00
7	ZZ/007	INSTALL REVERSE SENSOR 2 EYES	300.00	.00
8	ZZ/008	FAULT DIAGNOSTIC RESET	280.00	.00
9	ZZ/009	CONDUCT REAR LIGHTING TEST AFTER REPAIR	150.00	50.00
10	ZZ/011	REMOVE,REFIX REAR CARPET/GARNISH/UPHOLSERY & SEAT TO FACILITATE REPAIR	400.00	.00
11	ZZ/012	REMOVE/REFIX REAR U/CARRIAGE TO FACILITATE REPAIR	300.00	.00
12	ZZ/013	REMOVE/REFIX FUEL TANK	300.00	.00
13	ZZ/014	CONDUCT 4 WHEEL ALIGNMENT	200.00	.00
14	ZZ/015	REPAIR/REPLACE REAR LH FENDER REAR RH FENDER & FLOORPAN	1680.00	.00
15	ZZ/016	RESPRAY REAR LH FENDER, REAR RH FENDER & FLOORPAN 1260		
16	ZZ/017	CONDUCT REAR PROTECTANT COATING	500.00	.00
17	ZZ/018	CONDUCT REAR ANTI RUST COATING	580.00	.00
18	ZZ/019	REPAIR END PANEL & SPARE TYRE FLOOR PANEL (SUPP)	560.00	560.00 ✓ (supp)
19	ZZ/020	RESPRAY REAR END PANEL, FLOOR PANEL & BEAM(SUPP)	840.00	840.00 ✓ (supp)
20	ZZ/021	CONDUCT ANTI RUST COATING (SUPP	80.00	80.00 ✓ (supp)
21	ZZ/10	REMOVE/REFIX EXHAUST	150.00	.00
TOTAL LABOUR CHARGES			9855.00	4085.00