

Case Details

Case Reference Number :
TAX/05/22/2072
Type of Repair : Accident Repair
Vehicle Registration Number :
SHB127M

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-18378-ID
Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
Accident Date and Time : 25/05/2022 01:30 AM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			FASCIA-FRT BPR	1	721.65	721.66	10.00	649.49	Replace	0	0	Not Give	Xm
Standard	Main			FINISHER-FRT BPR - LH	1	98.80	98.80	10.00	88.92	Replace	0	0	Not Give	Xm
Standard	Main			FINISHER-FRT BPR - RH	1	98.80	98.80	10.00	88.92	Replace	0	0	Not Give	Xm
Standard	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	Xm
Standard	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	Xm
Standard	Main			GRILLE ASM-RAD	1	978.02	978.02	10.00	880.22	Replace	1	880.22	Replace	coa
Standard	Main			INSERT-FRT LIC PLT EMB	1	30.26	30.26	10.00	27.23	Replace	1	27.23	Replace	re
Standard	Main			BAR ASM-FRT BPR IMP	1	624.00	624.00	10.00	561.60	Replace	0	0	Not Give	Xm
Standard	Main			SOCKET-CHRG	1	2,036.74	2,036.74	10.00	1,833.07	Replace	0	0	Check	? Xm
Total Spare Part Cost									4,189.45	Surveyor Total		907.45		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									4,189.45	Final Sur Total		907.45		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,200.00	200	
Total:			1,200.00	200.00	

Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	428.00	0 X17	
Total:			428.00	0.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 X17	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 X17	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 XM	
4	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0 XM	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0 X17	
6	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150 /	
7	Main	ISOLATED OF (EV) (NET)	150.00	150.00 /	
Total:			1,080.00	300.00	


Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,189.45	907.45
Total Labour Cost	1,200.00	200.00
Total Spray Painting	428.00	0.00
Other	1,080.00	300.00
Overall Total	6,897.45	1,407.45
Lump Sum Repair Option	<input type="checkbox"/>	<input type="checkbox"/>
Lump Sum Total	0.00	1,407.45
Surveyor Approved Amount		1,407.45
No of Repair Days*	5	2
Remarks	-	PART BY PART REPAIR / RESURVEY NEW AND OLD PARTS PHOTO . REQUIER DETAILED PHOTO OF THE FRONT
Surveyor Name		Rasul

Signature

Estimator Assessment(\$)

Surveyor Assessment(\$)



Save

Clear

Survey Date

26/05/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: