



南方摩哆 Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

30 May 2022

Lonpac Insurance Bhd

300 Beach Road #17-04/07

The Concourse

Singapore (199555)

Dear Sirs,

RE: Cost of repair to Honda Var10 -JTW6186

1 set of Front Fork Comp	✓ X R	S\$	280.00 X
1 pc of Head Lamp Comp	✓ mis		380.00 ✓
1 pc of Front Body Set	✓ cut		480.00 400 ✓
1 pc of Meter Cover	✓ mis		180.00 120 ✓
1 pc of Handle Bar	✓ Ji		110.00 90 ✓
1 pc of Brake Cable	✓ cut		85.00 ✓
1 pc of Front Lamp Stay Bracket	✓ Ji		65.00 ✓
1 pc of Exhaust Pipe Cover	✓ cut		65.00 ✓
1 pc of Handle Balancer	✓ cut		45.00 30 ✓
1 pc of Givi Box	✓ cut		120.00 ✓
		1355	1,810.00
		-10%	181.00
Less 10%		1219.50	1,629.00
Nett			30.00 ✓
Transport			380.00 2.100 ✓
Jack & Alignment Body			300.00 200 ✓
Labour		330	<u>\$2,339.00</u>

=1549.50

Yours Faithfully,
Southern Motor



Stew (LKK)

31/5/22, 12.00pm

8322 8813

M L

L/S

M L G

3 L/S

L/S - 1239.60

=1250