

Not authorized
 11pm @ 4100h
 Punny After Paint
 5 days

JA AUTOCARE PTE LTD
 Blk 24, Sin Ming Road
 #03-25
 Tel : 94513429
 Tel : 94513429

MSIG Insurance (Singapore) Pte Ltd
 4 Shenton Way
 #21-01 SGX Tower Two
 Singapore 068807

ESTIMATE
 Date: 28.05.22
 vehicle number: SLA 1760K
 Model T/ALTIS
 Chassis/Eng# :
 Accident Date : 28.05.2022

Parts :

- 01) Front lh door *1079.60*
- 02) Front lh door handle *155.20*
- 03) Front lh door weatherstrip
- 04) Front door regulator & motor assy
- 05) Front lh door lock assy
- 06) Rear Lh door *1069.20*
- 07) Rear lh door weatherstrip
- 08) Rear lh door regulator assy (with motor) *485.10*
- 09) Rear lh door lock assy
- 10) Rear fender lh

\$ R	1,250.00	✓
\$ Tm	258.00	✓
\$ M	110.00	X
<i>Dist</i> \$ M	560.00	✓
\$ M	350.00	✓
\$ R	1,350.00	✓
\$ Rm	258.00	X
\$ Oii	560.00	✓
<i>Oii</i> \$ Rcl	350.00	✓
\$ R	850.00	X
\$	5,896.00	
Less 25%	\$ (1,474.00)	
\$	4,422.00	

Labour Charges

- 11) To dismantle door board , upholstery etc
- 12) To transfer 2 door glass
- 13) To check wiring
- 14) To knock out dents on affected areas and renew parts
- 15) To putty & respray painting

\$	220.00	<i>80l</i>
\$	240.00	<i>120l</i>
\$	120.00	<i>20l</i>
\$	1,000.00	<i>700l</i>
\$	1,400.00	<i>800l</i>
\$	2,980.00	

Total **\$ 7,402.00**

for JA AutoCare Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JA AUTOCARE PTE LTD

Blk 24, Sin Ming Road

#03-25

Tel : 94513429

Tel : 94513429

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01 SGX Tower Two
Singapore 068807

SUPPLEMENTARY ESTIMATE

Date: 31.05.2022
vehicle number: SLA 1760K
Model T/ALTIS
Chassis/Eng# :
Accident Date : 28.05.2022

Parts :

01) Front lh door handle inner bracket lh	125	\$ M	250.00	✓
02) Front lh door outer garnish	67.50	\$ M	180.00	✓
03) Front lh door glass channel	124.90	\$ M	350.00	✓
04) Rear lh door checker	148.60	\$ M	290.00	✓
05) Rear lh door garnish	67.50	\$ M	180.00	✓
		\$	1,250.00	
		Less 25%	\$ (312.50)	
		\$	937.50	

Labour Charges

06) To knockout dents on centre door pillar & rocker panel lh	} Already calculated in high estimate	\$	450.00
07) To putty & respray painting		\$	450.00
		\$	900.00
Total		\$	1,837.50

for JA AutoCare Pte Ltd