



CAR CITY AUTO CENTRE PTE LTD

Blk 9006 Tampines Street 93 #01-198 Singapore 528840

TEL: (65) 85114276 FAX: (65) 67820300 EMAIL: ccapl@singtel.com.sg

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : SMG 7099 D

Make & Model : BMW 216

Year of Manufacture : _____

Chassis No. : WBA6V120X0ED05667

Ins Company : CHINA VS AXA

Engine No. : _____

Excess : 2018

Policy No. : _____

Date of Accident : 27/05/2022

Time of Accident : 5.40PM

Suggested Days of Repair : _____

Service Advisor : _____

Repair Estimates

Parts (a) Cost / List Price Items \$ 6,044.00

Plus/Less 5% \$ 302.20

Total of Cost / List \$ 5,741.80

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 300.00

Total Parts Cost (Appendix A) \$ 6,041.80

Labour (Appendix B) \$ 1,150.00

Total Repair Cost \$ 7,191.80

In-house Vehicle Assessor

Case Owner : _____

Signature : _____

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Mercus

Company : LKK

Survey conducted on : 6/6/22 at 12pm

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 3 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature] Date: _____

not authorized #1290096608 to be able to repair 1/5 @ 1800



CAR CITY AUTO CENTRE PTE LTD

Blk 9006 Tampines Street 93 #01-198 Singapore 528840

TEL: (65) 85114276 FAX: (65) 67820300 EMAIL: ccapl@singtel.com.sg

ESTIMATED REPAIR COST DETAILS

Vehicle No : SMG 7099 D Case Owner : 0

Make & Model : BMW 216 Year Manufacture : 0

Chassis No : WBA6V120X0ED05667 Engine No : 0

Date & Time : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	RHF FENDER	1		\$ 630.25	R X	
2	FRONT BUMPER	1		\$ 1,115.50	Deep cut	—
3	FRONT BUMPER RETAINER RH TOP	1		\$ 27.70	MAX	
4	FRONT BUMPER RETAINER RH BOTTOM	1		\$ 24.20	MAX	
5	FRONT BUMPER BRACKET RH	1		\$ 99.45	MAX	
6	HEADLAMP RH	1		\$ 2,640.65	SVCX	
7	HEADLAMP BRACKET RH	1		\$ 154.25	MAX	
8	SPORTS RIM 17"	1		\$ 1,100.80	R X	
9	TYRE 205/55/17	1			SVCX	\$ 300.00
10	RHF BUMPER SENSOR	1		\$ 251.20	shhd	—
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

