

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	JC / 27052022 / SKQ8259Z (OD)
Policy No:	MPC21B00027080	Date of Loss:	27/05/2022
Vehicle Reg. No.:	SKQ8259Z	Driveable?	NO
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	LOH MEE FOE EDMUND		
Driver:	LOH MEE FOE EDMUND		
Make/Model:	MAZDA 6, 2.0 (A)	Vehicle Reg. Date:	29/12/2014
Vehicle Colour:	Blue		
Engine No:	PE20579363	Chassis No:	JM6GJ1071F0147292
Odometer:	120000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	JACK CARS ENTERPRISE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	6,014.50
Miscellaneous Items	200.00
Labour	4,300.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	10,514.50
+ GST 7.00% (\$\$)	736.02
Nett Amount (\$\$)	11,250.52

This claim is handled by: **THANALETCHUMI SANTERASHIGARM**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 May 2022)

Parts: 143 MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Jack Cars Enterprise Pte Ltd/SKQ8259Z/30/05/2022 13:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>Distorted</i>	0.00	0.00	*800.00 F ✓
2	1		*FRONT BUMPER BRACKETS (LEFT & RIGHT) <i>LH Dmgd</i>	0.00	0.00	*100.00 F <i>50</i>
3	1		*FRONT BUMPER GRILLE <i>crackd</i>	0.00	0.00	*500.00 F ✓
4	1		*HEADLIGHT - LEFT <i>crackd</i>	0.00	0.00	*1,000.00 F ✓
5	1		*HEADLIGHT - RIGHT <i>new</i>	0.00	0.00	*1,000.00 F ✓
6	1		*HEADLIGHT BRACKETS (LEFT & RIGHT) <i>LH Dmgd</i>	0.00	0.00	*100.00 F <i>50</i>
7	1		*FRONT BUMPER LOWER LIPS <i>Rehnd</i>	0.00	0.00	*300.00 F ✓
8	1		*MUDGUARD - LEFT LINER <i>Rehnd Missing</i>	0.00	0.00	*230.00 F <i>180</i>
9	1		*FENDER - FRONT LEFT <i>Rehnd</i>	0.00	0.00	*1,200.00 F <i>780</i>
Sub Total (S\$)						5,230.00
+ Margin on L,N Items 15.00% (S\$)						784.50
Total Parts (S\$)						6,014.50

F=Franchise part.

Jack Cars Enterprise Pte Ltd/SKQ8259Z/30/05/2022 13:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	CLIPS , SCREWS & RIVETS <i>Ne</i>	100.00 <i>50.</i>
2	1	NUMBER PLATE - FRONT <i>Beats</i>	45.00 <i>30</i>
3	1	NUMBER PLATER COVER <i>Dehamed</i>	55.00 <i>30</i>
Sub Total (S\$)			200.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,500.00 <i>500.</i>
2	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	New	2,300.00 <i>700.</i>
3	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	New	500.00 <i>30.</i>
Gross Labour Cost (S\$)			4,300.00

Jack Cars Enterprise Pte Ltd/SKQ8259Z/30/05/2022 13:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
4/5 04/06/22.
05 Days -
Not Authorised,
Excess to be advised.