

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	ALLIANZ INSURAN	NCE SINGAPORE PTE LTD		Ref:	CS/AIS22005103/Tqy3m4	
	79 ROBINSON RO #09-01 SINGAPOR			Date:	18/07/2022	
				Code:	AIS	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJJ 4100Y	Veh. Inspected		SHC 8976X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	2022 22005023SL	Excess (\$)		0.00	
	Assign From	SHANTI	Assign Date		30/05/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	KMHLB41UMGU089804	Colour		BLUE	
	Odometer	800596 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE		6 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE		6 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE		6 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	26/05/2022	Inspection Date	)	30/05/2022	
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD			
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					
L	1					