

ASS. REE. BY: Tauhin

REF:

CS/41522005103/Tg3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / (P)WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

WP
h m TSVeh No: SNC8976XYr Regn: 2016, MayType: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

Truck / Trailer or

Make: Hyundai140

c.c.

1685Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 866596

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMH LB4 / MMG 4089804Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim orTyre Size: F: 205/60 R14R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 30/5/22Survey held at Comfort Wzy

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Rep. Format: _____

Lump Sum / L.B.I. (\$) _____

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 28.05.2022 (Sat)INSURANCE: ALLIANZ *C45J*MODEL: Hyundai i40MVA: LIM T SVEHICLE NO.: SHC8976X

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Wheel Cap RH	1		\$ 217.20
	Rocker Panel Garnish RH			<i>732.80</i>
	SUB TOTAL			\$ 217.20
	LESS 25%			\$ 54.30
	DISCOUNTED TOTAL			\$ 162.90
	Rear Fender Adv.Sticker RH	1		\$ 100.00
	Rocker Panel Garnish Adv.Sticker RH	1		\$ 100.00
	Labour Charge			
	Panel Beating - Rear Fender Arch RH			\$ 300.00
	Spray Painting Charge - Rocker Panel Garnish RH <i>, Rear RH fender</i>			\$ 600.00
	Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 1,020.00
	ESTIMATE TOTAL			\$ 1,382.90

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfer 97495449
 WP 30/5/22
 tanfer@lkkauto.com
 02 days
 tanfer@lkkauto.com

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(csat)

Date/Time: 28.05.2022 09:32

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4220850

JC NO.305517629

STOMER

I/MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755 (O)
(P)

SCOUNT CARD NO.

REGN NO.: SHC8976X	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 27.05.2022 15:10
YR OF MANU. 19.05.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU089804	COMPLETION DATE/TIME:

Accident Date: 26.05.2022
NATURE: 3P 26.05.2022

S/NO LABOR CODE
000010 PB


JOB DESCRIPTION

4S Allianz

SJJ

4100Y

DESCRIPTION
LUMPSUM REPAIR-SHC8976X-TP



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

Vehicle No.:

SHC8976X

SHC8976X

LIMITS

Signature/Date

Name of Service Advisor