



JACK CARS

DRIVE WITH ASSURANCE

ESTIMATE

DATE OF ACCIDENT : 28/05/2022	
VEHICLE : SJM5909M	
MAKE & MODEL : HONDA FREED	GB71064063
INSURANCE : GREAT AMERICAN INSURANCE COMPANY	Veron.
SURVEYOR : LKK AUTO ADRIAN	

PARTS		AMOUNT
1.	REAR BUMPER <i>Dehnd.</i>	\$ 900 ✓
2.	REAR BUMPER INNER BRACKET <i>new</i>	\$ 50 ✓
3.	REAR BOOT <i>Distorted.</i>	<u>\$ 1200</u> ✓
4.	REAR BOOT INNER COVER <i>Dehnd.</i>	\$ 180 ✓
5.	REAR BOOT WEATHERSTRIP <i>lt</i>	\$ 320 ✓
6.	REAR BOOT CHROME GARNISH <i>Not new</i>	\$ 210 ✗
7.	REAR END PANEL <i>Dented</i>	\$ 280 ✓
8.	REAR END PANEL TOP COVER <i>Dehnd</i>	\$ 180 ✓
9.	SPARE TYRE COMPARTMENT <i>Repair</i>	\$ 900 ✗
10.	SPARE TYRE COMPARTMENT COVER <i>crumpled.</i>	\$ 180 ✓
11.	FRONT BUMPER <i>Dehnd.</i>	\$ 900 ✓
12.	FRONT BUMPER CHROME GARNISH <i>lt</i>	185 <u>\$ 350</u> ✓
13.	HEADLIGHT - LEFT <i>Crushed</i>	\$ 1200 ✓



JACK CARS

DRIVE WITH ASSURANCE

14.	HEADLIGHT - RIGHT <i>replaced</i>	\$ 1200	✓
15.	RIGHT TAIL LAMP - OUTER	\$ 540	+
16.	RIGHT TAIL LAMP - INNER	\$ 730	+
17.	LEFT TAIL LAMP - OUTER	\$ 540	+
18.	LEFT TAIL LAMP - INNER	\$ 730	+
19.	BOOT LOCK - UPPER <i>James</i> <i>6963</i> <i>188</i>	\$ 320	-
20.	BOOT LOCK - LOWER <i>He m</i> <i>lend 20%: \$570.40</i>	\$ 180	+
SPECIAL NETT			
1.	FRONT NUMBER PLATE & COVER <i>Bert</i>	\$ 65	-
2.	REAR NUMBER PLATE & COVER <i>He m</i>	\$ 65	+
3.	CLIPS, RIVETS & SCREWS <i>He m</i>	\$ 100	<i>60</i>
4.	TOW HOOK COVER - REAR <i>He m</i>	\$ 75	+
5.	"FREED" EMBLEM <i>He m</i>	\$ 90	✓
6.	"HYBRID" EMBLEM	\$ 65	✓
7.	<i>Hyundai</i> "TOYOTA" EMBLEM <i>He m</i>	\$ 90	<i>50</i>
8.	WINDSCREEN SEALANT <i>He m</i>	\$ 100	<i>60</i>
9.	REAR END PANEL SEALANT <i>He m</i>	\$ 100	<i>60</i>
10.	WINDSCREEN WEATHERSTRIP <i>He m</i>	\$ 100	+
LABOUR			



JACK CARS

DRIVE WITH ASSURANCE

1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	\$ 1500 <i>1000</i>
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	\$ 2500 <i>1300</i>
3.	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	\$ 350 <i>100</i>
4.	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	\$ 220 <i>80</i>
5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	\$ 280 <i>80</i>
6.	TO REMOVE & REINSTALL SENSORS	\$ 200 <i>50</i>
7.	TO REMOVE & REINSTALL REAR WINDSCREEN	\$ 200 <i>120</i>
8.	ANTI RUST TREATMENT	\$ 200 <i>60</i>
	PARTS - 20%:	\$ 8,872
	SPECIAL NETT :	\$ 850
	LABOUR :	\$ 5,450
	TOTAL :	\$ 15,172
	LUMP SUM :	\$ 12,137.60
	7% GST :	\$ 849.63
	GRAND TOTAL :	\$ 12,987.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li

8/2, 4/5 23/06/22.

09 Days.

total: 8810.40

w/s: 7050. ✓