

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

			196K GST Keg. No			
		Affiliated to Federation Internation	nale Des Experts E	n Automo	bile CS3/I	LPC2200394
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPCZZ	ປປວອ <del>4ອ/</del> ⊑ເ <u></u> yວ
	300 BEACH ROAD #17-04/07 THE CO	ONCOURSESINGAPORE 199555		Date:	2 <del>7/04/202</del> 2	30/05/2022
				Code:	LPC2	
	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YP 9782L	Veh. Inspected	d	YP 8353Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VC05/025715	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		27/04/2022	30/05/2022
		Vehicle Partic	culars & Condit	ion		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
		Conditi	ons of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
		Description	on of Damages			
5.		Genera	I Information			
	Accident Date	22/04/2022	Inspection Dat	te	27/04/2022	
	Survey held at	KOH KOCK LEONG ENTERPRI	SE PL			
		NO.4 TUAS DRIVE 2 SINGAPORE 638638				
a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					