

ASS. REC. BY:

REF:

ASM / 22 005111/kg3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

S2M042KZ

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

GIA not ready

01/06/22@3.04pm revised to Cynthia Loh via Smart Claims.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

: Firms

: Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Veh No:

Gek 2771M

Yr Regn:

03, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy

1-Hacc

c.c

2734

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

59207

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GD17201 - 2011046

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

Dun

195R15X8

R:

Rf

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

B.5

6

mm

L/Bal.

6

mm

L/Bal.

Dun

8

mm

D.O.A.

28/5/12

D.O.I.

31/3/2022

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

NIS Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date: 30 / 05 / 2022

ESTIMATE COSTS OF REPAIR

M/s Hock Yu Seng Funeral Sercives

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

*Not Authorised
C/Sing &
Mummy After Paim
7days*

Dear Sir / Madam ,

Vehicle no. : GBK 2771 M - Toyota Hiace
Accident date : 28 / 05 / 2022

Quantity	Descriptions	Amount (S\$)
----------	--------------	----------------

1	1 pc	n/s step panel	\$	<i>K</i>	1,245.60	<i>X</i>
2	1 pc	n/s step panel garnish	\$	<i>Sm</i>	703.40	<i>X</i>
3	1 pc	n/s rear fender	\$	<i>Sm</i>	1,321.80	<i>✓</i>
4	1 pc	n/s rear fender inner pillar	\$	<i>K</i>	1,370.90	<i>X</i>
5	1 pc	n/s rear fender centre roller rail	\$	<i>Sm</i>	494.80	<i>X</i>
6	1 pc	n/s rear fender inner garnish (inner twin board)	\$	<i>Sm</i>	158.60	<i>X</i>
7	1 pc	n/s rear mud flap	\$	<i>Sm</i>	105.60	<i>X</i>
8	1 pc	n/s rear shock absorber	\$	<i>Sm</i>	113.70	<i>X</i>
9	1 pc	n/s rear driver shaft	\$	<i>n/s</i>	858.40	<i>X</i>
10	1 pc	n/s sliding door inner lock sensor	\$	<i>Sm</i>	1,049.14	<i>X</i>
11	1 pc	n/s sliding door rubber (near door)	\$	<i>Sm</i>	1,067.00	<i>X</i>
12	1 pc	n/s sliding door rubber (near body)	\$		370.40	<i>?</i>
13	1 pc	n/s sliding door top garnish	\$	<i>Sm</i>	271.90	<i>X</i>
14	1 pc	n/s sliding door motor	\$		1,919.40	<i>?</i>
15	1 pc	n/s sliding door glass	\$	<i>Sm</i>	685.50	<i>X</i>
16	1 pc	n/s sliding door inner trim board	\$	<i>Sm</i>	536.80	<i>X</i>
17	1 pc	n/s sliding door top roller	\$	<i>Sm</i>	98.50	<i>X</i>
18	1 pc	n/s sliding door centre roller	\$	<i>Sm</i>	161.60	<i>X</i>
19	1 pc	n/s sliding door bottom roller	\$	<i>Sm</i>	320.40	<i>X</i>
20	1 pc	n/s sliding door centre lock	\$		804.70	<i>?</i>
21	1 pc	n/s sliding door inner lock (front)	\$	<i>K</i>	189.60	<i>X</i>
22	1 pc	n/s sliding door inner lock (rear)	\$	<i>K</i>	595.50	<i>X</i>
23	1 pc	n/s rear wheel cap	\$	<i>Sm</i>	175.90	<i>✓</i>
24	1 pc	n/s rear wheel bearing	\$		150.70	<i>?</i>
Balance C/FD				\$	14,769.84	

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

		Balance B/FD (GBK 2771 M)	\$ 14,769.84
25	1 pc	n/s rear wheel rim	\$ 365.40 7
			\$ 15,135.24
		Less 25%	\$ 3,783.81
			\$ 11,351.43
26	1 pc	n/s rear wheel tyre	\$ 285.00 sn X
27	1 pc	body lettering	(Bill) \$ 850.00 sn 7
			\$ 12,486.43
		Labour charges	\$ 2,800.00 800
		To putty and spray painting	\$ 1,200.00 600
		Re-seal anti rust	\$ 250.00 60
		To check, replace, repair wiring ,reset fault code	\$ 120.00 X
		Remove and refix undercarriage	\$ 450.00 7
		To check wheel alignment	\$ 120.00 60
		Remove and refix interior wooden panel	\$ 350.00 X
		To transfer n/s sliding door	\$ 160.00 60
			\$ 17,936.43
		Plus : 7% GST	\$ 1,255.55
		Sub_Total	\$ 19,191.98

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: