



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
NTUC INCOME INSURANCE CO-OPERATIVE LTD C/O LEGAL SOLUTIONS LLC 80 RAFFLES PLACE #44-01 UOB PLAZA 1 SINGAPORE 048624		Ref: CS/LAW22005132/Gce2 Date: 20/07/2022 Code: INC3	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SDK 6516J	Veh. Inspected	SLP 9803P
Policy No.		Coverage (\$)	0.00
Claim No.	LIH/974893/NTUC	Excess (\$)	0.00
Assign From	LIM HUI YING	Assign Date	26/05/2022
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0154500	Colour	BLUE
Odometer	92863 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	GOODYEAR	6 mm
L/H Front Tyre	205/60 R16	GOODYEAR	6 mm
R/H Rear Tyre	205/60 R16	GOODYEAR	6 mm
L/H Rear Tyre	205/60 R16	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	15/01/2019	Inspection Date	01/07/2022
Survey held at	18 SENANG CRESCENT SINGAPORE 416591		
Repairer	6 SPEED AUTOWERKZ PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	