



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 8708A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,510.00	1,510.00
1	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE HOLDER @\$59.00 (CONSISTENT)	NECESSARY	118.00	118.00
1	REAR BUMPER LOWER GARNISH (CONSISTENT)	DEFORMED	336.00	336.00
1	REAR BUMPER LOWER GARNISH CHROME MOULDING (CONSISTENT)	CUT	258.00	258.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	DENTED	764.00	764.00
1	REAR BUMPER CENTRE GUIDE (CONSISTENT)	CRACKED	185.00	185.00
2	REAR BUMPER EXHAUST CHROME PIPE @\$266.00 (CONSISTENT)	DENTED	532.00	532.00
1	REAR BUMPER LOWER KICK SENSOR BRACKET (CONSISTENT)	DAMAGED	102.00	102.00
2	REAR BUMPER LOWER SIDE BRACKET @\$69.00 (CONSISTENT)	DAMAGED	138.00	138.00
4	REVERSE SENSOR @\$250.00 (CONSISTENT)	DAMAGED (2 PIECES ONLY)	1,000.00	500.00
2	TAILLAMP @\$645.00 (CONSISTENT)	NOT NECESSARY	1,290.00	-
2	TAILLAMP BRACKET @\$75.00 (CONSISTENT)	NOT NECESSARY	150.00	-
	LESS 10% DISCOUNT		-	-449.30
			6,433.00	4,043.70
<u>LABOUR</u>				
	PANEL BEATING.		500.00	300.00
	SPRAY PAINTING.		400.00	250.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO PERFORM DIAGNOSTIC TEST.	NOT NECESSARY	200.00	-
			1,250.00	630.00
GRAND TOTAL			7,683.00	4,673.70



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00
---	--	--	-----------------

Report Ref No. CS/ASM22005134/Avcm4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.