

ASS. REL. BY: Taufan

REF:

CS/TM1220051361TqC**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TPWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. M2202756

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHR2451M Yr Regn: 2018 / Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai ioniq c.c. 1580Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 367051 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCB51CVKH114874

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: W / S/Rim / STD A/Rim orTyre Size: F: 195 / 65 R15R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 31/5/22Survey held at Conquest Agency

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

01/06/22 @ 3.51pm revised to Fiona Gan via Merimen.

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.L. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

(Jumani)
Yusuf

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	30/05/2022
Vehicle Reg. No.:	SHB2451M	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	18/10/2018
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEJU111406	Chassis No:	KMHC851CVKU114874
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,758.60
Miscellaneous Items	11.00
Labour	800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,569.60
+ GST 7.00% (S\$)	179.87
Nett Amount (S\$)	2,749.47

This claim is handled by: JUMANI BIN MASUDIN

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 30 May 2022)

Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
--------	-----	--

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHB2451M/30/05/2022 14:21

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	<i>Ry</i> *459.40 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	<i>nee</i> *22.00 FL
3	1		*REAR BUMPER MAT	0.00	0.00	<i>x</i> *50.00 F
4	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	<i>cur</i> *451.25 FL
5	1		*REAR BUMPER CENTRE LOWER MOULDING	20.00	0.00	<i>?</i> *155.00 FL
6	1		*REAR BUMPER TOW COVER	20.00	0.00	<i>de</i> *98.80 FL
7	1		*REAR NUMBER PLATE	0.00	0.00	<i>Cur</i> *50.00 F
8	1		*REAR BUMPER BEAM	20.00	0.00	<i>?</i> *394.80 FL
9	1		*REAR FOG LAMP	20.00	0.00	<i>?</i> *201.50 FL
10	1		*ANTENNA ASSY - SMARTK	20.00	0.00	<i>?</i> *40.50 FL
11	1		*ADVERTISEMENT LOGO - FENDER	0.00	0.00	<i>nee</i> *200.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,123.25
- List Item Discount on L Items (S\$)	364.65

Total Parts (S\$)	1,758.60
--------------------------	-----------------

ComfortDelGro Engineering Pte Ltd/SHB2451M/30/05/2022 14:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

350

400.00

2 SPRAYPAINT

New

250

300.00

3 CHECK WIRING

New

4

50.00

4 REMOVE/REFRIG REVERSE SENSOR

New

30

50.00

Gross Labour Cost (\$\$)

800.00

ComfortDelGro Engineering Pte Ltd/SHB2451M/30/05/2022 14:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97445749
 Sup' 31/5/22 @ 4/1m
 02 days
 1/3 Resurvey after repair
 tanpin@lkkauto.com.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 30.05.2022 13:33

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:


JC NO.305517914

TOMER		REGN NO.: SHB2451M	MILEAGE
AS	CITYCAB PTE LTD	MAKE: HYUNDAI	FUEL E.....1/2.....F
TOMER NO.	7010070	MODEL IONIQ(G2)	DATE/TIME IN 30.05.2022 09:30
RESS	383 SIN MING DRIVE	YR OF MANU. 18.10.2018	TARGET DATE
	Singapore SINGAPORE 575717	CHASSIS CODE KMHC851CVKU114874	COMPLETION DATE/TIME:
(R)	65551188		
(P)			
OUNT CARD NO.			

JOB DESCRIPTION

ccident Date: 30.05.2022
ATURE: 3P.30.05.2022

/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: **SHB2451M**

JU TOKIO

Vehicle No.:

SHB2451M

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard