

ASS. REF. BY: T. J. H.

REF: CS/FC122005138/Tvy3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: YN 3237U

Policy No. _____

Claims No. D22001638MFCV

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: 964K.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP'

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 9649169 Y Yr Regn: 2018, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace c.c. 2982

Colour: 124232 A/C: Insured / Std / NI / NA

Sp. Reading: Silver T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STEHT02P400 245654

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/R15

R: 21

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 27/5/2022 D.O.I. 31/5/22 @ 12pm

Survey held at Green Forest

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	GIA in Views
18/7/22	LS \$4100 confirmed by email (red 10,477.20, 71%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 18/7/22-typist

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Rep. Format: TP

Lump Sum / L.S. / \$4100

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

31st MAY 2022

FUDA FOOD PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

Accident date: 27.5.22

Estimated repair cost for vehicle no: GBH9169Y Toyota Hiace

S/n	Qty	Items	U/price	Amount
1	1	Rear windscreen		\$1,250.00 X
2	1	boot lid windscreen rubber		\$358.00 nei ✓
3	1	windscreen seal		\$380.00 nei ✓
4	1	Rear boot lid		\$2,500.00 bt ✓
5	1	Rear boot lid HIACE logo		\$55.00 nei ✓
6	1	Rear boot lid Emble logo		\$75.00 nei ✓
7	1	Rear boot lid 70Km/h logo		\$20.00 nei ✓
8	1	Rear boot lid TOYOTA logo		\$20.10 nei ✓
9	1	Rear boot lid center moulding		\$221.00 bt ✓
10	2	Rear boot lid hinges	\$185.20	\$370.40 X
11	2	Rear boot lid absorber	\$229.10	\$458.20 X
12	1	Rear boot lid inner lock		\$385.20 bt ✓
13	1	Rear boot lid inner trim board		\$550.00 de ✓
14	10	Rear boot lid inner clips	\$12.90	\$129.00 30 nei ✓
15	1	Rear boot lid inner rubber		\$329.10 int ✓
16	2	Rear boot lid number plate lamp	\$83.20	\$166.40 X
17	1	Rear boot lid number plate		\$50.00 X
18	2	Rear tail lamp	\$425.00	\$850.00 LH X RH int ✓
19	2	Rear tail lamp lower garnish	\$252.20	\$504.40 X
20	2	Rear tail lamp lower garnish bracket	\$131.75	\$263.50 X
21	1	Rear bumper		\$825.20 crn ✓
22	2	Rear bumper side bracket	\$215.20	\$430.40 X
23	1	Rear bumper reverse sensor		\$350.00 nw ✓ 200
24	6	Rear bumper clips	\$12.90	\$77.40 1 BC ✓ 30
25	1	Rear end panel		\$812.20 bt ✓
26	1	end panel top garnish		\$288.50 X
27	1	Rear spare tire bracket		\$358.20 X
28	1	Rear step panel		\$795.00 X

Subtotal :- \$12,077.20

Labour charges

To remove & re-fix rear windscreen	\$120.00 ✓
Gum	\$50.00 40 hrs ✓
To remove & re-fix rear reverse sensor	\$100.00 30 hrs ✓
To remove & re-fix rear cushion	\$150.00 50 hrs ✓
To check wiring system	\$80.00 30 hrs ✓
Panel beating	\$1,000.00 700
Spray painting	\$1,000.00 700

Subtotal :- \$2,500.00

Total:- \$14,577.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749
WP 21/5/22
L/S Reaney after repair
taufik@lkkauto.com
6 days