

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

FUDA FOOD PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

31st MAY 2022

Accident date: 27.5.22

Estimated repair cost for vehicle no: GBH9169Y Toyota Hiace

S/n	Qty	Items	U/price	Amount	
1	1	Rear windscreen		\$1,250.00	X nn
2	1	boot lid windscreen rubber		\$358.00	294 hel
3	1	windscreen seal		\$380.00	80 SN hel
4	1	Rear boot lid		\$2,500.00	1754 bt
5	1	Rear boot lid HIACE logo		\$55.00	hel
6	1	Rear boot lid Emble logo		\$75.00	hel
7	1	Rear boot lid 70Km/h logo		\$20.00	hel
8	1	Rear boot lid TOYOTA logo		\$20.10	hel
9	1	Rear boot lid center moulding		\$221.00	bt
10	2	Rear boot lid hinges	\$185.20	\$370.40	X nn
11	2	Rear boot lid absorber	\$229.10	\$458.20	X nn
12	1	Rear boot lid inner lock		\$385.20	257.60 bt
13	1	Rear boot lid inner trim board		\$550.00	267.60 de
14	10	Rear boot lid inner clips	\$12.90	\$129.00	300 hel SN
15	1	Rear boot lid inner rubber		\$329.10	296.25 cut
16	2	Rear boot lid number plate lamp	\$83.20	\$166.40	X nn
17	1	Rear boot lid number plate		\$50.00	X nn
18	2	Rear tail lamp	\$425.00	\$850.00	300.80 24X RH cut
19	2	Rear tail lamp lower garnish	\$252.20	\$504.40	X nn
20	2	Rear tail lamp lower garnish bracket	\$131.75	\$263.50	X nn
21	1	Rear bumper		\$825.20	598 cut
22	2	Rear bumper side bracket	\$215.20	\$430.40	X nn
23	1	Rear bumper reverse sensor		\$350.00	nn 200 SN
24	6	Rear bumper clips	\$12.90	\$77.40	2 BC 30 SN
25	1	Rear end panel		\$812.20	bt R 18/7/22 Taufikh
26	1	end panel top garnish		\$288.50	X
27	1	Rear spare tire bracket		\$358.20	X nn
28	1	Rear step panel		\$795.00	X

Subtotal :- \$12,077.20

4159.35
25% 3119.51
SN 340

Labour charges

To remove & re-fix rear windscreen

\$120.00 ✓

Gum

\$50.00 40 hrs ✓

To remove & re-fix rear reverse sensor

\$100.00 30 hrs ✓

To remove & re-fix rear cushion

\$150.00 50 hrs ✓

To check wiring system

\$80.00 30 hrs ✓

Panel beating

\$1,000.00 700

Spray painting

\$1,000.00 700

1670

Subtotal :- \$2,500.00

Total:- \$14,577.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749

WP 21/5/22

4/s Resurvey after repair

taufik@lkkauto.com

6 days

3119.51

340

1670

5129.51

4/s \$4100

6 days #