



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22005140/Tvy3m4 Date: 19/04/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SG 5580Y	Veh. Inspected	SMS 8118M
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/05/22/5044	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	31/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	B.M.W. 740LI	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WBA7E22050G764357	Colour	BLUE
	Odometer	67068 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	245/45 R19	CONTINENTAL	6 mm
	L/H Front Tyre	245/45 R19	CONTINENTAL	6 mm
	R/H Rear Tyre	245/45 R19	CONTINENTAL	6 mm
	L/H Rear Tyre	245/45 R19	CONTINENTAL	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	26/05/2022	Inspection Date	31/05/2022
	Survey held at	DETAIL LAB BLK 8 KAKI BUKIT AVE 4 #02-03/04 PREMIER @ KB SINGAPORE 415875		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	