

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SJV 903K  
at Workshop m/s ZOOM  
of \_\_\_\_\_  
Insured: SKL 8318M  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SJV 903K Yr Regn: 11/01/10  
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA  
Make: Toyota wish 18XA c.c. 1797  
Colour: 3/blk A/C: Insured / Std / NI / NA  
Sp. Reading: 208102 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: 26E20 0013815  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: in order / Jammed / Leaked / Burnt or  
Brake: in order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 195/65R15  
R: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front 6 mm Rear 6 mm  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 29/05/22 D.O.I. 31/05/22  
Survey held at \_\_\_\_\_

Bal. or Market Value: \$55k.  
IDAC Accident Rpt: Consistent?: Yes or No  
GIA / PR Seen: Consistent?: Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
nil Pnt, nil body  
The UIC / Chassis frame / Body Structure affected due to collision.

CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: LIA 527694  
Vehicle: 6682 IN / OUT

Date / Time Action / Instruction  
30/7/22. 2278k.  
COE unbr 31-05-2022

6/6/22 1/5 @ 2400 informed E1.1

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
1) \_\_\_\_\_  
Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
\_\_\_\_\_ S + RS \_\_\_\_\_ SI  
Photos  
Others  
TOTAL

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$) \_\_\_\_\_ )



# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

LKK Auto Consultants henceforth the Repairer of the following: **Tel: 9450 7920**

\* **zoomautowerks@gmail.com**

- To resurvey before final spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation **31 May 2022**
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not authorized  
re  
31/5/22  
1/5 # 2400  
3 days*

REG NO. : SJV 903 K  
MAKE/MODEL : TOYOTA WISH

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION		AMT(\$)
<b>LIST ITEMS</b>			
1	Front headlamp - HID	1 1	\$ 2,313.10 X
1	Front bumper	De/Toon 761.10	\$ 881.25 /
1	Front bumper side retainer	1 1	\$ 48.85 X
1	Front fender -LH	20	\$ 788.51 /
1	Front fender inner shield	Toon	\$ 161.25 /
1	Front door -LH	R	\$ 1,296.65 X
1	Front door glass outer moulding	1 1	\$ 126.50 X
2	Front door hinges	1 1	\$ 157.70 X
1	Front door lock	1 1	\$ 280.95 X
1	Front door outer handle	1 1	\$ 175.20 X
1	Front door regulator	1 1	\$ 286.50 X
1	Front door regulator motor	1 1	\$ 381.60 X
1	Front door rubber	1 1	\$ 124.45 X
1	Rocker panel side skirt -LH	2	\$ 650.00 X
			\$ 7,672.51
		Less 25%	\$ 1,918.13
			\$ 5,754.38

<b>SPECIAL NETT ITEMS</b>			
1	Front bumper clip (1 set)	1 set	\$ 60.00 50
1	Front fender inner shield clip (1 set)	1 set	\$ 35.00 /
1	Front tyre	1 1	\$ 400.00 X
1	Front wheel rim	cut	\$ 800.00 400
1	Front door black tape	1 1	\$ 120.00 X
			\$ 1,415.00

S/N	LABOUR CHARGES		AMT(\$)
1	To check wiring and reset headlamps focusing.		\$ 80.00 20
2	To conduct wheel alignment.		\$ 150.00 60
3	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	1 1	\$ 200.00 X
4	To apply undercoating.		\$ 150.00 30
5	Panel beating.		\$ 1,600.00 450
6	To re-spray painting on the affected areas.		\$ 1,500.00 700
			\$ 3,680.00

GRAND TOTAL :

*1710.88  
252  
1783.14  
485  
1260*

**\$ 10,849.38**