

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592

Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

User ID PohSuan

	Section A - Accident Details						
Registration Number	SHC4873K						
Case Reference Number	TAX/05/22/2082						
Registration Date	5/2/2016						
Company Type	Strides Taxi Pte Ltd						
Make	ТОУОТА						
Model	PRIUS						
Name of Driver	TOH CHIN KHOON						
Type of Accident	Head to Rear						
Accident Date and Time	30/5/2022 10:30 AM						
Accident Reported Date and Time	30/5/2022 12:43 PM						
Is Surveyor Required?	Yes						
Survey by							
Vehicle is Towed Back?	No						
Towed Back Date and Time							
Replacement Vehicle issued?	No						
Job Card Number	24115156						
Special Instruction to ARC,if	TP/ REAR PORTION						
Prepared Date and Time	30/5/2022 1:34 PM						
Chassis Number							
Mileage							
Work Shop							
Repair Completion Date and Time							

	Section B - Summary of Re	epair Estimates					
Summary of Repair Estimates							
	Quotation from ARC	Adjusted by Surveyor, if applicable					
Total Labour Cost	\$676.00	\$200.00					
Total Spray Cost	\$738.00	\$200.00					
Total Spare Part Cost	\$2,002.38	\$287.76					
Total Other Cost	\$500.00	\$50.00					
TOTAL COST	\$3,916.38	\$737.76					
Lump Sum Total	\$3,900.00	\$750.00 (L/S)					
Number of Repair Days	4.0	2.0					
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / Sompo					
ARC / Surveyor Sign Off Date	31/05/2022 5:39 PM	31/05/2022 1:13 PM					
Signature		- Jank					
Remarks		LUMP SUM REPAIR / AFTER PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HF : 9691 0663 / Email : kennethkong@lkkauto.com					



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/06/2022 User ID PohSuan

Section C - Quotation and Accident Invoice Details						
Quotation Number	QN-2206-0121	Invoice Number				
Quotation Date	10.06.2022	Invoice Date				
Invoice Amount		Prepared Date				

Section D - Details of Repair Estimates							
Part 1 - Labour Works							
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable					
TO REPAIR REAR PORTION	\$676.00	\$200.00					
Total Labour \$676.00 \$200.00							

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
ΓO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$738.00	\$200.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$50.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$500.00	\$50.00

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		51442-	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given
		12210							
		58308-	UNDER COVER SUB-ASSY,	0.00	\$514.50	0.00	\$0.00	Replace	Not Given
		47011	RR FLOOR						
		76891-	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Check
		47020							
		76087- 47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
		76088-	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		47020						'	
		52591-	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given
		47021	·						
		52592-	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given
		47021	·						
		52575-	BUMPER SIDE RETAINER	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		47020	RR/RH					ļ .	
		52576-	BUMPER SIDE RETAINER	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		47020	RR/LH					ļ .	
		89997-	ANTENNA,ELECTRICAL	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
		30070	LOWER REAR					ļ .	
		52023-	BUMPER REINFORCEMENT	0.00	\$205.70	0.00	\$0.00	Replace	Not Given
		12240	REAR			1		Ι΄.	
		90467-	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace
		07211				1		Ι΄.	'
		52159-	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		47905				1		Ι΄.	1 .
		52015-	ARM SUB-ASSY. RR	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		47050	BUMPER RH			1		Ι΄.	
		52016-	ARM SUB-ASSY. RR	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		47030	BUMPER LH			1		Ι΄.	
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number: 68662672

Date Generated : 11/06/2022 User ID PohSuan

	1	58307- 47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	Χ
Total					\$3,226.90		\$359.70			

Added Spare Parts / Material Usage After Surveyor Signed off								
Part Number		Stock Number	Part Name	Quantity	List Price \$	Final Price (\$)	ARC Check	Surveyor Check
Total								

		•
	359.70	
	-20%	
	287.76	L/S \$750/-
+	200.00	
+	250.00	
	737.76	