

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	217C
Vehicle Details	
Vehicle No.:	SML2190D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 May 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 ELEGANCE (AUTO)
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1ZR0D49759
Chassis No.:	MR053REH604596629
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,881.00
Original Registration Date:	10 May 2019
First Registration Date:	10 May 2019
Transfer Count:	0
Actual ARF Paid:	\$21,234.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 May 2029
PARF Rebate Amount:	\$15,925.00
Intended COE Rebate Details	
COE Expiry Date:	09 May 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$29,159.00
COE Rebate Amount:	\$20,263.00
Total Rebate Amount:	\$36,188.00

The information contained herein is correct as at 27 May 2022

OK



BIDDED CARPLATE NUMBERS FOR SALE

Find and buy your favourite car plate number here!

START SEARCH NOW!

Post an Advertisement
Sell it yourself! Advertise it at just **\$68 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

05/21 Mercedes-Benz S-Class S450L @ \$505,800 ONLY!

Full Loan Available. 3 Years Agent Warranty. High Trade In Guaranteed.

StarAd

NEW & USED COMMERCIAL VEHICLES

[Save Search](#)

Sort by [Date Posted](#) 20 results/page

11 vehicles

Any Category

Advanced Search

Search

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Toyota Altis	Any	Any	Any	Any	2019	Any	Any	Any	Available
<input type="checkbox"/> Toyota Corolla Altis 1.6A Elegance	\$90,518	\$11,920 /yr	16-Jan-2019	1,598 cc	33,800 km	Sedan	Available	<p>1st/Direct Owner, Excellent Condition. Mainly Being Driven On TPE/MCE To/From Work Because Of Covid 19, So The Road Condition Is Good, Fully Maintained By Toyota Padan Centre. Toyota Altis Elegance Highest Spec Model. No Loan, No GST. Low Mileage, And Low Fue...</p> <p>Posted: 11-Apr-2022</p>	
<input type="checkbox"/> Toyota Corolla Altis 1.6A Elegance	\$88,800	\$11,460 /yr	28-Feb-2019	1,598 cc	89,680 km	Sedan	Available	<p>Buy with confidence with Toyota certified pre owned selection, 145 points certification, approved service history, 5 years/unlimited mileage warranty from date of registration and complimentary servicing inclusive.</p> <p>Borneo Motors (S)</p> <p>Posted: 18-May-2022</p>	
<input type="checkbox"/> Toyota Corolla Altis 1.6A Elegance	\$93,700	\$11,920 /yr	15-May-2019	1,598 cc	28,509 km	Sedan	Available	<p>Fully agent serviced and maintained, warranty from Borneo Motor till 2024, accident free, very well maintained by 1 careful owner, bank loan with attractive interest rate from 1.88%, high loan available too! High trade in offer. Call for a viewing appointment now!</p> <p>Posted: 27-May-2022</p>	
<input type="checkbox"/> Toyota Corolla Altis 1.6A Elegance	\$93,800	\$11,830 /yr	06-Jun-2019	1,598 cc	44,208 km	Sedan	Available	<p>1 Owner, Excellent Condition, 5 Years Warranty, Fully Serviced At Borneo Motor, High Trade Ins Welcome, 90% Flexible Loan Available With Attractive Interest Rate, Call For More Queries Today! Price Are Inclusive Of GST.</p> <p>Tai Huat Automobile</p> <p>Posted: 15-May-2022</p>	
<input type="checkbox"/> Toyota Corolla Altis 1.6A Standard	\$85,800	\$10,750 /yr	17-Jun-2019	1,598 cc	69,000 km	Sedan	Available	<p>Reliable and low maintenance Toyota sedan to own! One of the finest unit your money can buy currently! Full loan available, well maintained by previous owner! Trade in welcome, high price for trade in! Call or WhatsApp for viewing and test drive.</p> <p>Posted: 20-May-2022</p>	
<input type="checkbox"/> Toyota Corolla Altis 1.6A Standard	\$89,800	\$11,240 /yr	22-Jul-2019	1,598 cc	45,723 km	Sedan	Available	<p>No Gimmicks, Cheapest Depreciation Priced Altis 1.6A (Ideal Workhorse For Daily Use). Condition Totally Like New With New Car Feel/Smell Intact. Genuine Mileage Done 45723km! Serviced At Borneo Motors With Proof/5-yrs Warranty. 1 Owner. New Paintwork. Bidd...</p> <p>Lake View Credit Pte Ltd</p> <p>Posted: 26-May-2022</p>	
<input type="checkbox"/> Toyota Corolla Altis 1.6A Elegance	\$96,800	\$11,800 /yr	13-Sep-2019	1,598 cc	-	Sedan	Available	<p>New facelift, original factory paint work, fully service and maintained by Borneo Motors, service promptly, healthy engine, clean and neat. Stylish, spacious, suitable for family usage. Great handling with comfort, low maintenance, fuel efficiency. Best driving pleasure. Bank/in...</p> <p>EDM Cars Pte Ltd</p>	

[Compare](#)

[SHORTLISTED](#)

[HISTORY](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/05/2022 12:17 (SGT)
Date of Accident	27/05/2022 18:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CTE TOWARDS AYE BEFORE BRADDELL RD EXIT LAMP POST NO. 235F
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML2190D
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CAI JIANLING
NRIC No	SXXXX217C
Email Address	TEDCAI@YAHOO.COM
Mobile Phone No	(Phone) +65-85338040
Alternative Phone No	+65-85338040

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	ALTIS
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1364

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA539048/1
Cover Note Number	-

DRIVER

Name of Driver	CAI JIANLING
----------------	--------------

NRIC No	SXXXX217C
Date Of Birth	19/12/1973
Occupation	Indoor
Date Of Driving Pass	02/08/2010
Driving experience	11 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-85338040
Alt. Phone Number	+65-85338040
Email Address	TEDCAI@YAHOO.COM
Address	BLK 332A ANCHORVALE LINK
Address complement	#07-350
Postcode	541332
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON THE STATED DATE AND TIME, I, VEHICLE A (SML2190D) WAS TRAVELLING STRAIGHT ALONG AT THE STATED LOCATION ON LANE 4. AS VEHICLE INFRONT OF ME SLOWED DOWN AND CAME TO A STOP, I FOLLOWED SUIT. SECOND LATER, I FELT A HUGE IMPACT FROM MY REAR PORTION, VEHICLE B (SLF2015X) COLLIDED ONTO THE REAR PORTION OF MY VEHICLE CAUSING ME TO SURGE FORWARD AND COLLIDED ONTO VEHICLE C (SMH5723T).

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF2015X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-

Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMH5723T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	CAI JIANLING
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SML2190D
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time




Witnessed by Reporting Centre Personnel

28 May 2020

Sketch Plan

CTE towards AYE before Braddell Road Exit lamp post no. 235F




Vehicle A - JML 2190P
Vehicle B - SLF2015X
Vehicle C - SMH5723T


Describe Circumstances of the Accident

On the stated date and time, I, vehicle A (SMC24901) was travelling straight along at the stated location on lane 4. As vehicle in front of me slowed down and came to a stop, I followed suit. Second later, I felt a huge impact from my rear portion, vehicle B (SEF 3015X) collided onto the rear portion of my vehicle causing me to surge forwards and collided onto vehicle C (SMH 5723T).

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


28 MAY - 13
Witnessed by Reporting Centre Personnel

C. S. ONG AUTO PTE LTD

Co. Reg. No.: 201408916W

7030, ANG MO KIO AVE 5, #B1-01 NORTHSTAR @ AMK, SINGAPORE 569880

TEL: 6484 1933 | FAX: 6484 1922

E-Mail: csongauto.claims@yahoo.com.sg

To: MSIG
Att: Motor Claims Dept

ACCIDENT INVOLVING SLF2015X [YOUR INSURED] & SML2190D [OUR CLIENT]
ON 27/05/2022.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED REPAIR COSTS FOR SML2190D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	REAR DOOR LH <i>new</i>	\$ 1,858.20	X
1PC	REAR DOOR HANDLE LH <i>new</i>	\$ 189.40	X
1PC	REAR DOOR WINDOW MOULDING LH <i>new</i>	\$ 159.20	X
1PC	REAR DOOR BLACK PLASTIC MOULDING LH <i>new</i>	\$ 99.42	X
1PC	REAR DOOR INNER TRIM BOARD LH <i>new</i> <i>detached</i>	634.00 \$ 892.40	X ✓
1PC	REAR DOOR LOCK LH <i>new</i>	\$ 374.50	X
1PC	REAR DOOR POWER WINDOW MOTOR LH <i>new</i>	\$ 699.92	X
1PC	REAR DOOR WINDOW REGULATOR LH <i>new</i>	\$ 321.91	X
1PC	REAR DOOR WEATHER STRIP OUTER LH <i>new</i>	\$ 284.50	X
1PC	REAR DOOR WEATHER STRIP INNER LH <i>new</i>	\$ 349.85	X
1PC	ROCKER PANEL LH <i>new</i>	\$ 1,421.94	X
2PCS	REAR FENDER RH / LH <i>Detached</i>	939.20 x 2 = 1878.40 \$ 2,194.52	✓
1 2PCS	REAR FENDER INNER PANEL LH <i>new</i>	395.70 \$ 787.00	✓
1PC	REAR FENDER WHEEL HOUSING LH <i>new</i>	839.70 \$ 2,456.00	✓
1PC	REAR FENDER INNER SHIELD LH / RH <i>detached</i>	124.90 \$ 378.42	✓
2PCS	REAR FENDER INNER TRIM RH / LH <i>detached</i>	180.30 x 2 = 360.60 \$ 798.50	798.50 ✓
1PC	REAR FENDER AIR DUCT LH <i>broken</i>	\$ 123.90	✓
2PCS	REAR FENDER INNER TOP TRIM LH / RH <i>mostly broken</i>	360.60 \$ 1,546.00	✓
1PC	ROOFTOP LINING <i>crumpled</i>	1120.00 \$ 2,541.00	✓
1PC	REAR WHEEL HOUSING LH <i>MS</i>	\$ 1,984.51	X
1PC	REAR WINDSCREEN GLASS <i>shattered</i>	1240.00 \$ 1,765.00	✓
1PC	REAR WINDSCREEN MOULDING <i>new</i>	163.00 \$ 321.90	✓
1PC	REAR SPEAKER PANEL <i>Detached</i>	1047.30 \$ 2,478.00	✓
1PC	REAR SPEAKER PANEL TOP BOARD <i>cut 1st</i>	\$ 953.00	✓
1PC	BOOTLID <i>new</i>	374.45 756.16 \$ 1,785.26	✓
2PCS	BOOTLID LAMP LH / RH @ \$689.29 EACH <i>broken</i>	748.90 \$ 1,378.58	✓
1PC	BOOTLID LOGO <i>new</i>	80.00 \$ 129.85	✓
1PC	BOOTLID COROLLA EMBLEM <i>new</i>	58.60 \$ 132.45	✓
1PC	BOOTLID ALTIS EMBLEM <i>new</i>	65.20 \$ 124.19	✓
2PCS	BOOTLID HINGE LH / RH @ \$239.10 EACH <i>1st 155.30 x 2 =</i>	310.60 \$ 478.20	✓

11698.40 //

1PC	BOOTLID CENTER GARNISH <i>crack/cut</i>	255.60	\$ 465.00	✓
1PC	BOOTLID LOCK <i>bst</i>	124.00	\$ 389.91	✓
1PC	BOOTLID LOCK CATCH <i>bst</i>	87.00	\$ 123.96	✓
1PC	BOOTLID WEATHER STRIP <i>damaged</i>	195.00	\$ 395.61	✓
1PC	BOOTLID INNER TRIMBOARD <i>crumpled</i>	285.30	\$ 426.00	✓
1 SET	BOOTLID INNER TRIMBOARD CLIPS <i>h/c</i>	15.00	\$ 50.00	✓
1PC	REAR BUMPER <i>Dent</i>	573.30	\$ 974.30	✓
2PCS	REAR BUMPER SIDE RETAINER LH / RH <i>broken h/s</i>		\$ 206.98	✓ X
2PCS	REAR BUMPER SIDE RETAINER LONG LH / RH <i>broken h/s o/s crack</i>		\$ 234.39	✓ 185.00
1PC	REAR BUMPER REINFORCEMENT <i>Dent</i>	395.10	\$ 689.00	✓
2PCS	REAR BUMPER REINFORCEMENT BRACKET LH / RH <i>nt / Dam</i>		\$ 256.00	✓
2PCS	REAR BUMPER REFLECTOR LH / RH <i>o/s h/c h/s broken</i>	68.50	\$ 198.74	✓
1PC	REAR END PANEL <i>Pnc</i>	695.00	\$ 1,128.71	✓
1PC	REAR END PANEL TOP GARNISH <i>damaged</i>	266.90	\$ 348.75	✓
1PC	REAR KEYLESS BUZZER <i>h/c</i>		\$ 472.50	X
1PC	SPARE TYRE PANEL <i>Pnc</i>	896.50	\$ 1,645.33	✓
1PC	SPARE TYRE PANEL TOP BOARD <i>crumpled</i>	288.50	\$ 532.98	✓
1PC	SPARE TYRE PANEL TOP TRAY <i>nt</i>		\$ 319.25	X
1PC	SPARE TYRE LOCK SCREW <i>src</i>		\$ 132.23	X
2PCS	SPARE TYRE PANEL SIDE PANEL LH / RH <i>h/s Pnc o/s h/c 145.00</i>		\$ 621.56	✓
1PC	REAR RIM LH <i>h/c</i>		\$ 2,140.29	X
1PC	REAR WHEEL BEARING LH / RH <i>h/c</i>		\$ 339.40	X
1PC	REAR WHEEL BEARING HUB LH / RH <i>h/c</i>		\$ 401.51	X
1PC	REAR ABSORBER LH / RH <i>h/c</i>		\$ 798.50	X
1PC	REAR AXLE BEAM <i>distorted</i>	1815.12	\$ 2,495.25	✓
1PC	REAR EXHAUST PIPE <i>h/c Dent h/s src</i>	794.50	\$ 1,674.51	X X
1PC	REAR EXHAUST MOUNTING <i>h/c</i>		\$ 139.40	X
1PC	REAR EXHAUST HEAT SHIELD <i>h/c bst</i>	171.80	\$ 249.81	✓
2PCS	TAIL LAMP LH / RH <i>broken</i>	381.90 x 2 = 763.80	\$ 2,091.00	✓
2PCS	TAIL LAMP PANEL LH / RH <i>Dent h/s o/s rep</i>	244.50	\$ 996.80	✓
2PCS	TAIL LAMP LOWER BRACKET LH / RH <i>src o/s mainly broken h/s</i>		\$ 497.42	✓ 177.40
1PC	BONNET <i>Bent / Dent</i>	1058.90 <i>distorted</i>	\$ 1,280.90	✓
1PC	BONNET INSULATOR <i>crumpled</i>	265.80	\$ 330.40	✓
1PC	BONNET SEAL <i>src</i>		\$ 249.10	X
1PC	HEAD LAMP LH / RH @ \$1,180.10 EACH <i>broken</i>		\$ 2,360.20	✓
1PC	HEAD LAMP LOWER BRACKET LH / RH @ \$102.80 EACH <i>h/c</i>		\$ 205.60	X
1PC	HEAD LAMP WIRE HARNESS <i>h/c</i>		\$ 992.00	X
1PC	FRONT GRILLE <i>crack</i>		\$ 314.00	✓
1PC	FRONT GRILLE OUTER CHROME <i>crack</i>	238.00	\$ 432.00	✓
1PC	FRONT GRILLE LOGO <i>broken</i>	78.00	\$ 144.20	✓
1PC	FRONT BUMPER <i>tom</i>	531.00	\$ 701.01	✓
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$87.00 EACH <i>crack / broken</i>		\$ 174.00	✓
1PC	FRONT BUMPER REINFORCEMENT BAR <i>Dent</i>	386.60	\$ 792.00	✓
1PC	FRONT BUMPER SPONGE <i>tom</i>	178.20	\$ 223.00	✓
1PC	FRONT BUMPER FOG LAMP GARNISH LH / RH @ \$289.78 EACH <i>h/s h/c</i>		\$ 579.56	✓ 119.80
1PC	FRONT BUMPER FOG LAMP LH / RH @ \$289.78 EACH <i>h/c o/s h/c</i>		\$ 579.56	X
1PC	FRONT BUMPER FOG LAMP SIDE GARNISH LH / RH @ \$199.82 EACH <i>h/c</i>		\$ 399.64	X
1PC	FRONT BUMPER FOG LAMP WIRE HARNESS <i>h/c</i>		\$ 930.00	X

13,608.82

1PC	FRONT BUMPER LOWER GRILLE <i>cut</i>	188.00	\$ 399.17	✓
1PC	FRONT BUMPER UNDER COVER <i>HN</i>		\$ 310.82	X
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$87.00 EACH <i>replaced</i>		\$ 174.00	X
1PC	FRONT BUMPER SPONGE <i>replaced</i>		\$ 223.00	X
1PC	FRONT REINFORCEMENT BAR <i>replaced</i>		\$ 792.00	X
1PC	FRONT SUPPORT PANEL <i>st</i>	997.20	\$ 1,080.29	✓
1PC	FRONT BRACE PANEL <i>st</i>		\$ 129.80	✓
1PC	A/C CONDENSOR <i>st / painted</i>		\$ 1,283.40	✓
1PC	A/C CONDENSOR SUCTION PIPE <i>HN</i>		\$ 519.20	X
1PC	A/C CONDENSOR DISCHARGE PIPE <i>HN</i>		\$ 601.90	X
1PC	A/C CONDENSER LIQUID PIPE <i>HN</i>		\$ 317.00	X
1PC	A/C CONDENSER FAN COWLING <i>st broken HS</i>		\$ 345.00	✓ X
1PC	A/C CONDENSER FAN BLADE <i>damage HS</i>		\$ 109.29	✓ X
1PC	A/C CONDENSER FAN MOTOR <i>Don HS</i>		\$ 401.92	✓ X
1PC	RADIATOR ASSY <i>st / painted</i>		\$ 1,529.40	✓
2PCS	RADIATOR SIDE GARNISH LH / RH <i>st money broken</i>	213.80	\$ 317.00	✓
1PC	RADIATOR TOP MOUNTING <i>HN</i>	106.90 x2	\$ 118.30	X
1PC	RADIATOR FAN MOTOR <i>st HS Don</i>		\$ 401.92	X ✓
1PC	RADIATOR FAN BLADE <i>HS damaged</i>		\$ 109.29	X ✓
1PC	RADIATOR FAN COWLING <i>HS broken</i>		\$ 331.80	X ✓
1PC	RADIATOR SPARE TANK <i>money returned / st</i>	125.30	\$ 175.00	✓
2PCS	FRONT FENDER LH / RH <i>Revised</i>		\$ 1,284.45	✓
2PCS	FRONT FENDER INNER SHIELD LH / RH <i>HN</i>		\$ 425.00	X
1 SET	FRONT FENDER INNER SHIELD CLIPS LH / RH <i>HN</i>		\$ 100.00	X
1PC	BATTERY TRAY <i>HN</i>		\$ 187.28	X
6PC	ABS PUMP <i>HN</i>		\$ 6,512.00	X
1PC	ABS PUMP BRACKET <i>HN</i>		\$ 934.00	X
1PC	FUSE BOX TOP <i>HN</i>		\$ 153.95	X
1PC	FUSE BOX CENTER <i>HN</i>	6,594.36	\$ 534.39	X
1PC	FUSE BOX BOTTOM <i>HN</i>		\$ 239.34	X

31,901.50
25% 23926.18

PARTS SUM: \$ 81,139.69
PARTS LESS 25%: \$ 20,284.92
PARTS TOTAL: \$ 60,854.77

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 1 PC TYRE <i>HN</i>	\$ 400.00	X
*	TO SUPPLY REAR FENDER SEALANT <i>HN</i>	\$ 80.00	25/-
*	TO SUPPLY REAR WINDSCREEN SEALANT <i>HN</i>	\$ 80.00	40/-
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL <i>HN</i>	\$ 30.00	X
*	TO SUPPLY ROCKER PANEL SEALANT <i>HN</i>	\$ 120.00	X
*	TO SUPPLY SPARE TYRE PANEL SEALANT <i>HN</i>	\$ 50.00	25/-
*	TO SUPPLY REAR DOOR INNER TRIM CLIPS <i>HN</i>	\$ 50.00	15/-
*	TO SUPPLY REAR BUMPER CLIPS <i>HN</i>	\$ 50.00	25/-
*	TO SUPPLY REAR NUMBER PLATE <i>st</i>	\$ 50.00	45/-
*	TO SUPPLY TAIL LAMP CLIPS <i>HN</i>	\$ 50.00	X

* TO SUPPLY TAIL LAMP PANEL SEALANT Hec	\$ 80.00 20/-
* TO SUPPLY REAR END PANEL SEALANT Hec	\$ 80.00 20/-
* TO SUPPLY REAR END PANEL TOP GARNISH CLIPS Hec	\$ 50.00 15/-
* TO SUPPLY BONNET INSULATOR CLIPS Hec	\$ 50.00 15/-
* TO SUPPLY HEAD LAMP CLIPS HH	\$ 50.00 X
* TO SUPPLY FRONT BUMPER CLIPS Hec	\$ 50.00 20/-
* TO SUPPLY FRONT BUMPER GRILLE CLIPS Hec	\$ 50.00 15/-
* TO SUPPLY FRONT BUMPER UNDER COVER CLIPS HH	\$ 50.00 X
* TO SUPPLY FRONT BUMPER FOG LAMP HOLDER CLIPS HH	\$ 50.00 X
* TO SUPPLY FRONT BUMPER LOWER GRILLE CLIPS Hec	\$ 50.00 15/-
* TO SUPPLY COOLANT HH	\$ 100.00 X
* TO SUPPLY FRONT NO. PLATE & CASING Hec	\$ 100.00 45/-
325.00 //	
* TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 150/-
* TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 5,000.00 2000/-
* TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 4,000.00 1600/-
* TO TUFF COAT DAMAGED AREAS	\$ 300.00 40/-
* TO RNR REAR UNDERCARRIAGE SYSTEM TO FACILITATE REPAIRS	\$ 400.00 150/-
* TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	\$ 200.00 HH
* TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	\$ 250.00 120/-
* TO CONDUCT WHEEL ALIGNMENT TEST	\$ 150.00 60/-
* TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	\$ 200.00 120/-
* TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	\$ 200.00 50/-
* TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	\$ 150.00 40/-
* TO RNR EXHAUST & ATTACHEMENT PARTS TO FACILITATE REPAIRS	\$ 300.00 60/-
* TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 30/-
4420.00 //	

LABOUR & S/N TOTAL: \$ 13,370.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 74,224.77

01/06/2022 @ 1000m - Check MV
 HA Andri - Check Part price
 Part by Part - Photo after repair
 20 days with damaged parts.
 28,671.18
 Supp 1,217.55
 P/P 29,888.73
 Lkr Andri

C. S. ONG AUTO PTE LTD

Co. Reg. No.: 201408916W

7030, ANG MO KIO AVE 5, #B1-01 NORTHSTAR @ AMK, SINGAPORE 569880

TEL: 6484 1933 | FAX: 6484 1922

E-Mail: csongauto.claims@yahoo.com.sg

To: MSIG

Att: Motor Claims Dept

ACCIDENT INVOLVING SLF2015X [YOUR INSURED] & SML2190D [OUR CLIENT]
ON 27/05/2022.

SUPPLEMENTARY ESTIMATED REPAIR COSTS FOR SML2190D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET LOCK <i>1st</i>	131.60	\$ 328.00 ✓
1PC	BONNET LOCK CABLE <i>1st</i>	110.60	\$ 335.00 X ✓
2PCS	BONNET HINGE LH / RH <i>1st</i> <i>78.50 X 2 =</i>	157.00	\$ 362.00 <i>1st</i> X
1PC	FRONT GRILLE TOP GARNISH <i>1st</i> <i>135.00</i>	227.90	\$ 588.00 ✓
1PC	RADIATOR TOP GARNISH <i>1st</i> <i>227.90</i>		\$ 539.00 ✓
1PC	BATTERY TOP BRACKET <i>1st</i>	36.40	\$ 341.00 ✓
2PCS	HEADLAMP TOP CHROME LH / RH <i>1st</i> <i>90.95 X 2 =</i>	181.90	\$ 824.00 ✓
2PCS	REAR BUMPER PARKING SENSOR <i>1st</i>	220.00	\$ 773.00 ✓
1PC	SPARE TYRE INSULATOR <i>1st</i>	80.00	\$ 448.00 ✓
1PC	REAR PASSENGER SEAT <i>1st</i>		\$ 6,127.00 <i>1st</i> 300.00
1PC	AIR INTAKE MANIFOLD <i>1st</i>		\$ 1,453.22 X

PARTS SUM: \$ 12,188.22

PARTS LESS 25%: \$ 3,047.06

PARTS TOTAL: \$ 9,141.17

08/06/2022 @ 1108am

1st

1st 300.00
2nd 300.00

1st 823.40

25% 617.55

2kk Auto

Check part price

1217.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: