



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MINISTRY OF DEFENCE
AFPN 1615 , HQ SUPPLY
151 CHO A CHU KANG WAY
BLK822 #03-05
SINGAPORE 688248

Ref: CC2/MIDF22005148/Rpq2

Date: 09/06/2023

Code: MIDF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	MID 59375	Veh. Inspected	SDS 5425C
Policy No.	OA 22008519	Coverage (\$)	0.00
Claim No.	WY 22/23/001	Excess (\$)	0.00
Assign From		Assign Date	31/05/2022

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI CN7 AVANTE 1.6S	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	KMHLN41ETMU066657	Colour	GREY
Odometer	15625 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	HANKOOK	6 mm
L/H Front Tyre	205/55 R16	HANKOOK	6 mm
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/05/2022	Inspection Date	31/05/2022
Survey held at	CARZ AUTO SERVICES PTE LTD 61 WOODLANDS IND PARK E9 #04-04 (S) 757047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDS 5425C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	OUTER REAR QUARTER PANEL LH	BUCKLED	1,892.00	1,892.00
1	INNER REAR QUARTER PANEL LH (NPA)	NOT NECESSARY	-	-
1	REAR DOOR SHELL ,LH	BUCKLED	2,147.90	1,983.00
1	REAR DOOR TRIM PANEL ,LH (NPA)	NOT NECESSARY	-	-
1	BELT WEATHER STRIP ,WINDOW INNER REAR DOOR ,LH (NPA)	NOT NECESSARY	-	-
1	BELT MOULDING ,WINDOW OUTER REAR BOOT ,LH (CHROME)	NECESSARY	85.10	85.10
1	TRIM QUARTER PANEL OUTER LH (CHROME)	NECESSARY	45.00	45.00
1	WEATHERSTRIP ,REAR DOOR SIDE ,LH	NECESSARY	105.80	105.80
1	WEATHERSTRIP ,REAR BODY SIDE ,LH	NOT NECESSARY	95.80	-
1	WINDOW SWITCH ASSY ,REAR DOOR ,LH	NOT NECESSARY	75.80	-
1	WATER DEFLECTOR ,REAR DOOR ,LH (NPA)	NOT NECESSARY	-	-
1	HINGE UPPER ,REAR DOOR ,LH	NOT NECESSARY	45.90	-
1	HINGE LOWER ,REAR DOOR ,LH	NOT NECESSARY	45.90	-
1	STRIKER ,REAR DOOR ,LH	NOT NECESSARY	25.30	-
1	CHECKER ASSY ,REAR DOOR ,LH	NOT NECESSARY	47.30	-
1	SPEAKER REAR DOOR ,LH (NPA)	NOT NECESSARY	-	-
1	WINDOW REGULATOR ASSY ,REAR DOOR ,LH	CRACKED	223.40	223.40
1	RUN CHANNEL REAR DOOR LH (NPA)	NOT NECESSARY	-	-
1	GUIDE CHANNEL ,REAR DOOR ,LH (NPA)	NOT NECESSARY	-	-
1	OUTER DOOR HANDLE ,REAR LH	TO REPAIR SEE LABOUR	49.40	-
1	INNER DOOR HANDLE ,REAR LH	NOT NECESSARY	48.20	-
1	LOCK ASSY ,REAR LH	CRACKED	191.50	191.50
1	REAR BUMPER	TO REPAIR SEE LABOUR	470.80	-
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	32.90	-
1	FENDER LINER ,REAR LH	NOT NECESSARY	75.00	-
	LESS 20% DISCOUNT		-	-905.16
			5,703.00	3,620.64

Report Ref No. CC2/MIDF22005148/Rpq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	<u>SPECIAL NETT ITEMS</u>	NECESSARY		
	DOOR TRIM PANEL CLIPS (SN)		25.00	25.00
			25.00	25.00
	<u>LABOUR</u>	NOT NECESSARY		
	TO REMOVE AND RENEW LEFT REAR DAMAGED PARTS ,REPLACE REALIGNED ALL AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF OUTER DOOR HANDLE ,REAR LH AND REAR BUMPER .		1,800.00	800.00
	TO RESPRAY AFFECTED AREAS .		1,000.00	600.00
	TOWING . (NPA)		-	-
	TO REMOVE/REFIX WIRING CHECKS.		20.00	20.00
	TO TUFFCOAT AFFECTED AREA.		40.00	40.00
	TO REMOVE/REFIX INTERIOR UPHOLSTERY .		60.00	60.00
	TO REMOVE /REPLACE DOOR MECHANISM PARTS .		80.00	60.00
	TO REPROGRAM ALL RELATED /NECESSARY SYSTEM.		100.00	80.00
	TO COMPUTERISED FOUR WHEEL ALIGNMENT.		120.00	60.00
			3,220.00	1,720.00
GRAND TOTAL			8,948.00	5,365.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CC2/MIDF22005148/Rpq2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDS 5425C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDS 5425C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDS 5425C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

