

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0433/2022/JT
DATE : 27-May-22
WIP : 26009

VEHICLE NOT IN WORKSHOP. SURVEY TBC.

YOUR INSURED VEH NO : GBD 9069 Z

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07, THE CONCOURSE

SINGAPORE 199555

OWNER'S NAME : MISS NG LI QING
ADDRESS : 36 JALAN LIMAU MANIS
SINGAPORE 468364
TELEPHONE : HP +65 9835 1077
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : GA595591
VEHICLE NO : **SMU 6025 A**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TFSI
MODEL YEAR : 17/9/2019
ENGINE NO : CHZ C29277
CHASSIS NO : WAUZZZ8V1KA064690
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-May-22
PLACE OF ACCIDENT : BEDOK ROAD AND BEDOK RISE JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 6025 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR.	S/N \$ 280.00	
3	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER. TO REPAIR RHS FRONT DOOR. REINSTALL CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,500.00	
4	TO RESPRAY RHS FRONT FENDER AND RHS FRONT DOOR.	\$ 2,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 5,332.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6025 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - RH	1	\$ 954.00	
2	FRONT FENDER POP RIVET	8	\$ 31.00	
3	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00	
4	FRONT FENDER BRACKET - RH	1	\$ 56.00	
5	FRONT FENDER BRACKET END - RH	1	\$ 31.00	
6	FRONT FENDER BRACE - RH	1	\$ 107.00	
7	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 68.00	
8	FRONT FENDER INSULATION - RH	1	\$ 48.00	
9	FRONT FENDER CLOSING ELEMENT END - RH	1	\$ 37.00	
10	FRONT WHEEL HOUSING LINER - RH	1	\$ 183.00	
11	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 60.00	
12	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH	1	\$ 302.00	
13	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 2,252.00	
TOTAL LABOUR CHARGES		:	\$ 5,332.00	
GRAND TOTAL		:	\$ 7,584.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT