

TP Budget Direct SKV9103 G. 2016 Nov

Hui Peng Volkswagen Scirocco.

WVWZZ2Z13ZHV003901

Rees	Number Plate	2 x 30(SN) X
Rees	Number Plate Holder	30(SN) X.
Rees	Number Plate Lamp x 02	68 x 2 = 176. X
Rees	Bumper Deband	1122 -
Rees	Bumper Clips.	30(SN) -
Rees	Bumper Reinforcement	546. X
Rees	Bumper Lower Garment	395. -
Rees	Bumper Reflector x 02	89 x 2 = 178. X
Rees	Bumper Centre Guide.	230. -
Rees	Bumper Side Holder x 02	72 x 2 = 142. -
Tailgap	x 02. RH and L	485. X
Reverse Sensor.	2nd	485 x 2 = 970. X

~~280(SN)~~ 200(SN)

2374

213660

S.N: 230

SKV9103G.

Panel Beating

Spry Painting

Wiring.

To remove reverse sensor.

630

~~400~~ 300

~~400~~ 250

~~50~~ 30

~~100~~ 50

Total: 2996.60

L/S. 2-4/c.

03 Days

2,400

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: