

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0450/2022/JT
DATE : 1-Jun-22
WIP : 26608

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 7/6/2022
YOUR INSURED VEH NO : GBC 4889 L

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

OWNER'S NAME : MR SARAVANAN GOPINATHAN
ADDRESS : 61 NAMLY AVENUE
SINGAPORE 267631
TELEPHONE : HP +65 9677 8925
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5116646297-01
VEHICLE NO : **SMS 3511 T**
MODEL CODE : AUDI A3 SB 1.4 TFSI
MODEL YEAR : 30/6/2016
ENGINE NO : CZC 545476
CHASSIS NO : WAUZZZ8V8GA147685
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-May-22
PLACE OF ACCIDENT : AYE, SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 3511 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250 ✓
3	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY.	S/N \$ 2,400.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000 ✓
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,000.00	1650 ✓
6	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	240 ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 7,922.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Asher.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 3511 T

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>rehand</i>	1	\$ 2,146.00	✓ 1,716.80
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 195.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$ 175.00	+
4	FRONT BUMPER GUIDE SECTION- LH <i>Dented</i>	1	\$ 71.00	✓ <i>fls.</i> 56.48
5	FRONT BUMPER AIR GUIDE GRILE - LH <i>new</i>	1	\$ 122.00	+
6	FRONT FENDER - LH <i>Dented</i>	1	\$ 954.00	✓ 763.20
7	FRONT FENDER ATTACHMENT PARTS <i>3X NN</i>	1	\$ 75.00	✗
8	FRONT FENDER BRACKET - LH <i>Best</i>	1	\$ 44.40 56.00	✓ <i>fls.</i>
9	FRONT FENDER POP RIVET <i>new</i>	9	\$ 27.36 35.00	✓
10	FRONT FENDER BRACE - LH <i>Best</i>	1	\$ 85.60 107.00	✓ <i>fls.</i>
11	FRONT FENDER CLOSING ELEMENT - LH <i>Dented</i>	1	\$ 54.24 68.00	✓ <i>fls.</i>
12	FRONT FENDER BRACKET END - LH <i>3X NN</i>	1	\$ 31.00	✗
13	FRONT WHEEL HOUSING LINER - LH <i>new torn</i>	1	\$ 146.40 183.00	✓ <i>fls.</i>
14	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 93.00	+
15	HEADLIGHT - LH <i>ut</i>	1	\$ 2,810.00	✓ 2,248.00
16	HEADLIGHT POWER MODULE <i>new</i>	1	\$ 616.00	+
17	HEADLIGHT CONTROL UNIT <i>new</i>	1	\$ 1,237.00	+
18	GAS DISCHARGE LAMP <i>new</i>	1	\$ 453.00	+
19	HEADLIGHT HOSE - LH <i>new</i>	1	\$ 60.00	+
20	LIFT CYLINDER - LH <i>new</i>	1	\$ 211.00	+
SUB TOTAL SPARE PARTS			\$ 9,698.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Adrian L
 Resurveyed *fls.*

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 3511 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER HOSE <i>xhe n</i>	1	\$ 204.00	+
22	RUBBER VALVE <i>xhe n</i>	1	\$ 4.00	+
23	TRACK CONTROL ARM ?	1	\$ 393.00	?
24	FRONT WHEEL BEARING HOUSING ?	1	\$ 627.00	?
25	FRONT WHEELHUB BEARING ?	1	\$ 553.00	?
26	SUSPENSION GUIDE JOINT ?	1	\$ 137.00	?
27	COUPLING ROD ?	1	\$ 105.00	?
28	GAS SHOCK ABSORBER ?	1	\$ 281.00	?
29	TRACK ROD ?	1	\$ 98.00	?
30	TIE ROD END - LH ?	1	\$ 126.00	?
31	LHS FRONT RIM 64	S/N	TBC	✓
32	LHS FRONT TYRE <i>xhe n</i>	S/N	TBC	+
33	SUNDRIES ?	\$	600.00	?
TOTAL SPARE PARTS		:	\$ 12,826.00	
TOTAL LABOUR CHARGES		:	\$ 7,922.00	
GRAND TOTAL		:	\$ 20,748.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian Ling
07/06/22

Not Authorised, 05 Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/TP/0450/2022/JT
7-Sep-22
GLORY
1 of 1
SMS 3511 T
AUDI A3 SB 1.4 TFSI

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR LHS FRONT DOOR.	S/N \$ 280.00	\$ 280.00 ✓
GRAND TOTAL		\$ 280.00	\$ 280.00

For Premium Automobiles Pte Ltd

Authorised Signature