

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	tef:	CS/AGI22005172/Dny3q2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	23/11/2022	
			С	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMM 5807J	Veh. Inspected		SHD 3577S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10015492 /JT	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		31/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JTDKB3FU703563401	Colour		BLUE	
	Odometer	510366 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST LAKE		5 mm	
	L/H Front Tyre	195/65 R15	WEST LAKE		5 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE		5 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/05/2022	Inspection Date		31/05/2022	
	Survey held at	Blk 9 Sector C #01-42, Sin Ming	Industrial Estate			
	Repairer	BIFROST AUTO PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					

8 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: