

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHD3577S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 May 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZRS061319
Chassis No.:	JTDKB3FU703563401
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	10 Aug 2017
First Registration Date:	10 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Aug 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	09 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,320.00
COE Rebate Amount:	\$14,498.00
Total Rebate Amount:	\$18,248.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 May 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/05/2022 20:09 (SGT)
Date of Accident	27/05/2022 14:30 (SGT)
Exact Location of Accident	Bedok Reservoir Rd, Singapore
Additional Location Information	BLK 149 BEDOK RESERVOIR ROAD CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3577S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-65508768
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	-
Cover Note Number	-

DRIVER

Name of Driver	MOHAMED BIN MAHMOOD
NRIC No	SXXXX613H

Date Of Birth	17/08/1950
Occupation	Outdoor
Date Of Driving Pass	02/12/1972
Driving experience	49 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91860304
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	467 TAMPINES STREET 44 #04-140
Address complement	-
Postcode	520467
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head on collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 27/05/2022 AT ABOUT 14:30HRS. I WAS DRIVING VEHICLE A, SHD3577S TRAVELLING INSIDE CARPARK OF BLK 149 BEDOK RESERVOIR ROAD CARPARK. I WAS GOING TOWARDS THE GANTRY AND SUDDENLY VEHICLE B FROM THE PARKING LOT JUST DASHED OUT AND HIT ONTO MY LEFT SIDE OF THE VEHICLE.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE NOT SUITABLE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMM5907J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	MARSHALL

Contact Number	(Phone) +65-91442539
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims,
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A-SH03571S

B-Smm5907J

Blk 149 BEDOK RESERVOIR RD CP

Describe Circumstances of the Accident

ON 27/05/2022 AT ABOUT 14:30HRS. I WAS DRIVING VEHICLE A, SHD3577S TRAVELLING INSIDE CARPARK OF BLK 149 BEDOK RESERVOIR ROAD CARPARK. I WAS GOING TOWARDS THE GANTRY AND SUDDENLY VEHICLE B FROM THE PARKING LOT JUST DASHED OUT AND HIT ONTO MY LEFT SIDE OF THE VEHICLE.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time 17:15 27.05.22

Witnessed by Reporting Centre Personnel MD NARRIN

Customer:	LIM TAN	Date:	6/1/2022 10:29 AM
Company:	01-42	VIN	
License NO:	SHD 3577S	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT
TOYOTA, PRIUS ZVW30 (G's), 12-12 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°20'	5°19'	6°49'	4°18'
		Right	5°03'	5°19'	6°49'	5°12'
	Camber	Left	1°24'	-1°00'	0°30'	1°30'
		Right	-1°06'	-1°00'	0°30'	-1°12'
	Toe	Left	0°45'	-0°08'	0°03'	-0°21'
		Right	1°09'	-0°08'	0°03'	2°15'
Total		1°54'	-0°16'	0°05'	1°54'	
Rear	Camber	Left	-0°54'	-2°00'	-1°00'	-0°48'
		Right	-1°18'	-2°00'	-1°00'	-1°18'
	Toe	Left	0°09'	0°03'	0°19'	0°09'
		Right	0°00'	0°03'	0°19'	0°00'
		Total	0°09'	0°05'	0°38'	0°09'
	Thrust Angle		0°05'	0°15'		0°05'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		14°19'	----	----	14°19'
	Right		14°21'	----	----	14°21'
Included Angle	Left		15°43'	99°59'	99°59'	15°49'
	Right		13°15'	99°59'	99°59'	13°09'
Toe Out On Turns	Left		----	99°59'	99°59'	----
	Right		----	99°59'	99°59'	----
Max Turn Inside	Left		----	99°59'	99°59'	----
	Right		----	99°59'	99°59'	----
Toe Curve Change	Left		----	0°00'	199°59'	----
	Right		----	0°00'	199°59'	----
Setback	Front		-14mm	2540mm	2540mm	-14mm
	Rear		3mm	2540mm	2540mm	3mm
Track Width Diff.			-4mm			-4mm
Wheel Base Diff.			-16mm			-16mm
Front Ride Height	Left		----	2540mm	2540mm	----
	Right		----	2540mm	2540mm	----
Rear Ride Height	Left		----	2540mm	2540mm	----
	Right		----	2540mm	2540mm	----
Frame Angle						----

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 30-May-22

INSURANCE: Budget Direct

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHD 3577S

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR BUMPER <i>cut / mostly white</i>	1	\$503.04	\$503.04	✓
REAR BUMPER SIDE RETAINER <i>src</i>	1	\$112.70	\$112.70	X
REAR BUMPER CLIPS <i>Huc</i>	1	\$22.00	\$22.00	✓
REAR BUMPER SIDE CLIP <i>HH</i>	1	\$25.00	\$25.00	X
SEAL, REAR BUMPER SIDE, LH <i>HH</i>	1	\$148.40	\$148.40	X
REAR FENDER, LH <i>Devel</i>	1	\$992.04	\$992.04	✓
REAR FENDER SHIELD (LH) <i>HH</i>	1	\$174.20	\$174.20	X
REAR FENDER AIR DUCT <i>HH</i>	1	\$165.10	\$165.10	X
PANEL SUB-ASSY, REAR DOOR, LH <i>Devel</i>	1	\$1,258.30	\$1,258.30	✓
REAR DOOR HINGE UPPER <i>HH</i>	1	\$82.30	\$82.30	X
REAR DOOR HINGE LOWER <i>HH</i>	1	\$82.30	\$82.30	X
REAR DOOR CHECK <i>HH</i>	1	\$153.00	\$153.00	X
REAR DOOR INNER LOCK <i>HH</i>	1	\$644.70	\$644.70	X
MOTOR, POWER WINDOW REGULATOR FRT, LH <i>HH</i>	1	\$941.80	\$941.80	X
REGULATOR, FRONT DOOR WINDOW REAR, LH <i>HH</i>	1	\$228.40	\$228.40	X
PANEL SUB-ASSY, FRONT DOOR, LH <i>Devel</i>	1	\$1,264.00	\$1,264.00	✓
FRONT DOOR INNER LOCK <i>HH</i>	1	\$688.80	\$688.80	X
FRONT DOOR HINGE UPPER <i>HH</i>	1	\$91.20	\$91.20	X
FRONT DOOR HINGE LOWER <i>HH</i>	1	\$91.20	\$91.20	X
FRONT DOOR CHECK <i>HH</i>	1	\$153.52	\$153.52	X
FRONT DOOR WHETHER STRIP <i>src</i>	1	\$457.90	\$457.90	X
FRONT DOOR RUBBER SEAL <i>HH</i>	1	\$257.00	\$257.00	X
MOTOR ASSY, POWER WINDOW FRT, LH <i>HH</i>	1	\$941.80	\$941.80	X
REGULATOR, FRONT DOOR WINDOW FRT, LH <i>HH</i>	1	\$228.40	\$228.40	X
FRONT DOOR COMFORT LOGO <i>Huc</i>	1	\$75.00	\$75.00	✓ SH
RADIATOR GRILLE <i>HH</i>	1	\$438.00	\$438.00	X
RADIATOR GRILLE EMBLEM <i>HH</i>	1	\$88.00	\$88.00	X
FRONT BUMPER COVER <i>cut / mostly broken</i>	1	\$591.75	\$591.75	✓
FRONT BUMPER REINFORCEMENT <i>HH</i>	1	\$812.89	\$812.89	X
FRONT BUMPER REINFORCEMENT ABSORBER <i>HH</i>	1	\$115.70	\$115.70	X
FRONT BUMPER LOWER REINFORCEMENT <i>HH</i>	1	\$364.20	\$364.20	X
FT BUMPER LOWER REINFORCEMENT BRACKET LH/RH <i>HH</i>	2	\$330.00	\$660.00	X
ABSORBER, FRONT BUMPER, LOWER <i>HH</i>	1	\$127.70	\$127.70	X
FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH) <i>HH</i>	2	\$ 320.70	\$641.40	X
FRONT BUMPER SPONGE <i>HH</i>	1	\$78.80	\$78.80	X
FRONT BUMPER LOWER GRILLE <i>HH</i>	1	\$193.18	\$193.18	X
LAMP ASSY, FOG, RH <i>HH</i>	1	\$920.00	\$920.00	X
LAMP ASSY, FOG, LH <i>HH</i>	1	\$920.00	\$920.00	X
FRONT NO. PLATE GARNISH <i>HH</i>	1	\$99.00	\$99.00	X
FRONT BUMPER SIDE RETAINER <i>HH</i>	2	\$77.00	\$154.00	X
FRONT LOWER PANEL <i>HH</i>	1	\$320.65	\$320.65	X

FRONT LOWER SIDE RAIL (LH/RH) HH	2	\$230.80	\$461.60	X
FRONT BUMPER TOP GARNISH HH	1	\$225.40	\$225.40	X
COVER, FRONT BUMPER HOLE, RH HH	1	\$28.38	\$28.38	X
COVER, FRONT BUMPER HOLE, LH HH	1	\$28.38	\$28.38	X
UNIT ASSY, HEADLAMP, RH (LED) HH	1	\$3,455.00	\$3,455.00	X
UNIT ASSY, HEADLAMP, LH (LED) <i>monly broken</i>	1	\$3,455.00	\$3,455.00	X
HEADLAMP ECU HH	2	\$682.60	\$1,365.20	X
HEAD LAMP PANEL (RH) HH	1	\$240.10	\$240.10	X
HEAD LAMP PANEL (LH) NN	1	\$240.10	\$240.10	X
TOP PANEL CENTRE HH	1	\$364.98	\$364.98	X
TOP PANEL SIDE LH	1	\$145.90	\$145.90	X
BRACE PANEL HH	1	\$75.20	\$75.20	X
RADIATOR ASSY HH	1	\$1,841.80	\$1,841.80	X
RADIATOR FAN GRILLE HH	1	\$632.40	\$632.40	X
DEFLECTOR, RADIATOR SIDE, RH HH	1	\$83.50	\$83.50	X
DEFLECTOR, RADIATOR SIDE, LH HH	1	\$83.50	\$83.50	X
STAY, RADIATOR SUPPORT, LH/RH HH	2	\$278.68	\$557.36	X
RADIATOR FAN BLADE (RH) HH	1	\$233.10	\$233.10	X
RADIATOR FAN BLADE (LH) HH	1	\$233.10	\$233.10	X
RADIATOR FAN MOTOR (RH) HH	1	\$543.70	\$543.70	X
RADIATOR FAN MOTOR (LH) HH	1	\$543.70	\$543.70	X
RADIATOR FAN COWLING (LH/RH) HH	2	\$451.30	\$902.60	X
Cover, Radiator Support Opening HH	1	\$267.43	\$267.43	X
HORN (1 PC) HH	2	\$112.71	\$225.42	X
TUBE & ACCESSORY ASSY, AIRCONDITIONER HH	1	\$631.90	\$631.90	X
FENDER SUB-ASSY, FRONT LH <i>Dunk</i>	1	\$1,111.93	\$1,111.93	X
FRONT FENDER SHIELD <i>chymed</i>	1	\$38.00	\$38.00	X
FRONT FENDER SHIELD CLIP <i>ma</i>	1	\$14.90	\$14.90	X
BRACKET, FRONT SIDE PANEL, LH HH	1	\$86.30	\$86.30	X
EXTENSION, FRONT FENDER, LH HH	1	\$47.20	\$47.20	X
PROTECTOR, FRONT FENDER UPPER, LH HH	1	\$46.10	\$46.10	X
GUSSET, FRONT FENDER APRON, LOWER LH HH	1	\$34.90	\$34.90	X
MEMBER, FRONT APRON TO COWL SIDE, UPPER LH HH	1	\$138.40	\$138.40	X
FRONT APRON TO COWL SIDE, LOWER FRT LH HH	1	\$82.30	\$82.30	X
WIPER SPARE TANK ASSY HH	1	\$486.70	\$486.70	X
WIPER TANK NECK HH	1	\$89.40	\$89.40	X
FRONT WHEEL RIM <i>cut / distal</i>	1	\$1,570.55	\$1,570.55	X
FRONT WHEEL RIM CAP HF	1	\$189.60	\$189.60	X
FRONT WHEEL HUB AND BEARING <i>Dunk</i>	1	\$763.80	\$763.80	X
FRONT SUSPENSION LOWER ARM (LH) <i>distal</i>	1	\$637.50	\$637.50	X
FRONT SHOCK ABSORBER (LH) <i>distal</i>	1	\$401.80	\$401.80	X
ABSORBER TOP MOUNTING HH	1	\$196.20	\$196.20	X
FRONT DRIVE SHAFT (LH) HH	1	\$1,764.00	\$1,764.00	X
RACK & PINION ASSY HH	1	\$1,634.90	\$1,634.90	X
BAR, STABILIZER HH	1	\$360.00	\$360.00	X
LINK ASSY, FRONT STABILIZER, LH HH	1	\$199.00	\$199.00	X
KNUCKLE, STEERING, LH <i>distal</i>	1	\$580.80	\$580.80	X
JOINT ASSY, LOWER BALL, FRONT (LH) NN	1	\$199.98	\$199.98	X
END SUB-ASSY, TIE ROD, LH NN	1	\$159.30	\$159.30	X
SUB TOTAL			\$44,005.68	
LESS 20% 25%			\$8,801.14	

2637.60

94530

12,221.38

9,166.03

DISCOUNTED TOTAL				\$35,204.54
REAR DOOR COMFORT & APPS STICKER <i>NA</i>	SN	1	\$80.00	\$80.00
FRONT NO. PLATE <i>NA</i>	SN	1	\$25.00	\$25.00
FRONT NO. PLATE TRIM COVER <i>NA</i>	SN	1	\$30.00	\$30.00
COOLANT <i>NA</i>	SN	1	\$45.00	\$45.00
FRONT TYRE (LH) <i>NA</i>	SN	1	\$216.00	\$216.00
SUB TOTAL				\$396.00
Labour Charge				
Panel Beating		1	\$2,200.00	\$2,200.00
Spray Painting Charge		1	\$2,000.00	\$2,000.00
Wiring Charge		1	\$100.00	\$100.00
Tuff Kote		1	\$100.00	\$100.00
Towing Charge		1	\$80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00
Remove/Refix Fuel Tank		1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT		1	\$80.00	\$80.00
Re-set Frt Power Window System		1	\$200.00	\$200.00
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00
Re-set Rear Power Window System		1	\$200.00	\$200.00
Four Wheel Alignment		1	\$120.00	\$120.00
Remove/Refix Undercarriage (Frt)		1	\$400.00	\$400.00
Remove/Refix Radiator		1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00
Remove/Refix Steering Rack/Wheel/Dr Shaft		1	\$150.00	\$150.00
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00
TOTAL LABOUR				\$6,710.00
ESTIMATE TOTAL				\$42,310.54
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

✓
X
X
X
X

155.00/-

800/-
1000/-
30/-
40/-
40/-
80/-
40/-
60/-
40/-
60/-
40/-
60/-
150/-
40/-
40/-
40/-
150/-

2430.00/-

31/05/2022 @ 1630h

HVA Author

45mm 8 days.

1/2

2 Kt Author

check part prices.

11,751.03

4/5 9,400/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: