

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : HONDA

STREAM

Vehicle Number : SJZ2416R

Quantity	Description	Repairer's Estimate
A - PARTS		
1	BOOT <i>bt</i>	\$1,200
1	WINDSCREEN <i>bro</i>	\$2,000
1	REVERSE SENSOR LEFT <i>2 sca</i>	\$600
1	REVERSE SENSOR RIGHT	\$600
1	REINFORCEMENT BAR <i>X3VC</i>	\$1,200
1	TAIL LIGHT LEFT <i>bro</i>	\$800
1	TAIL LIGHT MIDDLE <i>X3VC</i>	\$800
1	BUMPER <i>de</i>	\$800
1	FENDER LEFT <i>repair</i>	\$1,500
1	FENDER RIGHT <i>Xnn</i>	\$1,500
1	EXHAUST PIPE <i>Xnn</i>	\$800
1	REAR WIPER <i>bro</i>	\$800
1	REAR WIPER MOTOR <i>X3VC</i>	\$1,500
LABOUR & MISC		
1	Checking of wiring, lighting & resetting	\$850 60
1	Remove and refit rear & front undercarriage	\$500 <i>Xnn</i>
1	Wheel alignment	\$100 <i>Xnn</i>
1	Remove and replace damaged parts	\$1,000 600
1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$2,000 <i>Xnn</i>
1	Respray including polishing and waxing on the changed body parts, repaired portortions where consistent to the accident	\$1,000 600
Total Repair Cost :		\$19,550

903
1207
S/N
3343.30.
20%
2674.64
X
368
X
683
XR
X
X
182.30
X

S/N-2000

1260

2674.64
2000.00
1260.00
4134.64
20%
3307.71

5days

Repair
Limit - 45-\$2,500