

ASS. REC. BY:

REF:

CS GAI 22005175 Dny³

ASSIGNMENT

CSE Jan 2028

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 108 days Res.: Yes or No
 Lum Sum: 71P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 6064 B Yr Regn: Jan / 2020
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Ioniq c.c. 1580
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 277495 T/Radio: Insured / Std / NI / NA
 Eng/No: G4LEKU 404652
 C/No: KMHC851CVLW188089
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front S mm Rear S mm
 R/Bal. S mm L/Bal. S mm
 D.O.A. 23/05/2022 D.O.I. 31/05/2022
 Survey held at Berut Sin Ming
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
H/S Runt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Great American GBB 54795</u>
<u>31/10/22</u>	<u>found 71P 18,470.12 with 10 days going</u> <u>(Red. 15533, 46%)</u>

Date/Time, File Pass to?

1) 31/10/22

Date/Time, File Return to?

2)

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 18,470.12

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/05/2022 19:32 (SGT)
Date of Accident	23/05/2022 22:40 (SGT)
Exact Location of Accident	Orchard Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA6064B
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-91116495
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

DRIVER

Name of Driver	TEO CHONG HUAT
NRIC No	SXXXX018J



Date Of Birth	20/10/1957
Occupation	Outdoor
Date Of Driving Pass	23/02/1978
Driving experience	44 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91116495
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 613B BEDOK RESERVOIR ROAD#12-1374
Address complement	-
Postcode	472613
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Tanglin Division Headquarters
Police Station Phone No	(Phone) +65-18003910000
Alt. Police Station Phone No	(Fax) +65-63964900
Police Station Address	21 Kampong Java Road Singapore 228892
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Refer to the Police Report

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG5479J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-

Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

A.SHA6064B
B.GBG5479J

Driver's Signature (If driver is not the policyholder) / Date & Time


24/05/20 / 0035 hrs

Witnessed by Reporting Centre Personnel

Batig

HULLET
ROAD

CAIRHILL
ROAD



Describe Circumstances of the Accident

REFER TO POLICE REPORT.

Declaration

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

24/05/20 / 0035hrs

Barry



**SINGAPORE
POLICE FORCE**



E/20220524/7021

1 of 3

POLICE REPORT (NP299)

Report No. E/20220524/7021

Police Station Of Origin
Tanglin Division HQ
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-3910000

Date/Time Report Made 24/05/2022 14:53	Vide Report No.	Station Diary No.
Name Of Informant TEO CHONG HUAT	Address 613B BEDOK RESERVOIR ROAD #12-1374 SINGAPORE 472613	
ID Type / ID No. NRIC NO / S1270018J	Contact No. Home/Office: Mobile: 91116495	
Nationality SINGAPORE CITIZEN	Email Address chteo1957@gmail.com	
Occupation Taxi driver	Sex Male	Age 64
	Date of Birth 20/10/1957	Race Chinese
Institution/School Name	Language English	
Date/Time Of Incident 23/05/2022 22:40 - 23/05/2022 22:50	Location Of Incident CAIRNHILL ROAD	

Brief details.

I was driving my comfort taxi (SHA6064B) on the most left lane of Cairnhill Road towards Orchard at approximately 1040pm on 23/5/2022 when a silver van (GBG5479J) suddenly came out of the minor road (near the T junction of Hullet road) without stopping as required. The van hit the front left side of my taxi and caused me to swerve across 2 lanes to the right.

The impact was so great that I instantly felt a sharp pain through my neck, shoulder and back.

Signature Of Officer Recording The Report:

Not applicable

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Signature Of Interpreter:

Not applicable

Date/Time:

24/05/2022 14:53

Officer In-Charge Of Case:

Classification Of Case:



**SINGAPORE
POLICE FORCE**



E/20220524/7021

2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20220524/7021

After colliding into my taxi, the van did not stop and attempted to escape. In shock, I sounded my horn and gave chase. Luckily for me the traffic light turned red at the junction of Cairnhill and Orchard Road. I stopped my car behind his van and alighted and asked for the van driver to step out too.

The van driver looks like an Indian, slightly taller than 1.63m. I told him that he hit my car and should not drive away. He denied colliding with my car so I ask him to follow me to check on his car and found out his van right front has the same collision impact as the front left side (front left tyre side) of my car. I then went back to my car to take my phone out to record. The van driver escaped when the light turn green before I can start recording.

I called the police and they assigned 2 traffic police to assist me. The officers arrived shortly and assisted to take down the information. They took my in car camera sd card. The report reference number is E/20220523/0153

I am waiting to see the doctor now due to the pain through my neck, shoulder and back as the pain has affected my rest despite eating some painkillers. There were few instances today while out making necessary reports, that I felt giddy too.

Subjects Involved			
Victim			
Person Name	TEO CHONG HUAT		
ID Type	NRIC NO	ID No	S1270018J
Gender	Male	Age	64
Race	Chinese	Language	English

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:
The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:
24/05/2022 14:53

Classification Of Case:



**SINGAPORE
POLICE FORCE**



E/20220524/7021

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20220524/7021

Occupation	Taxi driver	Address	613B BEDOK RESERVOIR ROAD #12-1374 SINGAPORE 472613
Mobile No	91116495	Is Informant A Victim?	Yes
Person Name	TEO CHONG HUAT (Informant)		

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:
The identity of the person making this
report has been authenticated by Singpass.
No signature is required.

Date/Time:
24/05/2022 14:53

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA6064B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 May 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU404652
Chassis No.:	KMHC851CVLU188089
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,351.00
Original Registration Date:	16 Jan 2020
First Registration Date:	16 Jan 2020
Transfer Count:	0
Actual ARF Paid:	\$12,492.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jan 2028
PARF Rebate Amount:	\$9,369.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,895.00
COE Rebate Amount:	\$18,255.00
Total Rebate Amount:	\$27,624.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 May 2022

OK

Customer:	LIM TAN	Date:	6/1/2022 9:11 AM
Company:	01-42	VIN	
License NO:	SHA 6064B	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT
HYUNDAI, IONIQ (AE HEV) Hybrid, 17-17 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°15'	4°00'	5°00'	4°30'
		Right	5°05'	4°00'	5°00'	5°18'
	Camber	Left	-2°48'	-0°53'	0°07'	-2°36'
		Right	-1°06'	-0°53'	0°07'	-1°06'
	Toe	Left	0°30'	-0°03'	0°09'	0°30'
		Right	0°12'	-0°03'	0°09'	0°15'
Total		0°42'	-0°06'	0°18'	0°45'	
Rear	Camber	Left	-0°54'	-1°42'	-0°42'	-0°48'
		Right	-1°18'	-1°42'	-0°42'	-1°18'
	Toe	Left	0°03'	-0°02'	0°10'	0°03'
		Right	0°03'	-0°02'	0°10'	0°03'
		Total	0°06'	-0°04'	0°20'	0°06'
	Thrust Angle		0°00'	---		0°00'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	14°14'	13°30'	14°30'	14°14'	
	Right	14°21'	13°30'	14°30'	14°21'	
Included Angle	Left	11°26'	---	---	11°38'	
	Right	13°15'	---	---	13°15'	
Toe Out On Turns	Left	---	---	---	---	
	Right	---	---	---	---	
Max Turn Inside	Left	---	---	---	---	
	Right	---	---	---	---	
Toe Curve Change	Left	---	---	---	---	
	Right	---	---	---	---	
Setback	Front	-14mm	---	---	-14mm	
	Rear	0mm	---	---	0mm	
Track Width Diff.		-9mm			-9mm	
Wheel Base Diff.		-14mm			-14mm	
Front Ride Height	Left	---	373mm	393mm	---	
	Right	---	373mm	393mm	---	
Rear Ride Height	Left	---	372mm	392mm	---	
	Right	---	372mm	392mm	---	
Frame Angle					---	

ONE STOP AUTOMOTIVE SOLUTION

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 30-May-22
 MODEL: HYUNDAI IONIC
 VEHICLE NO.: SHA 6064B

INSURANCE:

Great American

31/05/2022 @ 1600hrs

HA Accident

? 1st 10 days.

Repair & etc. And

Description	Qty	List Price	Amount
Bonnet	1	\$ 2,253.80	\$ 2,253.80
Bonnet Hinge (LH/RH) <i>key w/ls o/s H4</i>	2	\$ 118.70	\$ 237.40
Bonnet Moulding <i>gr</i>	1	\$ 41.40	\$ 41.40
Bonnet Lock <i>H4</i>	1	\$ 127.30	\$ 127.30
Bonnet Insulator <i>H4</i>	1	\$ 230.10	\$ 230.10
Bonnet Insulator Clips <i>H4</i>	1	\$ 15.00	\$ 15.00
Radiator Grille NEW MODEL <i>mondy broken</i>	1	\$ 1,568.60	\$ 1,568.60
Flap Assy Active Air Upper, (LH) <i>H4</i>	1	\$ 824.60	\$ 824.60
Front Bumper Cover <i>tom</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>H4</i>	1	\$ 476.30	\$ 476.30
Front Bumper Sponge <i>tom</i>	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement <i>H4</i>	1	\$ 1,136.70	\$ 1,136.70
Front Bumper Reinforcement ABSORBER (LH) <i>H4</i>	1	\$ 186.50	\$ 186.50
Front Bumper Towing Cover <i>H4</i>	1	\$ 29.00	\$ 29.00
Front Bumper Moulding Centre Upper <i>broken</i>	1	\$ 368.50	\$ 368.50
Front Bumper Moulding <i>H4</i>	1	\$ 93.60	\$ 93.60
Front Bumper Lower Stiffner <i>H4</i>	1	\$ 285.10	\$ 285.10
Front bumper lower grille <i>H4</i>	1	\$ 365.30	\$ 365.30
front bumper lower grille moulding <i>H4</i>	1	\$ 127.60	\$ 127.60
Front Bumper Lip <i>H4</i>	1	\$ 35.10	\$ 35.10
Front Bumper Bracket Top (LH) <i>H4 broken</i>	1	\$ 35.00	\$ 35.00
Front Bumper Bracket (LH) <i>broken</i>	1	\$ 28.00	\$ 28.00
Front Bumper Retainer Mounting (LH) <i>H4</i>	1	\$ 65.30	\$ 65.30
Front Bumper Clips 10 pcs <i>H4</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH) <i>dislodged</i>	1	\$ 186.90	\$ 186.90
Front bumper air duct (LH) <i>broken</i>	1	\$ 153.80	\$ 153.80
Day Light ,LH <i>mondy broken</i>	1	\$ 642.50	\$ 642.50
Day Light Wire, <i>tom</i>	1	\$ 585.50	\$ 585.50
BUZZER ASSY - PIEZO (LH) <i>H4</i>	1	\$ 388.00	\$ 388.00
Headlamp Support Panel Assy <i>broken</i>	1	\$ 1,139.30	\$ 1,139.30
Headlamp(LH) <i>broken</i>	1	\$ 3,987.30	\$ 3,987.30
Horn Unit (LH) <i>H4</i>	1	\$ 72.80	\$ 72.80
Horn Wire <i>H4</i>	1	\$ 386.70	\$ 386.70
Radiator Inverter <i>H4</i>	1	\$ 884.80	\$ 884.80
Radiator <i>H4</i>	1	\$ 710.50	\$ 710.50
Radiator fan blower motor assy <i>H4</i>	1	\$ 1,459.60	\$ 1,459.60
Radiator Air Guard (LH) <i>H4</i>	1	\$ 76.40	\$ 76.40
Radiator Air Guard, Upr (LH) <i>H4</i>	1	\$ 127.50	\$ 127.50
Frt Pillar Upper Cover - outer (LH) <i>H4</i>	1	\$ 89.60	\$ 89.60
Front Fender(LH) <i>Panel</i>	1	\$ 490.70	\$ 490.70
Front Fender Apron Panel (LH) <i>key</i>	1	\$ 756.20	\$ 756.20
Front Fender Apron Panel Upper(LH) <i>key</i>	1	\$ 329.00	\$ 329.00

2110.30

Front Fender Shield (LH) <i>torn</i>	1	\$ 164.70	\$ 164.70	✓
Aircon Condenser <i>rw</i>	1	\$ 663.60	\$ 663.60	X
Front Wheel Rim (LH) <i>distorted</i>	1	\$ 1,124.20	\$ 1,124.20	✓
Front Wheel Hub assy (LH) <i>Cost Down</i>	1	\$ 678.50	\$ 678.50	✓
Front Wheel Hub Cap <i>cut 1/2</i>	1	\$ 346.40	\$ 346.40	✓
Front Shock Absorber(Assy)(LH) <i>distorted</i>	1	\$ 372.50	\$ 372.50	✓
Front Shock Absorber Mounting (LH) <i>rw</i>	1	\$ 372.50	\$ 372.50	X
Front Drive Shaft (LH) <i>rw</i>	1	\$ 1,136.70	\$ 1,136.70	X
Rack & Pinion Assy <i>rw</i>	1	\$ 2,387.40	\$ 2,387.40	X
STG Tie Rod <i>rw</i>	1	\$ 125.60	\$ 125.60	X
STG Tie End <i>rw</i>	1	\$ 94.70	\$ 94.70	X
Stabilizer Bar <i>rw</i>	1	\$ 326.80	\$ 326.80	X
Stabilizer Bar Link <i>rw</i>	1	\$ 92.10	\$ 92.10	X
Front Suspension Lower Arm (LH) <i>distorted</i>	1	\$ 596.80	\$ 596.80	✓
Knuckle Arm (LH) <i>distorted</i>	1	\$ 663.60	\$ 663.60	✓
ABS Sensor <i>rw</i>	1	\$ 290.00	\$ 290.00	X
SUB TOTAL			\$ 31,126.40	
LESS 20%			\$ 6,225.28	
DISCOUNTED TOTAL			\$ 24,901.12	
COOLANT NEC SN	1	\$ 45.00	\$ 45.00	✓
Emblem-Blue Drive (LH) <i>rw</i> SN	1	\$ 26.60	\$ 26.60	✓ <i>see list</i>
Front Tyre(LH) <i>cut 50% depreciation</i> SN	1	\$ 216.00	\$ 216.00	108.00
SUB TOTAL			\$ 287.60	
Labour Charge				
Panel Beating	1	\$1,400.00	\$1,400.00	600/- 700/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	600/-
Wiring Charge	1	\$100.00	\$100.00	30/-
Tuff Kote	1	\$100.00	\$100.00	40/-
Towing Charge	1	\$80.00	\$80.00	rw
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00	150/-
Re-set Frt ABS System	1	\$200.00	\$200.00	rw
Remove/Refix Radiator	1	\$90.00	\$90.00	rw 1730.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	rw
Remove/Refix Steering Rack/Wheel/Dr Shaft	1	\$150.00	\$150.00	rw
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	150/-
TOTAL LABOUR			\$4,520.00	
ESTIMATE TOTAL			\$ 29,708.72	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

15365.90
12,292.72

153.00

34003.12

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 1-Jun-22

INSURANCE: Great American

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 6064 B (S)

Description	Qty	List Price	Amount
Wiring-Engine <i>Dem</i>	1	\$ 5,368.00	\$ 5,368.00
SUB TOTAL			\$ 5,368.00
LESS 20%			\$ 1,073.60
DISCOUNTED TOTAL			\$ 4,294.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

Sign

2kk And

[Handwritten signature]

14,175.72

Syp 4,294.40

7/p 18,470.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: