

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722

Tel : 6266 9511 Fax : 6266 9512

*Not Authorized
U/Ring @ 5100k
Resurvey After Paint
6 days*

Vehicle No : SMQ3051P
Vehicle Model : Toyota Voxy

Estimate Repair Cost

No.	Qty	Parts List Items			
1	1	Rear bumper	798.20	\$ Bu	891.60 ✓
2	2	Rear bumper retainers		N/S Bu	\$ 95.60 ✓
3	2	Rear bumper brackets		\$ R	98.90 X
4	2	Rear bumper reflectors		\$ Su	92.90 X
5	2	Rear bumper tow cover		\$ Rd	48.90 ✓
6	1 set	Rear bumper clips		\$ Ru	40.00 ✓
7	1	Rear tailgate		Ru	\$ 1,561.90 ✓
8	1	Rear tailgate centre logo		\$ Su	68.90 X
9	1	Rear tailgate outer chrome handle		\$ Su	769.50 X
10	1	Rear tailgate lock	581.90	\$ Ru	771.80 ✓
11	2	Rear tailgate hinges		\$ R	129.60 X
12	2	Rear tailgate dampers		\$ Su	419.50 X
13	2	Rear tailgate weatherstrip	371.85	NalD	\$ 471.60 SoBin
14	1	Rear tailgate number plate lamp		\$ Su	98.70 X
15	1	Rear tailgate inner top garnish		\$ Su	652.90 X
16	2	Rear tailgate inner side garnishs		\$ Su	783.60 X
17	1	Rear tailgate inner trim board		\$ Su	619.60 X
18	2	Tail lamps		\$ Su	1,973.80 X
19	2	Rear fender inner side trims	C 681.10	N/S Bu	\$ 1,979.80 ✓
20	1	Rear end panel	781.90	\$ Bu	918.00 ✓
21	1	Rear end panel top garnish	204.50	\$ Bu	352.90 ✓
22	1	Rear spare tyre compartment		\$ R	1,211.90 X
23	1	Rear spare tyre top board	938	\$ CM	938.00 ✓
24	1	Rear exhaust silencer		\$ R	711.60 X
25	1	Rear exhaust silencer mounting		\$ R	89.60 X
				Total	\$ 15,791.10

Parts Special Nett Items

26	1	Rear number plate		\$ Su	60.00 X
27	1 set	Reverse sensor		\$	300.00 20052
28	1	Reverse camera		\$ Su	250.00 X
					\$ 610.00

Total Parts \$ 16,401.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$	1,800.00	700
2	To putty and respray painting on affected areas.	\$	1,500.00	800
3	To remove, replace rear tailgate fittings to facilitate repair.	\$	300.00	60
4	To remove, replace rear windscreen glass.	\$	200.00	120
5	To remove, replace reverse camera.	\$	150.00	40
6	To remove, replace reverse sensor.	\$	150.00	50
7	To remove, replace rear exhaust silencer.	<i>nn</i> \$	200.00	X
8	To check wiring and lightings.	\$	80.00	20

Total Labour \$ 4,380.00

Total Parts and Labour \$ 20,781.10