



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SBS 8290C

Qty	Description of Parts	Condition	Recommended (\$)
1	<b><u>REPLACEMENT OF PARTS</u></b>	CUT	
	STKR SBS TRANSIT OS/NS.SG BUS		8.00
			8.00
	<b><u>LABOUR</u></b>	NOT NECESSARY NOT NECESSARY	
	CONTRACTOR LABOUR COST		550.00
	WORKSHOP LABOUR COST		188.00
	ADVERTISEMENT COST (NPA)		-
	TOW COST (NPA)		-
			738.00
<b>GRAND TOTAL</b>			<b>746.00</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>			<b>746.00</b>

Report Ref No. CS/INC22005185/Tvy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.