



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22005186/Tvy3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 29/09/2022

ATTN: CHARLOTTE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 9228A	Veh. Inspected	SBS 5120E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1174559-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	31/05/2022

2. Vehicle Particulars & Condition

Make & Model	SCANIA KUB4X2	c.c	9290
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	YS2K4X20001867490	Colour	MULTI COLOUR
Odometer	633036 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/05/2022	Inspect Date / Time	31/05/2022 (02:30 PM)
Survey held at	SBS TRANSIT LTD (Branch) BEDOK NORTH DEPOT 1470 BEDOK NORTH AVE 4 SINGAPORE 489946		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------